

LIAN HER MOTORS

BLK 5038 ANG MO KIO IND. PARK 2 #01-405

SINGAPORE 569541

Tel : 82990599 Fax : 64816131

Email : lhcar@hotmail.sg

H.L. CAR RENTAL PTE LTD

BLK 5038 ANG MO KIO IND. PARK 2 #01-405

SINGAPORE 569541

VEHICLE NO. SLR 9705 D
CHASSIS NO. ZYX102015961
MAKE. : TOYOTA C-HR
YEAR. : 2017

Not Authorized

Running Repair

14 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QTY	Description	Amount
-----	-------------	--------

ESTIMATE COST OF REPAIR

1	Front bumper fascia	B/LCM \$ 1,236.70 ✓
2	Front bumper side retainer	CM \$ 232.60 ✓
2	Front bumper side triangle garnish o/s & n/s	n/s m/s \$ 157.20 ✓
10	Front bumper clip	CM \$ 129.00 ✓
1	Front bumper centre air grille	\$ 154.70 ?
1	Front bumper number plate plinth	SM \$ 122.80 X
1	Front bumper tow hook cover	SM \$ 38.00 X
1	Front bumper lower skirt	D/L/CM \$ 499.30 ✓
2	Front bumper lower skirt sensor cover o/s & n/s	SM \$ 55.20 X
1	Front bumper spot lamp cover n/s	DC \$ 177.60 ✓
1	Front bumper lower skirt clip	CM \$ 129.00 ✓
1	Front bumper upper reinforcement	\$ R 461.60 X
1	Front bumper upper reinforcement sponge	\$ 90.20 ?
2	Front bumper upper reinforcement bracket	\$ R 354.20 X
1	Front bumper lower reinforcement	\$ R 237.60 X
1	Front bumper lower reinforcement sponge	\$ 75.30 ?
2	Front bumper lower reinforcement bracket	\$ R 144.20 X
2	Front engine lower cover n/s & o/s	CM \$ 191.80 ✓
8	Front engine lower cover clip	CM \$ 103.20 ✓
1	Front engine mounting n/s	\$ 335.10 ?
1	Front engine mounting bracket n/s	\$ 128.70 ?
1	Front engine mounting rear	\$ 295.10 ?
1	Front engine mounting bracket rear	\$ 125.80 ?

Page 1

Page Total :

\$ 5,474.90

Page 1 balance c/f :

\$ 5,474.90

1	Front bonnet	\$R	1,260.40	X
1	Front bonnet lock	\$R	92.40	X
8	Front bonnet insulation clip	\$un	103.20	X
3	Front bonnet rear side holder clip o/s	\$un	38.70	X
2	Front bonnet rear side holder clip n/s	\$un	38.70	X
1	Front grille assy	CM \$	434.80	✓
1	Front grille emblem	Sn \$	1,654.60	X
1	Front grille rear sleeve holder	\$Sn	38.60	X
5	Front grille clip	\$un	64.50	✓
1	Headlamp assy o/s	mg CM \$	1,804.30	✓
1	Headlamp assy n/s	Bn \$	1,804.30	✓
1	Headlamp panel n/s	\$Bn	305.70	✓
3	Headlamp clip n/s	\$un	38.70	✓
1	Headlamp panel o/s	\$R	305.70	X
3	Headlamp clip o/s	\$un	38.70	X
1	Headlamp wire harness n/s (complete front wire harness)	\$	4,778.68	?
1	Front support top arch panel	\$	204.20	?
1	Front support top arch panel cover garnish	\$	245.60	?
6	Front support top arch panel cover garnish clip	\$	77.40	?
1	Front top support panel	\$R	272.60	X
1	Front top support panel cover garnish	\$Sn	214.60	X
6	Front top support panel cover garnish clip	\$un	77.40	X
1	Front brace panel	\$R	145.70	X
1	Front support lower member	\$R	404.70	X
1	Front aircond condenser	\$Sn	1,486.20	X
2	Front aircond condenser side garnish n/s & o/s	\$Sn	190.40	X
6	Front aircond condenser side garnish clip n/s & o/s	\$un	77.40	X
1	Front radiator assy	\$Sn	2,054.60	X
1	Front radiator cooling fan assy	\$	958.90	?
1	Front main relay box assy n/s	\$	1,375.60	?
1	Front wiper tank assy o/s	\$Dn	220.90	✓
1	Front wiper tank motor o/s	\$Sn	245.71	X
1	Front wiper tank motor O ring seal o/s	\$	25.20	?
1	Front wheelhouse panel n/s	\$	958.00	?
2	Front fender o/s & n/s	\$Bn	1,638.80	✓
2	Front fender emblem o/s & n/s	\$un	115.60	✓
2	Front fender bracket o/s & n/s	\$Bn	207.80	✓
2	Front fender undershield o/s & n/s	\$CM	545.20	✓
16	Front fender undershield clip o/s & n/s	\$un	206.40	✓
2	Front fender rear partition garnish o/s & n/s	\$	190.40	?
6	Front fender rear partition garnish clip o/s & n/s	\$	77.40	?
2	Front fender inner sponge insulation pad o/s & n/s	\$	544.80	?
2	Front fender wheel arch garnish o/s & n/s	\$Dn / un	346.40	✓
16	Front fender wheel arch garnish clip o/s & n/s	\$un	206.40	✓
2	Front fender wheel arch garnish front retainer o/s & n/s	\$Dn	25.00	✓
6	Front fender wheel arch garnish front retainer clip o/s & n/s	\$un	77.40	✓

Page 2

Page Total :

\$ 26,218.69

Page 2 balance c/f :

\$ 31,693.59

1	Front door rear view mirror assy o/s	Bru	\$	1,441.90	✓
1	Front door rear view mirror cover o/s	n/s	\$	142.70	✓
1	Front door quarter glass o/s	sn	\$	111.30	X
1	Front door quarter glass rubber o/s	sn	\$	73.80	?
1	Front door quarter glass quarter pillar o/s	n/s	\$	457.80	✓
1	Front door window glass o/s	Painted	\$	543.60	✓
1	Front door window scrap moulding o/s	sn	\$	125.60	✓
1	Front door assy n/s	n	\$	1,242.30	X
1	Front door window vertical black garnish n/s	nn	\$	38.90	X
1	Front door window black sticker n/s	nn	\$	28.40	X
7	Front door window top black moulding rivert n/s	nn	\$	90.30	X
1	Front door lower protector n/s		\$	334.70	?
8	Front door lower protector clip n/s		\$	103.20	?
1	Rocker panel side skirt n/s	CM	\$	546.70	✓
8	Rocker panel side skirt clip n/s	n	\$	103.20	✓
1	Front suspension crossmember assy		\$	2,673.20	?
1	Front suspension crossmember o/s stay		\$	113.40	?
1	Front suspension crossmember n/s stay		\$	113.40	?
2	Front knuckle arm o/s & n/s	Bz	\$	1,170.40	✓
2	Front lower arm o/s & n/s		\$	1,275.00	?
2	Front lower arm ball joint o/s & n/s		\$	457.00	?
2	Front shock absorber o/s & n/s	\$ Bz	\$	907.20	✓
2	Front shock absorber mounting o/s & n/s		\$	380.20	?
1	Front driveshaft o/s		\$	2,272.90	?
1	Front driveshaft n/s	Pr	\$	2,055.80	✓
2	Front wheel bearing hub o/s & n/s	Bz/n/s	\$	1,098.40	✓
1	Front stabiliser bar		\$	239.50	?
2	Front stabiliser bar rod o/s & n/s		\$	393.40	?
1	Front steering rack and pinion		\$	1,658.20	?
2	Front steering rack end tie rod		\$	257.20	?
1	Front automatic transmission assy		\$	18,385.60	?
TOTAL			\$	70,528.79	
LESS			\$	17,632.20	
			\$	<u>52,896.59</u>	

Special Nett

1	Front radiator coolant	\$	50.00	?
1	Auto transmission fluid	\$	120.00	?
2	Front tyre	Pr	\$4w 700.00	508 n
2	Front alloy sport rim	n/s	\$ 1,900.00	✓

Total Materials Cost : \$ 55,666.59

Labour Cost

To remove all damaged parts with all necessary components/attachments. To apply hot-works where necessary, straighten chassis members, repair/reshape dented body panels, in accordance with factory specifications. Replace damaged parts, refit and align into position. Refit all necessary components/attachments.

\$ 2,800.00 1600

To remove/refit air-con condenser with all necessary pipes and hoses. Vacuum and replenish cooling agent. Check for proper function.

\$ 250.00 100

To remove/refit radiator assembly with all connecting hoses. Replenish cooling agent and check for proper function.

\$ 220.00 50

To remove/refit power steering rack assembly with all attachments. Refill power steering fluid, check for proper function.

\$ 350.00

To dismantle all necessary attachments/components, pipes, hoses, wirings in order to lift engine/gearbox assembly. Refit engine/gearbox with all necessary attachments and components. Reset and test engine for proper function.

\$ 850.00 ?

To conduct engine tests and reset to factory specifications.

\$ 250.00 150

To perform diagnostic checks on control units. Reset to factory specifications

\$ 380.00 ?

To set vehicle on chassis alignment bench, inclusive of all necessary preparatory works.

\$ 380.00 250

To remove/refit front undercarriage/suspension assembly with all attachments/components.

\$ 750.00 320

To conduct wheel alignment .

\$ 120.00 60

To renew n/s front wheel rim/tyre and conduct wheel balancing.

\$ 150.00 } 401

To renew o/s front wheel rim/tyre and conduct wheel balancing.

\$ 150.00 }

To transfer door window mechanisms with motor assembly, door glass and all attachments.

nn \$ 220.00 X

To remove/renew front wire harness, all related connectors.
Check proper function. Focus headlights.

\$ 1,200.00 ?

To remove andrefix front dashboard to facilitate the repairs.

\$ 650.00 ?

To provide towing service using "King Dolly

(Bill) \$ 150.00 ?

To spray paint replaced/repared body parts inclusive of preparatory works and painting materials.

\$ 2,500.00 18001

To apply underseal and rust-proofing on the affected areas.

\$ 280.00 1202

DURATION OF REPAIR: TWENTY EIGHT (28) WORKING DAY