

HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332 Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: Info@huahong.com.sg

Estimate Repair List

03 May 2019

QUOT201905-000008 HHTPCLAIMS19-68

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 ANSON RD, #16-00 SPRINGLEAF TOWER SINGAPORE 079909

Attn: Motor Claims Department

ACCIDENT INVOLVING SMA7623Y & GX3930L ON 30/04/2019 ALONG KEONG SAIK ROAD AT **ABOUT 1120 HOURS**

Insured

HUA HONG PTE LTD

Vehicle Registration No.

SMA7623Y

Vehicle Make

TOYOTA

Vehicle Model

C-HR HYBRID 1.8S CVT

Vehicle Chassis No.

ZYX102114433

Policy No.

5087272209-03

Date of Accident : 30/04/2019			Type of Claim: Third Party	
S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper X 1/2		\$ 546.00
2	10	Front Bumper Clip X SUC	\$ 2.50	\$ 25.00
3	1	Front Bumper Retainer (RH) X S v.		\$ 113.90
1	1	Front Fender Arch Garnish		\$ 158.00
5	1	Front Head Lamp (RH) X Su		\$ 1,549.10
-	·		Less.20%	\$ 2,392.00 6 \$ 478.40 20 \$ 1,913.60 III
To dis	smantle a	& change front bumper, front RH head lamp, knocking & pu RH fender and all area affected by accident		\$ 500.00 2
_		re checking		\$ 20.00 /
To spray front bumper and front RH fender \$			\$ 400.00	
	PI	puin phreo	7% GST	\$ 2,833.60 \$ 198.35
	After	puin phieo	Total	\$ 3,031.95
	,	0.10		

Sun Pin CLIUL) 20/10/2020

Authorised by Claims Dept

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- · To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Dat Reg. No. 200900309M