# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

Est. Duration of Repair

: 2

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Ong Chin Kiat Date: 31 Dec 2020

## **Preliminary Advice**

Insured Vehicle No : GX3930L

TP Vehicle No : SMA7623Y Accident Date : 30/04/2019
Make : TOYOTA C-HR HYBRID Assignment Date : 02/05/2019

Date of Inspection : 20/10/2020

Inspection At : Hua Hong Pte Ltd (Sungei Kadut)

25D Sungei Kadut Street 1

Singapore 729332

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,833.60
Revised Amount	:S\$	738.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	738.50

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

#### Remarks

(	)	The vehicle is repairable at our adjusted	amount. We have also	confirmed excess and po	olicy coverage.
		Kindly let us have your authorisation.			

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: TP: WP