

2/13/2007

A.E.S. REC. BY:

REF: CS/ C7119007730 / R15d3

Special Instruction:

Surveyor: Rasyi

ASSIGNMENT (Office)

From (Person): Ong chin kiat

of CTI

Date/Time: 2.5.19 17.27 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 6BC 4585m

Insured: SMC 2690A

at Workshop m/s MOYA

Tel: 62623377

of 15 Fan Yoong Road

Policy No: DMPCSN18203218000

Claim No: SNM19D201937C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 29.4.19

(Client's Record):

CA / REV / REP. / REV 24 HRS

"nr"

Date/Time: 3.5.19 9.43 a.m

Person Contacted:

Nabilah

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate (✓)
	6BC 4585m - X	
	SMC 2690A - X	

REF: 46374

REF:

ASSIGNMENT

COE XPIRY: 2022/01/01

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBC 4585M
 at Workshop m/s: MOVA
 of: 15, PAN YOUNG RO
 Insured: CTI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 30K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBC 4585M Yr Regn: 2012 / July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: NISSAN URVAN 3.0 JNT c.c. 2953
 Colour: GOLD A/C: Insured / Std / NI / NA
 Sp. Reading: 241085 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JN1M64E2520796869
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: NI / S/Rim / STD A/Rim or
 Tyre Size: F: 195R15C
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or BGarnay
 Front: _____ Rear: _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 29/04/19 D.O.I. 03/05/19
 Survey held at MOVA (FY)
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FR 8 N/S REAR
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

offer repair limit 10K

17/05/19 confirmed HS \$10K / 9 days with Resul.
 (\$5,450.50 Red - 35%)

RECEIVED 17 MAY 2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 9

1) Typist
 Date/Time, File Return to?

☒ : Final Report

Resurvey No. of Trip: 1

2)

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I: (\$ 10K HS)

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2019		02 May 2019 17:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	PRAMOJ S/O SANKAR, ID: S8141825Z			
Main Claimant:	MOVA AUTOMOTIVE PTE LTD, Co. Reg. No.: 198904033G			
Vehicle Reg. No.:	GBC4585M	Date of Loss:	29/04/2019 20:00 - :59 [81 Months and 13 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D201937C02	Policy/Cover Note No.:	DMPCSN18203218000 (Comprehensive) Coverage: 28/06/2018 - 27/06/2019	
Vehicle Reg. No. (Insured):	SMC2690A	Policy No. (Claimant):	2018-V0104946-VCV	
		Excess:	S\$0.00	
Repairer:	Mova Automotive Pte Ltd (FAN YOONG BRANCH) 15 Fan Yoong Road, CNG Singapore Centre, 629792 Boon Lay - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]			
Claimant's Insurer:	Great Eastern General Insurance Limited (HQ) - Tel: +65 248 2888			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/05/2019]			
Driver/Custodian (Insured):	PRAMOJ S/O SANKAR (/ Male) , NRIC: S8141825Z Email:			
Adj Asg. Remarks:	please arrange to contact Nabilah at 6262 3377 to arrange for survey tomorrow morning. thank you.			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Company

4033G

GBC4585M

Yes

02 May 2019

NISSAN

URVAN 3.0 5MT ABS AB 5DR LWB PANEL

Gold

2011

ZD30297912K

JN1MG4E25Z0796869

-

\$30,748.00

16 Jul 2012

16 Jul 2012

1

\$1,538.00

No

-

\$0.00

15 Jul 2022

C - Goods Vehicle & Bus

10

\$58,553.00

\$18,746.00

\$18,746.00

The information contained herein is correct as at 02 May 2019

OK

30,000
 18,746

 11,254

Shirley Hiew (LKK Auto)

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Monday, 13 May 2019 2:29 PM
To: Alan Chng
Cc: Shirley Hiew (LKK Auto)
Subject: RE: finalization for veh no:GBC4585M

Hi Alan,

Finalised amount repair limit 10k confirmed

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Alan Chng [mailto:tuckmeng@mova.com.sg]
Sent: Wednesday, 8 May, 2019 2:07 PM
To: Rasul (LKKAuto)
Cc: Admin A
Subject: finalization for veh no:GBC4585M

Dear Rasul,

Please refer the attach to confirm the COR & working days.
Repair cost lump sum limits \$10,000 & 9days.
Thanks!

Best Regards
Alan Chng
Claims Estimator
Mova Automotive Pte Ltd
H/P 9686 9276
Office No:6262 3377
Fax No:6264 3151

TP China Taipei

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/04/2019 18:09
Date Of Accident	29/04/2019 20:00
Exact Location Of Accident	UPPER SERANGOON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC4585M
Insured/Policyholder	
Name Of Registered Owner	MOVA AUTOMOTIVE PTE LTD
Co Reg No	198904033G
Email Address	AVRIL@MOVA.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62723892

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN 3.0 5MT ABS AB 5DR LWB PANEL

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2018-V0104946-VCV
Cover Note Number	

Driver

Name of Driver	TAN WEI JIE
NRIC No	S8412072C
Date Of Birth	23/04/1984
Occupation	INDOOR
Date Of Driving Pass	21/04/2006
Driving Experience	13 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90077275
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 608 BEDOK RESERVOIR ROAD #10-706
Postcode	470608
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : AH BOON GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC2690A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PRAMOJ S/O SANKAR
NRIC/Passport Number	S8141825Z
Contact Number	96537625
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLS1015J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHOO KOK CHIANG
NRIC/Passport Number	S7406229F
Contact Number	91398874
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



A: GBC 4585M
B: SMC 2690A
C: SLS1015J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: GBC 4585M	ACCIDENT DATE & TIME: 29/4/19 20:00
CONTACT NUMBER: 90077215	E-MAIL ADDRESS:
LOCATION: Upper Serangoon Road	
On 29/4/19 around 20:00, I am travelling along Upper Serangoon Road. The vehicle C (in front of my vehicle) SLS1015J did a jam brake. I manage to stop in time. However, the vehicle B SMC 2690A cannot stop in time and hit my vehicle. The impact caused my vehicle to move forward and hit the vehicle in front of my car.	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Estimate

02/05/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- GBC4585M

Veh Model :- NISSAN URVAN

Estimate# :- CK419086

Claim # :-

ACC. Date :- 29/04/19

Terms :- C.O.D Days

Remarks :- *Alan 9689276*

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 100B,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT BUMPER <i>TORN</i>	1 PC	680.00	680.00
2.	TAILGATE <i>RA</i>	1 PC	1,680.00	1,680.00
3.	REAR BUMPER <i>DE</i>	1 PC	595.00	595.00
LIST TOTAL S\$				2,955.00
30% DISCOUNT S\$				-886.50
				2,068.50
NET ITEMS :				
1.	FRONT BUMPER REINFORCEMENT <i>RA</i>	1 PC	450.00	450.00
2.	FRONT BUMPER BRACKET <i>RA</i>	2 PCS	190.00	380.00
3.	FRONT BUMPER CLIPS <i>RA</i>	10 PCS	3.00	30.00
4.	FRONT PANEL <i>ONE</i>	1 PC	1,430.00	1,430.00
5.	FRONT GRILLE <i>CR</i>	1 PC	480.00	480.00
6.	FRONT GRILLE LOGO <i>nee</i>	1 PC	35.00	35.00
7.	FRONT GRILLE CLIPS <i>nee</i>	10 PCS	3.00	30.00
8.	HEADLAMP - LH - <i>SC</i> / RH - <i>cut</i>	2 PCS	780.00	1,560.00
9.	FRONT SIGNAL LAMP <i>LH 30X / RH - CR</i>	1 PCS	230.00	460.00
10.	AIR INTERCOOLER RH <i>CR</i>	1 PC	2,300.00	2,300.00
11.	AIR INTERCOOLATER AIR GUIDE RH <i>CR</i>	1 PC	195.00	195.00
12.	AIR CON EVAPORATOR UNITS <i>CR</i>	1 PC	1,680.00	1,680.00
13.	TAILGATE INNER BOARD <i>Xan</i>	1 PC	310.00	310.00
14.	TAIL LAMP <i>Xan</i>	2 PCS	310.00	620.00
15.	TAILGATE RUBBER <i>nee</i>	1 PC	280.00	280.00
16.	AIR CON BLOWER MOTOR UNITS - TBA <i>CR</i>	1 PC		
17.	FRONT WINDSCREEN MOULDING <i>nee</i>	1 PC	290.00	290.00
NET TOTAL S\$				10,530.00
10% DISCOUNT S\$				-1,053.00
				9,477.00
SPECIAL NET ITEMS :				
1.	FRONT NUMBER PLATE <i>CR</i>	1 PC	35.00	35.00
2.	TAILGATE (10 PAX) STICKER <i>nee</i>	1 PC	10 15.00	15.00
3.	TAILGATE (70KM/H) STICKER <i>nee</i>	1 PC	10 15.00	15.00
4.	REAR WINDSCREEN SEALANT <i>nee</i>	1 PC	40.00	40.00
5.	FRONT WINDSCREEN SEALANT <i>nee</i>	1 PC	40.00	40.00
6.	REAR PARKING SENSOR <i>AW</i>	1 SET	200.00	200.00
SPECIAL NET TOTAL S\$				345.00
LABOUR :				
TO INSPECT FRONT LIGHTING WATER & LEAKAGE TEST				40.00
TO REMOVE & INSTALL FRONT WINDSCREEN				120.00
TO REMOVE & INSTALL REAR WINDSCREEN				120.00

Estimate

02/05/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 134763

Veh # :- GBC4585M

Veh Model :- NISSAN URVAN

Estimate# :- CK419086

Claim # :-

ACC. Date :- 29/04/19

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE			
	TO REMOVE & INSTALL DASHBOARD			
	TO REMOVE & INSTALL AIR CON EVAPORATOR IN ORDER TO CUT OFF FRONT PANEL			
	TO CUT OFF FRONT PANEL, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS			
	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS			
	TO APPLY RUST PROOF ON AFFECTED AREAS			
	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS			
	LABOUR TOTAL S\$			

8/5/19
Rasul
Hp 90010068
9 days
L/S
03/05/19 @ 1210
Reg after repair

60 ~~100.00~~
60 ~~300.00~~
? 80 ~~160.00~~
900 ~~1,200.00~~
40.00
60 ~~80.00~~
1000 ~~1,400.00~~
3,560.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 15,450.50

GST @ 7 % 1,081.54

AMOUNT DUE S\$ 16,532.04

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary (extra) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

limits. 10K

Estimate

02/05/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- GBC4585M

Veh Model :- NISSAN URVAN

Estimate# :- CK419086

Claim # :-

ACC. Date :- 29/04/19

Terms :- C.O.D Days

Remarks :- Alan 9689276

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT BUMPER <i>TORN</i>	1 PC	680.00	680.00
2.	TAILGATE <i>BH</i>	1 PC	1,680.00	1,680.00
3.	REAR BUMPER <i>PC</i>	1 PC	595.00	595.00
	LIST TOTAL S\$			2,955.00
	30% DISCOUNT S\$			-886.50
				2,068.50
NET ITEMS :				
1.	FRONT BUMPER REINFORCEMENT <i>9175</i>	1 PC	450.00	450.00
2.	FRONT BUMPER BRACKET <i>107</i>	2 PCS	190.00	380.00
3.	FRONT BUMPER CLIPS <i>8257.50</i>	10 PCS	3.00	30.00
4.	FRONT PANEL <i>one</i>	1 PC	1,430.00	1,430.00
5.	FRONT GRILLE <i>one</i>	1 PC	480.00	480.00
6.	FRONT GRILLE LOGO <i>one</i>	1 PC	35.00	35.00
7.	FRONT GRILLE CLIPS <i>one</i>	10 PCS	3.00	30.00
8.	HEADLAMP <i>LH-1/1RH-1</i>	2 PCS	780.00	1,560.00
9.	FRONT SIGNAL LAMP <i>LH-1/1RH-1</i>	2 PCS	230.00	460.00
10.	AIR INTERCOOLER RH <i>one</i>	1 PC	2,300.00	2,300.00
11.	AIR INTERCOOLER AIR GUIDE RH <i>one</i>	1 PC	195.00	195.00
12.	AIR CON EVAPORATOR UNITS <i>one</i>	1 PC	1,680.00	1,680.00
13.	TAILGATE INNER BOARD <i>X</i>	1 PC	310.00	310.00
14.	TAIL LAMP <i>X</i>	2 PCS	310.00	620.00
15.	TAILGATE RUBBER <i>one</i>	1 PC	280.00	280.00
16.	AIR CON BLOWER MOTOR UNITS - TBA <i>one</i>	1 PC		
17.	FRONT WINDSCREEN MOULDING <i>one</i>	1 PC	290.00	290.00
	NET TOTAL S\$			10,530.00
	10% DISCOUNT S\$			-1,053.00
				9,477.00
SPECIAL NET ITEMS :				
1.	FRONT NUMBER PLATE <i>one</i>	1 PC	35.00	35.00
2.	TAILGATE (10 PAX) STICKER <i>one</i>	1 PC	15.00	15.00
3.	TAILGATE (70KM/H) STICKER <i>one</i>	1 PC	15.00	15.00
4.	REAR WINDSCREEN SEALANT <i>one</i>	1 PC	40.00	40.00
5.	FRONT WINDSCREEN SEALANT <i>one</i>	1 PC	40.00	40.00
6.	REAR PARKING SENSOR <i>one</i>	1 SET	200.00	200.00
	SPECIAL NET TOTAL S\$			345.00
LABOUR :				
	TO INSPECT FRONT LIGHTING WATER & LEAKAGE TEST			40.00
	TO REMOVE & INSTALL FRONT WINDSCREEN			120.00
	TO REMOVE & INSTALL REAR WINDSCREEN			120.00

9175
107
8257.50
11
10326
P-10,533
SH-335
+ 2C-2480
13348
-20618
10,678.40
SH-335
10,512.80
Repair limit 10K
9 days

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-008864-2

Estimate

02/05/2019

CHINA TAIPING INSURANCE (S) PTE LTD

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 134763

Veh # :- GBC4585M

Veh Model :- NISSAN URVAN

Estimate# :- CK419086

Claim # :-

ACC. Date :- 29/04/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE			60 100.00
	TO REMOVE & INSTALL DASHBOARD			60 300.00
	TO REMOVE & INSTALL AIR CON EVAPORATOR IN ORDER TO CUT OFF FRONT PANEL			? 80 160.00
	TO CUT OFF FRONT PANEL, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS			900 1,200.00
	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS			40.00
	TO APPLY RUST PROOF ON AFFECTED AREAS			60 80.00
	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS			1000 1,000.00
	LABOUR TOTAL S\$			3,560.00

Repair
HP 90010068
9 days
L/S
03/05/19 @ 1210
Reg after repair
LC-2480

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 15,450.50

GST @ 7 % 1,081.54

AMOUNT DUE S\$ 16,532.04

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary device(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119007770/R1SD3N2

Date: 28/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN18203218000
Claimant Vehicle No :	GBC4585M	Insured Vehicle No :	SMC2690A
Date of Loss:	29/04/2019	Nature of Claim:	TP
		Claim No:	SNM19D201937C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC4585M		
Make & Model:	NISSAN URVAN, 3.0 5MT ABS AB 5DR LWB PANEL (A)		
Reg. Date:	16/07/2012 (Man. Year: 2011)	Engine No:	ZD30297912K
Colour:	Gold	Chassis No:	JN1MG4E25Z0796869
Engine Capacity:	2953 cc	Odometer:	241085 km
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Bearway 7 mm	Rear Left Side:	Bearway 7 mm
Front Right Side:	Bearway 7 mm	Rear Right Side:	Bearway 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,890.50	10,661.00	1,229.50	10.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	2,480.00	1,080.00	30.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,450.50	13,141.00	2,309.50	14.95
Approved Total (Overridden) (S\$)		10,000.00		
(S\$)	15,450.50	10,000.00	5,450.50	35.28
+ GST 7.00/7.00% (S\$)	1,081.54	700.00	381.54	35.28
Nett Amount (S\$)	16,532.04	10,700.00	5,832.04	35.28

INSPECTION

Date of Assignment:	02/05/2019	
Date Inspected:	03/05/2019 Inspected At:	Mova Automotive Pte Ltd (FAN YOONG BRANCH) 15 Fan Yoong Road, CNG Singapore Centre Singapore 629792

Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 May 2019)	
Parts:	N/A	NISSAN URVAN 3.0 5MT ABS AB 5DR LWB PANEL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC4585M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	680.00 FL	*680.00 FL
2	1		*TAILGATE	Bent	1,680.00 FL	*1,680.00 FL
3	1		*REAR BUMPER	Deformed	595.00 FL	*595.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	450.00 FN	*450.00 FN
5	2		*FRONT BUMPER BRACKET	Bent	380.00 FN	*380.00 FN
6	10		*FRONT BUMPER CLIPS	Necessary	30.00 FN	*30.00 FN
7	1		*FRONT PANEL	Buckled	1,430.00 FN	*1,430.00 FN
8	1		*FRONT GRILLE	Cracked	480.00 FN	*480.00 FN
9	1		*FRONT GRILLE LOGO	Necessary	35.00 FN	*35.00 FN
10	10		*FRONT GRILLE CLIPS	Necessary	30.00 FN	*30.00 FN
11	2		*HEADLAMP	N/s Scratched/O/s Cut	1,560.00 FN	*1,560.00 FN
12	1		*FRONT SIGNAL LAMP	O/s Cracked/N/s Serviceable	460.00 FN	*230.00 FN
13	1		*AIR INTERCOOLER RH	Cracked	2,300.00 FN	*2,300.00 FN
14	1		*AIR INTERCOOLER AIR GUIDE RH	Serviceable	195.00 FN	*- FN
15	1		*AIR CON EVAPORATOR UNITS	Cracked	1,680.00 FN	*1,680.00 FN
16	1		*TAILGATE INNER BOARD	Not Necessary	310.00 FN	*- FN
17	2		*TAIL LAMP	Not Necessary	620.00 FN	*- FN
18	1		*TAILGATE RUBBER	Necessary	280.00 FN	*280.00 FN
19	1		*AIR CON BLOWER MOTOR UNITS (NPA)	Cracked	0.00 FN	*- FN
20	1		*FRONT WINDSCREEN MOULDING	Necessary	290.00 FN	*290.00 FN
21	1		*FRONT NUMBER PLATE	Cracked	35.00 FS	*35.00 FS
22	1		*TAILGATE (10 PAX) STICKER	Necessary	15.00 FS	*10.00 FS
23	1		*TAILGATE (70KM/H) STICKER	Necessary	15.00 FS	*10.00 FS
24	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
25	1		*FRONT WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
26	1		*SET REAR PARKING SENSOR	Not Working	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

	Sub Total (S\$)	13,830.00	12,465.00
- List Item Discount on L Items 30.00/30.00% (S\$)	886.50		886.50
- Nett Item Discount on N Items 10.00/10.00% (S\$)	1,053.00		917.50

Total Parts (S\$) 11,890.50 10,661.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO INSPECT FRONT LIGHTING WATER & LEAKAGE TEST	New	40.00	40.00
2	TO REMOVE & INSTALL FRONT WINDSCREEN	New	120.00	120.00
3	TO REMOVE & INSTALL REAR WINDSCREEN	New	120.00	120.00
4	TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE	New	100.00	60.00
5	TO REMOVE & INSTALL DASHBOARD	New	300.00	60.00
6	TO REMOVE & INSTALL AIR CON EVAPORATOR IN ORDER TO CUT OFF FRONT PANEL	New	160.00	80.00
7	TO CUT OFF FRONT PANEL,STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS	New	1,200.00	900.00
8	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	40.00	40.00
9	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	80.00	60.00
10	TO SPRAY PAINT ON REPLACED,REPAIRED AREAS	New	1,400.00	1,000.00
Gross Labour Cost (S\$)			3,560.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >