

ASS. REC. BY:

REF: CS/PC1/9007795/Eqd3.12

Special Instruction:

CWS

Surveyor: Steve L

ASSIGNMENT (Office)

From (Person): May chua

of PC1

Date/Time: 3.5.19 12.46 p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLQ 43125

Insured: SHB 4030 G

at Workshop m/s Teamwork Garage

Tel: 6844 2475

of BIK 53 Wb Ave 1 #01-24

Policy No:

Claim No: D19002874MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30.4.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3.5.19 1.56 p.m

Person Contacted: Darren

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SLQ 43125 - NA/INC19007655/24	D.O.A - 30/04/2019
	SHB 4030 G - NA/INC19007655/24	D.O.A - 30/4/2019
26/5/19 @ 5	05p - revised to May Chua by email.	

Steve

REF: PCT

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
QD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s: _____
ol: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
XXX	

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLR 43125 Yt Regn: 6/6/16
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Lexus 15200T cc 1998
Colour: Silver A/C Insured / Std / NI / NA
Sp. Reading: 57231 T/Rndln: Insured / Std / NI / NA
Eng/No: _____
C/No: JTHBA ID 2505928689
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 255/302R19
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal. 7 mm R/Bal. 7 mm
L/Bal. 7 mm L/Bal. 7 mm
D.O.A. 20 20/4/19 D.O.I. 3/5/19
Survey held at Teamnik
Des. of Damages: Frl Rear / O/S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision

Date / Time : Action / Instruction

MV-119K

* Bryan check the report 7/5/19, 5:40pm
Steve
pls see my remark.

13/6/19 - Finalize confm \$5950, 4 days
used to 7/6/21, 55%.

RECEIVED 1 JUN 2019

Date/Time. File Pass to: ☐ : Prel. Report
14/6/19 ☐ : Final Report
Date/Time. File Return to?

Days Of Repair: 4
Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____
Transportation

Report Format: 7p
Lump Sum / LB: 5950

3x15 45
170+45
50
50+50
81
17/6/19
446



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002874MFSH
Our Ref: CS/FCI19007795/Eqd3

Date: 06 May 2019

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 4312S .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/05/2019 at the premises of M/s TEAMWORK GARAGE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,860.00 (SN+LABOUR)</u> .
Revised Estimate Amount	: S\$ <u>1,480.00</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Steve
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	02-05-2019	Our Ref No. D19002874MFSH
Accident Date	30-04-2019	Claim Type. Third Party
Insured Vehicle	SHB4030G	Third Party Vehicle. SLQ4312S
Survey Location	BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK	
Contact Person.	SHU SHAN	
Contact No.	68442425/ 68442425	Fax No. 68442474
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TEAMWORK GARAGE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Steve Chen (LKK Auto)

From: claims@teamworkgarage.com
Sent: Thursday, June 13, 2019 5:23 PM
To: Steve Chen (LKK Auto)
Cc: 'TEAMWORK GARAGE CLAIMS'
Subject: RE: SLQ4312S LEXUS IS250

Hi steve ,

We confirm COR @ \$5950 and DOR @ 4 days

Thank you and have a nice day! ☺

letitia

Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore (408934)
Tel: 6844 2475 Fax: 6844 2474

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Thursday, June 6, 2019 7:24 PM
To: Darren <claims@teamworkgarage.com>
Subject: SLQ4312S LEXUS IS250

Dear Darren,

The finalize is \$5950 (L/S, before GST). 4 repair days.

Kindly confirm.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Darren [mailto:claims@teamworkgarage.com]
Sent: Thursday, June 06, 2019 10:29 AM
To: Steve Chen (LKK Auto)
Subject: SLQ4312S LEXUS IS250

Hi Steve,

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 6 May 2019 5:05 PM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'May Chua Hui Chin'
Subject: RE: SURVEY ASSESSMENT - D19002874MFSH/1
Attachments: CSFCI19007795Eqd3.pdf

Dear May,

Enclosed herewith preliminary advice of SLQ 4312S.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 3 May 2019 2:01 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19002874MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 3 May, 2019 12:46 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002874MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

SUPREME



CLICK HERE OR CALL FOR A TEST DRIVE
6479 6280

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 10 Years Coc Renewal Toyota Wish 1.8A

 2.99pp & 31 Admin Fee/yr
Finance 2 Years Warranty 3.20pp
Down Monthly From \$758
GV Credit Pte Ltd - Borealis

Think One Automobile

NEW & USED
COMMERCIAL VEHICLES



Browse by Category

« Back (1 2 3) Next »

Sort by Date Posted 20 results/page

55 vehicles

Lexus IS

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Lexus IS		Any	Any	Any	Any	Any	Any	Available
	Lexus IS Turbo IS200t Executive	\$116,800	\$13,890 /yr	23-Feb-2016	1,998 cc	36,000 km	Luxury	Available
Borneo Motor 5 Years Unlimited Mileage Warranty, Low Mileage Of 36K Km, 100% Loan Available, Vehicle In Showroom Condition, Grooming Done By Professional Groomer. Elegant Grey With Black Leather Seats...								
Shuang Hup Credit								
Posted: 29-Apr-2019 Tags: 2016 Lexus IS, 2016 Lexus is, Lexus IS, Lexus is, Lexus IS, is, Used Lexus								
	Lexus IS Turbo IS200t Executive	\$116,000	\$13,740 /yr	29-Feb-2016	1,998 cc	50,100 km	Luxury	Available
Limited Period Only Loan Interest At 2.28%, Extremely Well Maintained And Fully Agent Maintained. This Beast Does Not Just Look Beautiful, It's 100% Accident-Free. View To Believe! Up To 70% Financing...								
Posted: 04-Mar-2019 Tags: 2016 Lexus IS, 2016 Lexus is, Lexus IS, Lexus is, Lexus IS, is, Used Lexus								
	Lexus IS Turbo IS200t Executive	\$116,000	\$13,470 /yr	21-Apr-2016	1,998 cc	59,700 km	Luxury	Available
Handsome Pearl White On Luxury Brown Interior! Borneo Syrs Unlimited Mileage Warranty! Just Serviced In March! Road Tax Till Oct 2019! Silent And Powerful Drive! Beautiful Condition Inside Out! Attrac...								
Posted: 24-Apr-2019 Tags: 2016 Lexus IS, 2016 Lexus is, Lexus IS, Lexus is, Lexus IS, is, Used Lexus								
	Lexus IS Turbo IS200t Executive	\$118,800	\$13,790 /yr	05-May-2016	1,998 cc	54,000 km	Luxury	Available
Graded A by STI Mileage Done Only 54000 Km. Full Agent Serviced. Under Full Agent Warranty. Excellent Condition! Buy With A Peace Of Mind From Award Accredited Company! Attractive Loan Package Interest From 2.78% And...								
Autolink Holdings Pte Ltd								
Posted: 04-May-2019 Tags: 2016 Lexus IS, 2016 Lexus is, Lexus IS, Lexus is, Lexus IS, is, Used Lexus								
	Experience Luxury-Class Standard With Audi A4							
Low Mileage Luxury Sedan Audi A4 2.0 S Line For Rent. Call Us For More Information!								
Find out more!								
	Lexus IS Turbo IS200t Executive	\$125,800	\$14,170 /yr	26-Aug-2016	1,998 cc	25,500 km	Luxury	Available
Graded A by STI Mileage Done Only 25500 Km. Full Agent Serviced. Under Full Agent Warranty. Excellent Condition! Buy With A Peace Of Mind From Award Accredited Company! Attractive Loan Package Interest From 2.78% And...								
Autolink Holdings Pte Ltd								
Posted: 04-May-2019 Tags: 2016 Lexus IS, 2016 Lexus is, Lexus IS, Lexus is, Lexus IS, is, Used Lexus								
	Lexus IS Turbo IS200t Executive	\$138,800	\$15,900 /yr	02-Sep-2016	1,998 cc	34,000 km	Luxury	Available
Impeccable Condition, Well Maintained By 1st Owner. Full Servicing And Maintenance Record With Lexus Service Centre, 160 Point Check And Certified By Borneo Motors Singapore. Extended 5 Years Warranty...								
Borneo Motors (S)								
Posted: 21-Mar-2019 Tags: 2016 Lexus IS, 2016 Lexus is, Lexus IS, Lexus is, Lexus IS, is, Used Lexus								
	Lexus IS Turbo IS200t Executive	\$133,800	\$14,640 /yr	28-Oct-2016	1,998 cc	27,677 km	Luxury	Available
1 Owner Agent Unit. \$2000 Republic Auto Warranty Workshop Credit, Full Service With Borneo/ Under Agent Warranty Till Oct.2019/100,000km. Buy With A Peace Of Mind. Enjoy Exclusive Low Interest Rate At...								
Republic Auto								
Posted: 07-Apr-2019 Tags: 2016 Lexus IS, 2016 Lexus is, Lexus IS, Lexus is, Lexus IS, is, Used Lexus								
	Lexus IS Turbo IS200t F Sport	\$128,500	\$13,300 /yr	18-Nov-2016	1,998 cc	46,100 km	Luxury	Available
The IS F Sport Is Designed To Stimulate The Senses, Inside Out. Flawless Paintwork. Bought With 5 Years Agent Warranty, Full Agent Servicing Records. High Spec With Customisable Digital Instrument Cla...								

Compare

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Enquire PARF/COE Rebate for Registered Vehicle	
Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9529A
Vehicle Details	
Vehicle No.:	SLQ4312S
Vehicle to be Exported:	No
Intended Deregistration Date:	06 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS IS200T EXECUTIVE
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	8ARZ042696
Chassis No.:	JTHBA1D2505028689
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$37,505.00
Original Registration Date:	06 Jun 2016
First Registration Date:	06 Jun 2016
Transfer Count:	1
Actual ARF Paid:	\$44,507.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Jun 2026
PARF Rebate Amount:	\$33,380.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jun 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,010.00
COE Rebate Amount:	\$36,120.00
Total Rebate Amount:	\$69,500.00

The information contained herein is correct as at 06 May 2019

OK



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC number : 201015366H
 Repair Performa Invoice

First Capital Insurance Ltd
 6 Raffles Quay
 Singapore 048580

Vehicle number	SLQ43125
Make / Model	LEXUS/IS250
Chassis number	JTHBA1D2505028689
Accident date	30 April 2019
Reference	1904-73

Qty Particulars

PARTS REPLACEMENT - LIST ITEMS	
1	REAR BUMPER / DD
1	REAR BUMPER LOWER GARNISH / CNT
2	REAR BUMPER RETAINER / BR
2	REAR BUMPER BRACKET X
1	REAR BUMPER REINFORCEMENT ? / DD
1	REAR BUMPER SPONGE ? / BR
1	REAR PDC SENSOR ? / BR
4	SENSOR WIRE HARNESS X
1	REAR BUMPER REFLECTOR X LH - BR
1	KEYLESS SENSOR X / BR
1	END PANEL ? ? ? / DD
1	END PANEL TOP GARNISH / CRG
1	SPARE TYRE SIDE SPONGE LH X / BR
1	SPARE TYRE SIDE SPONGE RH X
1	REAR EXHAUST SILENCER / DD X R
2	REAR EXHAUST MOUNTING X
1	BOOTLID / DD
1	BOOTLID EMBLEM LOGO / NCC
1	BOOTLID EMBLEM - LEXUS / ACC
1	BOOTLID EMBLEM - IS 250 / ACC
2	BOOTLID LAMP X
2	TAILAMP X
	Boat lock / DD
	Less 25 %
	Subtotal
	Balance C/F
PARTS REPLACEMENT - SPECIAL NETT ITEMS	
	Balance B/F
1 SET	REAR BUMPER CLIP
1	JOINT SEALANT
	Subtotal
	Balance C/F

S/No	LABOUR AND MISCELLANEOUS CHARGES	
	Balance B/F	0.00
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30
2	REMOVE, REFIT REAR LINING, TRIM AND GANRISH	150.00 50
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 20
4	REMOVE AND RENEW REAR EXHAUST SILENCER	150.00 80
5	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 50
6	PANEL BEATING ON AFFECTED AREAS	1000.00 840 5600
7	SPRAY PAINTING ON AFFECTED AREAS	1000.00 450 550
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
	Subtotal	2860.00
	Grand total	2860.00

Store
(LK11)

will provide

3/5/19

12:30 pm

4 days

L/S

Re AL spy

James P
6/5/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

First Capital Insurance Ltd
 6 Raffles Quay
 Singapore 048580

Vehicle number	SLQ43125
Make / Model	LEXUS/IS250
Chassis number	JTHBA1D2505028689
Accident date	30 April 2019
Reference	1904-73

Qty Particulars

PARTS REPLACEMENT - LIST ITEMS			
1	REAR BUMPER / DD	1132.75 ✓	989
1	REAR BUMPER LOWER GARNISH / CNT	690 ✓	
2	REAR BUMPER RETAINER / DR	172.50 ✓	
2	REAR BUMPER BRACKET X NAI	172.50 x	
1	REAR BUMPER REINFORCEMENT. ? / DD	577.75 ✓	453.60
1	REAR BUMPER SPONGE ? / DR	109.25 ✓	
1	REAR PDC SENSOR ? / DR	875 ✓	218.75
4	SENSOR WIRE HARNESS X NAI	327.25 x	
2	REAR BUMPER REFLECTOR X / (LH) DR	147.20 x	73.60
1	KEYLESS SENSOR X / DR	312.60 ✓	
1	END PANEL ? x / DD	753.25 ✓	
1	END PANEL TOP GARNISH / CNT	318.55 ✓	
1	SPARE TYRE SIDE SPONGE LH x / DR	454.25 ✓	317
1	SPARE TYRE SIDE SPONGE RH x NAI	454.25 x	
1	REAR EXHAUST SILENCER / DD	2187.30 ✓	1454
2	REAR EXHAUST MOUNTING x NAI	1570 x	
1	BOOTLID / DD	2035.50 ✓	1450
1	BOOTLID EMBLEM LOGO / NCC	80.50 ✓	
1	BOOTLID EMBLEM - LEXUS / NCC	86.25 ✓	
1	BOOTLID EMBLEM - IS 250 / NCC	89.70 ✓	
2	BOOTLID LAMP x NAI	846.40 x	13514.65
2	TAILAMP X NAI	1115.50 x	
1	BootLid Lock / DD - 419.80	0.00	7988.35
		Less 25 %	0.00
		Subtotal	0.00
		Balance C/F	0.00
PARTS REPLACEMENT - SPECIAL NETT ITEMS			
	Balance B/F	0.00	
1 SET	REAR BUMPER CLIP NCC /	30.00 /	
1	JOINT SEALANT NCC /	150.00 jo	
		Subtotal	0.00
		Balance C/F	0.00

S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	0.00
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	150.00 50
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 20
4	REMOVE AND RENEW REAR EXHAUST SILENCER	150.00 80
5	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 50
6	PANEL BEATING ON AFFECTED AREAS	1000.00 4400 600
7	SPRAY PAINTING ON AFFECTED AREAS	1000.00 450 550
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
	Subtotal	2860.00
	Grand total	2860.00

Store
(CLKK)

W/L Prip Jln

3/5/19

12:30 pm

4 days

L/S

Re AL spray

P-5991.26

AI-60

L-1410

7461.26

L/S-5969.00

= 5950

13176.71



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19007795/Eqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-06-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4030G	Veh. Inspected	SLQ 4312S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002874MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	03/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA LEXUS IS200T	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTHBA1D2505028689	Colour	SILVER	
Odometer	57231	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/30 ZR19	MICHELIN	7 mm	
L/H Front Tyre	255/30 ZR19	MICHELIN	7 mm	
R/H Rear Tyre	255/30 ZR19	MICHELIN	7 mm	
L/H Rear Tyre	255/30 ZR19	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/04/2019	Inspection Date	03/05/2019	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 4312S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED	1,132.75	989.00
1	REAR BUMPER LOWER GARNISH	CUT	690.00	690.00
2	REAR BUMPER RETAINER	BROKEN	172.50	172.50
2	REAR BUMPER BRACKET	NOT NECESSARY	172.50	-
1	REAR BUMPER REINFORCEMENT	DENTED	577.75	453.60
1	REAR BUMPER SPONGE	BROKEN	109.25	109.25
4	REAR PDC SENSOR	BROKEN (1 PC ONLY)	875.00	218.75
4	SENSOR WIRE HARNESS	NOT NECESSARY	327.75	-
2	REAR BUMPER REFLECTOR	N/S BROKEN	147.20	73.60
1	KEYLESS SENSOR	BROKEN	312.60	312.60
1	END PANEL	DENTED	753.25	753.25
1	END PANEL TOP GARNISH	CRUMPLED	318.55	318.55
1	SPARE TYRE SIDE SPONGE LH	BROKEN	454.25	317.00
1	SPARE TYRE SIDE SPONGE RH	NOT NECESSARY	454.25	-
1	REAR EXHAUST SILENCER	DENTED	2,187.30	1,454.00
2	REAR EXHAUST MOUNTING	NOT NECESSARY	156.40	-
1	BOOTLID	DENTED	2,035.50	1,450.00
1	BOOTLID EMBLEM LOGO	NECESSARY	80.50	80.50
1	BOOTLID EMBLEM-LEXUS	NECESSARY	86.25	86.25
1	BOOTLID EMBLEM-IS 250	NECESSARY	89.70	89.70
2	BOOTLID LAMP	NOT NECESSARY	846.40	-
2	TAILLAMP	NOT NECESSARY	1,115.50	-
1	BOOTLID LOCK	DENTED	419.80	419.80
	LESS 25% DISCOUNT		-3,378.74	-1,997.09
			10,136.21	5,991.26
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	JOINT SEALANT (SN)	NECESSARY	150.00	30.00
			180.00	60.00

Report Ref No. CS/FCI19007795/Eqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	CHECK REAR WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE, REFIT REAR LINING, TRIM AND GARNISH.		150.00	50.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	20.00
	REMOVE AND RENEW REAR EXHAUST SILENCER.		150.00	80.00
	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW.		200.00	50.00
	PANEL BEATING ON AFFECTED AREAS.		1,000.00	600.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	550.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	30.00
			2,860.00	1,410.00
	GRAND TOTAL		13,176.21	7,461.26
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,950.00

Report Ref No. CS/FC19007795/Eqd3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.