

Steve (LKK) wil projudre 14/5/19, 10.15am
8372 8813 6 days

✓
S 1X0519

SERVICE ESTIMATE

42211 - C00001 SL: SERVICE SALES - PC

Ms Chua Seok Yin
Blk 11D Mount Sinai Lane
#05-15

Singapore 277053

Closed by : Derek Oh Siong Wee
Svc Consultant :
Remarks : Ms Chua Seok Yin

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 26/04/2019
WIP No. . : 11596
Veh.In/Out: 26/04/2019
*Tel.No. . : Mobile: 96184884
Reg.No. . : SMF6298H
Reg.date . : 19/11/2018
Mileage ... : 0
Chassis No: YV1XZACADK2080561

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BUMPER,FRT RH FENDER,FRT RH FENDER TRIM, FRT RH DOOR,FRT RH DOOR TRIM, FRT RH DOOR SEAL,ETC	0	3200.00	0		3,200.00 S	1600
800	TO PUTTY SPRAY PAINT ON FRT RH FENDER,FRT RH DOOR,ETC	0	2100.00	0		2,100.00 S	1400
031	TO REPLACE FRONT RH RIM	0	50.00	0		50.00 S	/
10	COMPUTERISED WHEEL ALIGNMENT	0	280.00	0		280.00 S	/
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	480.00	0		480.00 S	/
	FENDER FRT RH XC40 1	1.0 EA	1180.80			1,180.80 S	DD
	FENDER CARRIER RH XC	1.0 EA	133.90			133.90 S	?
	FENDER CARRIER RH XC	1.0 EA	11.90			11.90 S	?
	MUDGUARD WIDENER FRT	1.0 EA	94.10			94.10 S	crj
	DOOR TRIM MOULDING F	1.0 EA	184.60			184.60 S	cbj
	WHEEL ARCH LINER RH	1.0 EA	157.10			157.10 S	X

SERVICE ESTIMATE

42211 - C00001 SL: SERVICE SALES - PC

Ms Chua Seok Yin
Blk 11D Mount Sinai Lane
#05-15

Singapore 277053

Closed by : Derek Oh Siong Wee
Svc Consultant :
Remarks : Ms Chua Seok Yin

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 26/04/2019
WIP No. . : 11596
Veh.In/Out: 26/04/2019
*Tel.No. . : Mobile: 96184884
Reg.No. . : SMF6298H
Reg.date. : 19/11/2018
Mileage . : 0
Chassis No: YV1XZACADK2080561

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER CLIP 8x8,5 <i>NIEC</i>	10.0 EA	5.40			54.00	S
	DOOR PANEL FRT RH XC <i>X R</i>	1.0 EA	1536.80			1,536.80	S
	EXTERIOR ADHESIVE GL <i>X</i>	1.0 EA	142.20			142.20	S
	D WELDING PRIMER <i>X</i>	1.0 EA	350.00			350.00	S
	ADHESIVE TUBE CHEMIC <i>X</i>	2.0 EA	151.60			303.20	S
	ALLOY RIM 7,5x18" 5- <i>CUT</i>	1.0 EA	807.90			807.90	S

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed ~~and~~
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Total 6,110.00
Parts Total 4,956.50
Package Total 0.00

Gross Total. 11,066.50
Net..... 11,066.50
GST @ 7.0% 774.66
Total..... 11,841.15
Paid..... 0.00
Please Pay.. 11,841.15

GST: S=StdRated; O=OutOfScope; Z=ZeroRated