



FALCON-AIR

LIM WEE MENG EDMOND
BLK288A BUKIT BATOK ST 25 #10-232
SINGAPORE 650288

Attention : Motor Claim Department
Contact : 96368055

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003451

Date : 03/05/2019
Vehicle Num. : SMH4161X
Make/Model : MERC BENZ C180
Chassis/Eng# :
Accident Date : 30/04/2019
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
TO REPAIR/RESpray FRONT BUMPER

Labour Total S\$:

~~300.00~~ 250
300.00

PASU
Ap 9001068
1 day
P/P
26/11/2020 P1025
Respray after repair

E. & O.E.

Total S\$: 300.00



for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultant, Hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg