

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/TP/0579/2019/DY/TF  
Date : 6-May-19

**Vehicle NOT IN workshop. Kindly arrange for survey.**

**Your insured vehicle : SGS 7272 C**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

Owner's Name : Mr. Teh Thuan Khoon  
Address : 20D Watten Rise  
Singapore 287384  
Telephone : HP +65 86936566  
Type of Claim : Third Party Claims  
Policy No. : 2100450441-03  
Vehicle No : **SKX 2530 X** ✓  
Model Code : Audi Q7 2.0 TFSI QU  
Model / Year : Nov-15  
Engine No : CYR 001236  
Chassis No : WAUZZZ4M8GD021936  
Mileage : -  
Date In :  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 25-Apr-19  
Place of Accident : The Windstedt School Parking Lot

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SKX 2530 S

| S/N                  | Nature of Jobs                             | Estimated Charges                                                                |
|----------------------|--------------------------------------------|----------------------------------------------------------------------------------|
| 1                    | To respray rhs rear door and door cover. ✓ | <del>\$ 1,500.00</del> <sup>800</sup> <sub>door: 700</sub> <sub>cover: 200</sub> |
| 2                    | To carry diagnostic.                       | S/N \$ 192.00 *                                                                  |
| TOTAL LABOUR CHARGES |                                            | : \$ 1,692.00                                                                    |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKX 2530 X

| S/N               | Parts Description                     | Damage Parts & Prices |         |
|-------------------|---------------------------------------|-----------------------|---------|
|                   |                                       | S/NETT                | REMARKS |
| 1                 | REAR DOOR LOWER COVER - RH <i>new</i> | \$ 545.00             | ✓       |
| 2                 | SUNDRIES <i>new</i>                   | \$ 200.00             | *       |
| TOTAL SPARE PARTS |                                       | \$ 745.00             |         |
| TOTAL LABOUR      |                                       | \$ 1,692.00           |         |
| GRAND TOTAL       |                                       | \$ 2,437.00           |         |

All charges are not inclusive of GST.

Legend :      Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Lj  
Surveyed Date : 09/05/19  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised , 03 days

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant