

22/03/2019

ASS. REC. BY:

REF: CS/SM0190078731 4qdz

Special Instruction:

Surveyor:

MUKTU

ASSIGNMENT (Office)

From (Person):

Melvin Ye

of

SMO

Date/Time:

6.5.19 9.14 p.m

Estimated Cost:

Bill to:

GD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

GV3086T

Insured:

GBD2748T

at Workshop m/s

HUP motor Trading

Tel:

98154655

of

BIC 9004 Tampine street 93, # 01-120

Policy No:

D18MPCVE003178

Claim No:

CMD1902163

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3.6.19

7.5.19 (1.30-3.30)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

6.5.19

Person Contacted:

David Ang

Vehicle IN (OUT)

Date/Time

Action/Instruction

Estimate (✓)

GV3086T - NA/MSG19007846/24

D.O.A - 03/05/2019

GBD2748T - X

09/5/19 @ 9.56am revised to Melvin Ye via. Meimen.

REF: SMO

ASSIGNMENT

From:

Date: 7/5/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GY 3086 T

at Workshop m/s

Hup Motor

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

4pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GVA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

2

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 4452

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: GY 3086 T

Yr Regn:

3, 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Car /

Make:

Toyota Liteace

C.C

2.8x

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

266610

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

CR 42 5011191

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

1.85 R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

3/5/19

D.O.I.

7/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/5/19 4/5 @ 4000 Confirmed with David (Red 4945.11, 55%)

RECEIVED 10 MAY 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 4/5 4/5

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

250
10

260

Report Format:

Lump Sum / LB.1: (\$

MER-10

4000

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Melvin Ye

Date: 09 May 2019

Preliminary Advice

Insured Vehicle No	: GBD2748T	Accident Date	: 03/05/2019
TP Vehicle No	: GY3086T	Assignment Date	: 06/05/2019
Make	: TOYOTA LITEACE	Est. Duration of Repair	: 5.00
Date of Inspection	: 07/05/2019		
Inspection At	: HUP MOTOR TRADING & SERVICE (HQ) BLK 9004 TAMPINES STREET 93, #01-120 SINGAPORE 528838		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,731.36
Revised Amount	:S\$	4,425.38
Check Items (Estimated)	:S\$	595.65
Total	:S\$	5,021.03

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 May 2019		06 May 2019 09:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	JAPAN PACK SYSTEM PTE LTD, Co. Reg. No.: 199001590G		
Main Claimant:	SAN HE CAR REPAIRER, Co. Reg. No.: 27868500E		
Vehicle Reg. No.:	GY3086T	Date of Loss:	03/05/2019 13:00 - :59
Claim Type:	TP / CMTD1902163	Policy/Cover Note No.:	D18MTPCVE003178 (Comprehensive)
Vehicle Reg. No. (Insured):	GBD2748T	Policy No. (Claimant):	
		Excess:	
Repairer:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Melvin Ye - 6322 4667]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2019]		
Driver/Custodian (Insured):	NEO KENG KEONG (), NRIC: S6919827I, Tel: +6597988781 Email:		
Adj Asg. Remarks:	WS: DAVID ANG 98154655/ 67840039		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 6 May 2019 9:05 AM
To: hupmotor@gmail.com; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1902163/MYE - GBD2748T & GY3086T ACC ON 03.05.19 ALONG SLIP RD OF TOH GUAN RD INTO P.I.E. - Pls arr survey today

Without Prejudice

Our Reference: CMTD1902163/MYE
Your Reference: GY3086T

Hi David,

We acknowledged receipt of your claim submission.

Please be informed that **Mr. Melvin Ye** is the handler of this case.

As requested, we will appoint **LKK AUTO** to survey the above vehicle.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for GY3086T on a without Prejudice and any admission of liability basis.

Please submit your report via Merimen upon completion of survey

Aside to Melvin,

Please refer to the liability request from Hup Motor Trading & Service.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @ Download on the App Store or GET IT ON Google Play

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Henry, Irene James

Sent: Monday, May 06, 2019 7:57 AM

To: Claims - Motor Survey

Subject: FW: RE : ACCIDENT ON : 03/05/19, INVOLVING CLIENT'S (GY 3086 T) & YOUR INSURED (GBD 2748 T) ALONG SLIP RD OF TOH GUAN RD INTO P.I.E.

From: David Ang <hupmotor@gmail.com>

Sent: Sunday, 5 May, 2019 1:40 PM

To: Henry, Irene James <irene.henry@sompo.com.sg>

Subject: RE : ACCIDENT ON : 03/05/19, INVOLVING CLIENT'S (GY 3086 T) & YOUR INSURED (GBD 2748 T) ALONG SLIP RD OF TOH GUAN RD INTO P.I.E.

Dear Sirs,

Attach our estimate bill, GIA third party insurer search fee, Client's GIA report, insurance certificate, log card & your insured driver forwards us his van insurance certificate (cover by yours) for your reference & attention,

Please assign your panel surveyor (LKK Auto Consultants Pte Ltd) to survey client's damaged vehicle on : 07/05/19 (at 13:30hrs to 15:30hrs) as owner waiting, Kindly revert & confirm the survey assignment,

PLease revert & confirm client's third party claims liability, reference & OIC, as we are looking for direct settlement, Please let us hear from yours,

Best Regards
David Ang

Tel : 6784 0039, Fax : 6784 0076, HP : 9815 4655

Mailing Address :

Hup Motor Trading & Service

Blk 9004 Tampines St 93

#01-120

Singapore 528838



Virus-free: www.avg.com

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

SUPREME

NEW CARS | PRE-LOVED CARS | INSURANCE |

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Renewal Coe Toyota Altis 1.6A



2.98%p.a \$0 Admin Fees@Gv
Finance. 2 Years
Warranty.\$1800 Down Monthly
From \$488
GV Credit Pte Ltd StarAd



Browse by Category ▼

« Back (1 2) Next »

Sort by Date Posted

27 vehicles

toyota liteace

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	toyota liteace		Any	Any	> 10 year(s) old	Any	Any	
		Toyota Liteace 2.2A (New 5-yr COE)	\$24,800	\$4,950 /yr	15-Sep-2004	2,184 cc	-	
		Fuel Type: Diesel						
		Posted: 07-May-2019	Tags: Toyota Townace, 2004 Toyota Liteace, 2004 toyota liteace, Toyota Liteace, toyota liteace, Toyota, Liteace, liteace, Used Toyota					
		Toyota Liteace 2.2A (New 5-yr COE)	\$22,800	\$4,560 /yr	28-Sep-2004	2,184 cc	-	
		Fuel Type: Diesel						
		Lowest In The Market. Welcome Car Trade In. Call Our Friendly Sales Team For More Info Today!						
		Posted: 06-May-2019	Tags: Toyota Townace, 2004 Toyota Liteace, 2004 toyota liteace, Toyota Liteace, toyota liteace, Toyota, Liteace, liteace, Used Toyota					
		Toyota Liteace 2.2A (COE till 02/2024)	\$26,800	\$5,620 /yr	13-Feb-2004	2,184 cc	-	
		Fuel Type: Diesel						
		Rare Auto Diesel Van. New Paint Work Excellent Condition. No Repairs Needed. Hurry And Book A Test Drive Now! Doorstep Viewing Ca Arranged.						
		Net Link Partners Pte Ltd						
		Posted: 06-May-2019	Tags: Toyota Townace, 2004 Toyota Liteace, 2004 toyota liteace, Toyota Liteace, toyota liteace, Toyota, Liteace, liteace, Used Toyota					
		Toyota Liteace 2.2M (COE till 03/2024)	\$22,800	\$4,650 /yr	20-Apr-2004	2,184 cc	-	
		Fuel Type: Diesel						
		Rocket Auto Trading. One Owner, Diesel, 5 Doors, No SMS Please, Thank You.						
		Posted: 06-May-2019	Tags: Toyota Townace, 2004 Toyota Liteace, 2004 toyota liteace, Toyota Liteace, toyota liteace, Toyota, Liteace, liteace, Used Toyota					

GET YOUR
COE
RENEWAL
LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town approval in 2 days without effort! Enquire today.

Compare

ta Liteace 2.2A (New 5-yr \$27,800 \$5,550 /yr 14-Jul-2004 2,184 cc -

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8500E
Vehicle Details	
Vehicle No.:	GY3086T
Vehicle to be Exported:	No
Intended Deregistration Date:	07 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	LITEACE 5DR
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	3C4008035
Chassis No.:	CR425011191
Maximum Power Output:	-
Open Market Value:	\$18,669.00
Original Registration Date:	02 Mar 2005
First Registration Date:	02 Mar 2005
Transfer Count:	2
Actual ARF Paid:	\$934.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Mar 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$27,286.00
COE Rebate Amount:	\$4,452.00
Total Rebate Amount:	\$4,452.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 07 May 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	GY3086T		
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	LITEACE 5DR		
Chassis No. :	CR425011191		
Propellant :	Diesel		
Engine No. :	3C4008035		
Engine Capacity :	2184 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	2230 kg		
Unladen Weight :	1280 kg		
Year Of Manufacture :	2004		
Original Registration Date :	02 Mar 2005		
Lifespan Expiry Date :	01 Mar 2025		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$27,286.00		
COE Expiry Date :	01 Mar 2020		
Road Tax Expiry Date :	01 Sep 2019		
Inspection Due Date :	01 Sep 2019		
Intended Transfer Date :	06 May 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.			

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/05/2019 16:33
Date Of Accident	03/05/2019 13:30
Exact Location Of Accident	FILTER RD OF TOH GUAN RD TOWARDS P.I.E
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY3086T
Insured/Policyholder	
Name Of Registered Owner	SAN HE CAR REPAIRER
Co Reg No	27868500E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96881971

Vehicle Particulars

Manufacturer	TOYOTA
Model	LITEACE-2.2 D (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	D18MCV0001265
Cover Note Number	

Driver

Name of Driver	KHAN RUBEL
Passport No/FIN	G7111439U
Date Of Birth	01/09/1978
Occupation	INDOOR
Date Of Driving Pass	09/09/2008
Driving Experience	10 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86276074
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address #07-02 SUNNY GROVE, 5A GEYLANG LOR 37
Postcode 387914
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured FRIEND
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1 NAME: : RAHMAN MOST TAFIZUR
GENDER: : MALE
Passenger 2 NAME: : RANA MD RASEL
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

KINDLY REFER TO SKETCH PLAN ATTACHED.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD2748T
Vehicle Make/Model/Colour TOYOTA / VAN
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver MR NEO
NRIC/Passport Number
Contact Number 97988781
Address
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B1 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


三合修理汽車
SAN HE CAR REPAIRER

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 3/5/19 AT 1330 HOURS I WAS DRIVING MY VAN
 ALONG FILTER R.D OF TOHGUAN R.D TO PIE
 SUDDENLY THE FRONT CAR (HONDA) BRAKE AND
 STOP I STOP MY VAN ALSO SUDDENLY CAR
 B GBD 2748T HIT ON TO MY VAN BEHIND

DECLARATION

I/We declare the foregoing particulars are true in every respect.

SAN HE CAR REPAIRER

Policyholder's Signature

Date & Time:

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



ACCIDENT REPORTING CENTRE
& AUTHORISED WORKSHOP:
HUP MOTOR TRADING & SERVICE
BLK 9004 TAMPINES STREET 93
#01-120 SINGAPORE 528838
TEL: 67840039 (24 hrs) HP: 98154655
Email: hupmotor@gmail.com

INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 198703792k | GST Reg. No. M2-0078806-X
64 | Cecil Street | #04 | #05 | #06-02 | IOB Building | Singapore 049711
Office (65) 63476100 Email: insure@iii.com.sg
Fax (65) 62244174 Website: www.iii.com.sg

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

All Accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

CERTIFICATE NO.: D18MCV0001265

COVER: Third Party Only

1. Index Mark and Registration Number of Vehicle : GY3086T
Chassis No : CR425011191
2. Name of Policyholder : SAN HE CAR REPAIRER
3. Effective date of Insurance : 02 Sep 2018
4. Expiry date of Insurance : 01 Sep 2019
5. Persons or Classes of Persons entitled to drive*
Any person who is driving on the Policyholder's order or with their permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to use*
 - a) Use in connection with the Policyholder's business.
 - b) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
 - c) Use for social, domestic and pleasure purposes.

The Policy does not cover

 - a) Use for hire or reward or for racing, pace-making, reliability trial, or speed-testing.
 - b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

FOR DRIVERS BELOW 21 YEARS OR ABOVE 65 YEARS OF AGE &/OR LESS THAN 2 YEARS SINGAPORE DRIVING LICENCE, AN EXCESS OF \$2500/- ON SECTION II WILL BE APPLICABLE.

I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Agent/Broker : A000038/M Plus Consultancy
Date of Issue : 14/08/2018 11:07:58
MZ300C (GOODS CARRYING)
COMPANY

For India International Insurance Pte Ltd

R. Ravindra Kumar
MD & CEO



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-069727
Date of Request: 03/05/2019

Your Ref No: Online Purchase

Hup Motor Trading & Service
Blk 9004 Tampines Street 93
#01-120
Singapore 528838

Dear Sir/Madam,

Enquiry Date 03/05/2019
Enquiry By David Ang Beng Yeow
TP Vehicle No. GBD2748T
Accident Date 03/05/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBD2748T	Sompo Insurance Singapore Pte. Ltd.	01/09/2018-31/08/2019	6461 6555

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-069727
Date of Request: 03/05/2019

Your Ref No: Online Purchase

Hup Motor Trading & Service
Blk 9004 Tampines Street 93
#01-120
Singapore 528838

Dear Sir/Madam,

Enquiry Date 03/05/2019
Enquiry By David Ang Beng Yeow
TP Vehicle No. GBD2748T
Accident Date 03/05/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No: 378091/00W

Our Ref: TP 2943/05/19

Your Ref:

Date: 6th MAY 2019

M/S SAN HE CAR REPAIRER
BLK 1018, #01-348
Yishun Industrial Park A,
Singapore 768760

Not Authorized
5/5/19
4000/
7/5/19
hybrid theory

Estimate cost of repair to TOYOTA LITEACE 2.2 (M) Van - GY 3086 T

1 pc tail gate door		<i>body m</i> \$ 1,298.70
1 pc tail gate door inner lock		<i>m/jm</i> 269.40
1 pc tail gate door lock stricker		11 51.20 X
1 pc tail gate door key lock		11 79.70 X
1 pc tail gate door 'TOYOTA' sticker		NF 29.70 X
1 pc tail gate door '70km/h' sticker		ml 15.00/05.2
1 pc tail gate door weatherstrip		ml 246.00
1 pc tail gate door licence lamp garnish		11 157.80 X
1 pc tail gate door inner trim board cover		11 197.40 X
16 pcs tail gate door inner trim board clips	@ \$ 4.50	11 72.00 X
1 set rear windscreen glass moulding		ml 119.70
1 pc rear windscreen glass inner damper seal		ml 45.00
1 pc rear windscreen glass sealant		ml 60.00 40 s.2
2 pcs tail gate door o/s & n/s side stopper	@ \$ 16.50	11 33.00 X
1 pc rear bumper		ml 397.40
2 pcs rear bumper o/s & n/s stay	@ \$ 111.90	11 223.80 X
2 pcs rear bumper o/s & n/s side bracket	@ \$ 27.50	ml 55.00
8 pcs rear bumper clips	@ \$ 4.20	ml 33.60
2 pcs rear bumper o/s & n/s side reflector	@ \$ 42.50	11 85.00 X
1 pc rear end panel (outer)		ml 416.70
1 pc rear floor board panel top garnish		11 89.40 X
1 pc rear spare tyre carrier		11 328.00 X
1 pc rear exhaust pipe		11 482.80 X
1 pc rear exhaust muffler mounting		11 28.85 X

p-2881.5
2161.12

Less 25%

\$ 4,815.15

\$ 1,203.79

\$ 3,611.36

1 set rear bumper reverse sensor
1 set rear bumper reverse camera

slip 200.00 S.N
Daye 580.00 S.N 380

To wiring check up & transfer affected wiring system.

50.00 20

To remove & refix rear windscreen glass & necessary parts.

150.00 100

To transfer tail gate door inner trim board cover, hinge, shock absorber, wiper motor, third brake light, mirror, inner lock, garnish & necessary parts into new tail gate door.

120.00 60

To remove & refix rear carpet, floor mat, garnish, floor board cover, spare tyre, carrier & necessary parts.

11 120.00 X

\$ 4,831.36

Balance C/F.....

p-3166.5
2374.87

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2943/05/19 Your Ref: _____ Date: 6th MAY 2019

M/S SAN HE CAR REPAIRER.,

Balance B/F.... \$ 4,831.36

To jack, straighten & knocking out rear exhaust, muffler, tail pipe & necessary parts.

11 150.00 X

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel, rear inner end panel, rear side corner panel & necessary parts, to weld, renew & align above parts.

1,800.00 800

To respray Tuff-Kote on all affected accident parts.

150.00 60

To putty & respray painting on all affected accident parts,

1,800.00 980


\$ 8,731.36

=====

Dollars : Eight Thousand Seven Hundred Thirty One And Cents Thirty Six Only.

102487

HUP MOTOR TRADING & SERVICE



8945.11

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2943/05/19 Your Ref: _____ Date: 15th MAY 2019

M/S SAN HE CAR REPAIRER
BLK 1018, #01-348
YISHUN IND. PARK A,
SINGAPORE 768760


SUPPLEMENTARY BILL For TOYOTA LITEACE Van - GY 3086 T

1 pc tail gate door lock Actuator

Original \$ 285.00
Less 25% \$ 71.25
\$ 213.75
=====

Dollars : Two Hundred Thirteen And Cents Seventy Five Only.

HUP MOTOR TRADING & SERVICE


.....

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19007873/UQD3N2

Date: 16/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE003178
Claimant Vehicle No :	GY3086T	Insured Vehicle No :	GBD2748T
Date of Loss:	03/05/2019	Nature of Claim:	TP
		Claim No:	CMTD1902163

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GY3086T	Engine No:	3C4008035
Make & Model:	TOYOTA LITEACE, 2.2 D (M)	Chassis No:	CR425011191
Reg. Date:	02/03/2005 (Man. Year: 2004)	Odometer:	266610 km
Colour:	Silver		
Engine Capacity:	2184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165 R13	Rear Tyre Size:	165 R13
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,605.11	3,004.87	1,600.24	34.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,340.00	2,020.00	2,320.00	53.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,945.11	5,024.87	3,920.24	43.83
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	8,945.11	4,000.00	4,945.11	55.28

INSPECTION

Date of Assignment:	06/05/2019	
Date Inspected:	07/05/2019	Inspected At:
		Hup Motor Trading & Service (HQ)
		Blk 9004 Tampines Street 93, #01-120
		Singapore 528838
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 May 2019)	
Parts:	N/A	TOYOTA LITEACE 2.2 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GY3086T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE DOOR	Badly Dented	1,298.70 FL	*1,298.70 FL
2	1		*TAIL GATE DOOR INNER LOCK	Dented/Jammed	269.40 FL	*269.40 FL
3	1		*TAIL GATE DOOR LOCK STRICKER	Not Necessary	51.20 FL	*- FL
4	1		*TAIL GATE DOOR KEY LOCK	Not Necessary	79.70 FL	*- FL
5	1		*TAIL GATE DOOR TOYOTA STICKER	Not fitted	29.70 FL	*- FL
6	1		*TAIL GATE DOOR WEATHERSTRIP	Twisted	246.00 FL	*246.00 FL
7	1		*TAIL GATE DOOR LICENCE LAMP GARNISH	Not Necessary	157.80 FL	*- FL
8	1		*TAIL GATE DOOR INNER TRIM BOARD COVER	Not Necessary	197.40 FL	*- FL
9	16		*TAIL GATE DOOR INNER TRIM BOARD CLIPS	Not Necessary	72.00 FL	*- FL
10	1		*SET REAR WINDSCREEN GLASS MOULDING	Necessary	119.70 FL	*119.70 FL
11	1		*REAR WINDSCREEN GLASS INNER DAMPER SEAL	Necessary	45.00 FL	*45.00 FL
12	2		*TAIL GATE DOOR O/S & N/S SIDE STOPPER	Not Necessary	33.00 FL	*- FL
13	1		*REAR BUMPER	Deformed	397.40 FL	*397.40 FL
14	2		*REAR BUMPER O/S & N/S STAY	Not Necessary	223.80 FL	*- FL
15	2		*REAR BUMPER O/S & N/S SIDE BRACKET	Necessary	55.00 FL	*55.00 FL
16	8		*REAR BUMPER CLIPS	Necessary	33.60 FL	*33.60 FL
17	2		*REAR BUMPER O/S & N/S SIDE REFLECTOR	Not Necessary	85.00 FL	*- FL
18	1		*REAR END PANEL (OUTER)	Dented	416.70 FL	*416.70 FL
19	1		*REAR FLOOR BOARD PANEL TOP GARNISH	Not Necessary	89.40 FL	*- FL
20	1		*REAR SPARE TYRE CARRIER	Not Necessary	328.00 FL	*- FL
21	1		*REAR EXHAUST PIPE	Not Necessary	482.80 FL	*- FL
22	1		*REAR EXHAUST MUFFLER MOUNTING	Not Necessary	28.85 FL	*- FL
23	1		*TAIL GATE DOOR 70KM/H STICKER	Necessary	11.25 FS	*10.00 FS
24	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	45.00 FS	*40.00 FS
25	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
26	1		*SET REAR BUMPER REVERSE CAMERA	Damaged	580.00 FS	*380.00 FS
27	1		*TAIL GATE DOOR LOCK ACTUATOR	Damaged/Jammed	285.00 FL	*285.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,861.40	3,796.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,256.29	791.63
Total Parts (\$\$)	4,605.11	3,004.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP & TRANSFER AFFECTED WIRING SYSTEM	New	50.00	20.00
2	TO REMOVE & REFIX REAR WINDSCREEN GLASS & NECESSARY PARTS	New	150.00	100.00
3	TO TRANSFER TAIL GATE DOOR INNER TRIM BOARD COVER,HINGE,SHOCK ABSORBER,WIPER MOTOR,THIRD BRAKE LIGHT,MIRROR,INNER LOCK,GARNISH & NECESSARY PARTS INTO NEW TAIL GATE DOOR	New	120.00	60.00
4	TO REMOVE & REFIX REAR CARPET,FLOOR MAT,GARNISH,FLOOR BOARD COVER,SPARE TYRE,CARRIER & NECESSARY PARTS	New	120.00	0.00
5	TO JACK,STRAIGHTEN & KNOCKING OUT REAR EXHAUST,MUFFLER,TAIL PIPE & NECESSARY PARTS	New	150.00	0.00
6	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS,TO JACK,STRAIGHTEN & KNOCKING OUT REAR FLOOR BOARD PANEL,REAR INNER END PANEL,REAR SIDE CORNER PANEL & NECESSARY PARTS,TO WELD,RENEW & ALIGN ABOVE PARTS	New	1,800.00	800.00
7	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	150.00	60.00
8	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,800.00	980.00
Gross Labour Cost (S\$)			4,340.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >