

12/15/2012

ASS. REC. BY:

REF:

CITROPOCO7881/NC

Special Instruction:

SUPERVISOR

ASSIGNMENT (Office)

From (Person):

Kamalish Kamik

of

SPF

Date/Time:

2/4/2013

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU916SH

Insured:

at Workshop m/s

Tel:

of

Policy No:

MHASPF06000017235

Claim No:

TP/IP/64555/2012

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7/12/2012

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SKU916SH-X

12/19

From: Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>
Sent: Monday, 29 April 2019 8:00 AM
To: Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; sherwinbeh@lkkauto.com
Cc: SPF-TP FAIT <SPF-TP_FAIT@spf.gov.sg>; Chin Yong TAN (SPF) <TAN_Chin_Yong@spf.gov.sg>; Beifeng NG (SPF) <NG_Beifeng@spf.gov.sg>
Subject: Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **43 vehicles** below:

a) Case IAFP-IB-20190405 - Mechanical Inspection of Mini Bus, PC1978S (TP/IP/54999/2018)

On 26 September 2018 at about 5.45 p.m., it was revealed that the Accused was driving his mini bus and was travelling along the bus lane along Woodlands Avenue 3 towards Woodlands Avenue 5 when he colliding onto the Deceased, who was crossing at the signalised pedestrian crossing. As a result of the accident, the Deceased was conveyed in a critical condition to Khoo Teck Puat Hospital. On the same day, the Deceased succumbed to his injuries and was pronounced dead in hospital at 6.31 p.m., by the Dr Ashley Yuen.

Vehicles to be inspected: PC1978S (Potential Defendant)

IO In-Charge: SIO Clarence Lim

b) Case IAFP-IB-20190405 - Mechanical Inspection of Motor Car, SKU9165H (TP/IP/67555/2018)

On 7 December 2018 at about 8.30 p.m., the Involved Party was driving his motorcar, SKU 9165 H and was overtaking a stationary bus on the left of the 2 lanes of Petir Road towards Upper Bukit Road and was travelling behind the Witness on the right lane. After passing the stationary bus, the Involved Party was switching back to the left lane when he collided onto the Deceased, who was crossing from his right to left, ahead of the Witness. Due to the collision, the Deceased landed on the right lane, ahead of the Witness's motor car. The Deceased was reported to be unconscious and was conveyed to the National University Hospital however, the Deceased succumbed to his injuries and was pronounced dead at 10.04 p.m. by Dr Shao Hong in hospital.

Vehicles to be inspected: SKU9165H (Potential Defendant)

IO In-Charge: SIO Clarence Lim

c) Case IAFP-IB-20190405 - Mechanical Inspection of Motor Car, SKB3467B (TP/IP/02679/2019)

On 17 January 2019 at about 7.08 a.m., based on the video footage retrieved from FIR caller, the Involved Party was driving his motorcar, SKB 3467 B and was travelling along the right bend of Choa Chu Kang Way towards Sungel Kadut Drive, before Choa Chu Kang North 5, on lane 1 of the 3-lanes. At this juncture, the Deceased was seen running from the Involved Party's right side to left side. At the same time, the Involved Party was seen making a lane changed from lane 1 to lane 2 and subsequently made an abrupt lane changed back to lane 1. From the video footage, it is unable to ascertain if the Deceased did walk backwards to the centre divider. As a result of the accident, the Deceased was bleeding from his mouth and he sustained head injury thus he was conveyed by an ambulance in an unconscious state to Ng Teng Fong General Hospital. However, on the same