

2/20/2019

REF: CS/CTI19007901/ET d3 12

Special Instruction:

ASS. REC. BY:

SA/VEH/PT: Steve

ASSIGNMENT (Office)

From (Person):

Glainecheong of CTI

Date/Time: 8/5/2019 @ 2.01pm

Estimated Cost:

Bill to:

OD / P / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKL 9661P

Insured:

GBE 55152

at Workshop n/a

Tunsean fars

Tel:

63310683

of

27 A Tanyong Perjam.

Policy No: DMCVSN3002811900

Claim No:

SNM19D261890C02

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A 25/04/2019

7/5/19 @ 3pm-3.30pm.

H.O.D. Endorsement

CA / REV / REP. / REV 24 HRS

lupl

Date/Time:

2.38pm @ 6/5/19

Person Contacted:

eva

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SKL 9661P-X
	GBE 55152 - CC3/EQ117022222/K1h3y2 20/11/17
	Confirm COR \$21,138.95. 6days before GST.
	cked:

Surveyor

Steve

REF: CFF

ASSIGNMENT

From:
Estimated Cost:

Date: 8/5/2019

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKL 9661 P

at Workshop m/s

Trans Euro Cars
27A Tunjong Penjung

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

1000m

EVN

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lump Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

sup

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SKL 9661P
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Yr Regn: 12/2/18

Truck / Trailer or

Make: Porsche Macan

c.c 1984

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 14924

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WP122295 ZJL 805919

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Breke: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 265/45 R20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 25/4/19

D.O.I. 8/5/19

Survey held at

Trans Euro Cars

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11V-250K

Date/Time, File Pass to?

☐

: Preli. Report

☒

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$

21,138.95

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

) Photos

) Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2019		06 May 2019 14:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	REN XIAORONG, ID: S7289839G
Vehicle Reg. No.:	SKL9661P
Claim Type:	TP / SNM19D201890C02
Vehicle Reg. No. (Insured):	GBE5515Z
Date of Loss:	25/04/2019 07:00 - :59
Policy/Cover Note No.:	DMCVSN3002811900
Policy No. (Claimant):	10893449
Excess:	S\$2,000.00
Repairer:	Stuttgart Auto Pte Ltd (HQ) 27A Tanjong Penjuru, 609042 Sungei Kadut - Tel: 6331 0680 / 6331 0686 (DID)
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2019]

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 18 September 2019 5:02 PM
To: jessicahs@eurokars.com.sg; SUR; Admin A
Cc: janice.syn@porsche.com.sg; eva.kok@eurokars.com.sg; rickteo@eurokars.com.sg; stephanie.loke@eurokars.com.sg
Subject: RE: FINALIZATION CTI TP - SKL9661P.xlsx

Dear Jessica,

Confirm COR: \$21,138.95, 6 days. Before GST

Please submit relevant documents to China Taiping directly.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Wednesday, 18 September 2019 2:10 PM
To: jessicahs@eurokars.com.sg; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: janice.syn@porsche.com.sg; eva.kok@eurokars.com.sg; rickteo@eurokars.com.sg; stephanie.loke@eurokars.com.sg
Subject: RE: FINALIZATION CTI TP - SKL9661P.xlsx

Dear Jessica,

Will sent you the confirmation shortly.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg <jessicahs@eurokars.com.sg>
Sent: Wednesday, 18 September 2019 2:03 PM
To: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: janice.syn@porsche.com.sg; eva.kok@eurokars.com.sg; rickteo@eurokars.com.sg; stephanie.loke@eurokars.com.sg
Subject: RE: FINALIZATION CTI TP - SKL9661P.xlsx

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Monday, 6 May 2019 2:03 PM
To: eva.kok@eurokars.com.sg; 'assignments'
Subject: FW: TP CLAIMS- SKL9661P & GBE5515Z DOA 25/4/2019 (CLAIM REF: SNM19D201890C02/5)
Attachments: AMENDED GIA REPORT-SKL9661P.PDF; WhatsApp Video 2019-04-26 at 09.09.14.mp4; ESTIMATE- SKL9661P.pdf

WITHOUT PREJUDICE

Dear Eva,

We refer to your email of 03.05.19.

Our insured have yet to report the accident to us.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please refer email below and proceed to survey the third party vehicle.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Claims Dept of CTI
Sent: Friday, 3 May, 2019 8:49 AM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Cc: Angie Foo <angie.foo@sg.cntaiping.com>
Subject: FW: TP CLAIMS- SKL9661P & GBE5515Z DOA 25/4/2019

From: eva.kok@eurokars.com.sg [mailto:eva.kok@eurokars.com.sg]
Sent: Friday, 3 May 2019 8:39 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: janice.syn@porsche.com.sg; rickteo@eurokars.com.sg; jobithomas@eurokars.com.sg
Subject: FW: TP CLAIMS- SKL9661P & GBE5515Z DOA 25/4/2019

RESEND

YOUR REF: GBE5515Z / OUR REF: SKL9661P THIRD PARTY CLAIM

Dear Sir/Mdm,

Kindly arrange the survey of our client's car.

Attached is the ESTIMATE & ACCIDENT REPORT for your perusal.

We would appreciate it if you can kindly let us know the liability/status of this case.

Regards,



Eva Kok

Insurance Claims Officer

27A Tanjong Penjuru

Singapore 609042

T: (65) 6331 0680 D: (65) 6331 0683 F: (65) 6331 0690

E: eva.kok@eurokars.com.sg W: www.eurokarsgroup.com

From: Eva Kok

Sent: 30 April 2019 1:00 PM

To: 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>

Cc: Janice Syn <janice.syn@porsche.com.sg>; Rick Teo <rickteo@eurokars.com.sg>; Jobi Thomas <jobithomas@eurokars.com.sg>

Subject: TP CLAIMS- SKL9661P & GBE5515Z DOA 25/4/2019

YOUR REF: GBE5515Z / OUR REF: SKL9661P THIRD PARTY CLAIM

Dear Sir/Mdm,

Kindly arrange the survey of our client's car.

Attached is the ESTIMATE & ACCIDENT REPORT for your perusal.

We would appreciate it if you can kindly let us know the liability/status of this case.

Regards,



Eva Kok

Insurance Claims Officer

27A Tanjong Penjuru

Singapore 609042

T: (65) 6331 0680 D: (65) 6331 0683 F: (65) 6331 0690

E: eva.kok@eurokars.com.sg W: www.eurokarsgroup.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/04/2019 00:41
Date Of Accident	25/04/2019 07:50
Exact Location Of Accident	MSCP OF 238 ORCHARD BOULEVARD ORCHARD RESIDENCE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL9661P
Insured/Policyholder	
Name Of Registered Owner	REN XIAORONG
NRIC No	S7289839G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84908779
Alternative Phone No	OFFICE-84908779

Vehicle Particulars

Manufacturer	PORSCHE
Model	MACAN PDK CYP E6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10893449
Cover Note Number	

Driver

Name of Driver	POWELL TIMOTHY MARTIN
NRIC No	S7289840J
Date Of Birth	18/05/1972
Occupation	INDOOR
Date Of Driving Pass	04/11/2016
Driving Experience	2 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	+65-84908779
Fax Number	
Contact Number	
Email Address	TIMOTHYPOWELL@HITMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT NO T/20190425/7019 LODGE AT 10 Ubi Avenue 3 MY VEHICLE WAS HIT WHEN PARKED, UNATTENDED, AT LEVEL 6, LOT 34, BY A REVERSING VEHICLE; VEHICLE B. CASE OF HIT AND RUN. THIS INCIDENT WAS CAPTURED BY A SECURITY VIDEO. THIS WAS IN THE CAR PARK OF MY CONDO 'THE ORCHARD RESIDENCES. I HAVE PICTURES AND VIDEO EXCEEDING 2MB

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UPLOADED INTO FILE ZILLA
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE5515Z
Vehicle Make/Model/Colour	NISSAN NV350 PANEL VAN 2.5 5AT 5DR EURO V SILVER
Details Of Properties	HIT AND RUN
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NA
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
Hashim Kamari

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 9839G

Vehicle Details

Vehicle No.: SKL9661P
Vehicle to be Exported: No
Intended Deregistration Date: 08 May 2019
Vehicle Make: PORSCHE
Vehicle Model: MACAN PDK CYP E6
Primary Colour: Grey
Manufacturing Year: 2017
Engine No.: 094834
Chassis No.: WP1ZZZ95ZJLB05019
Maximum Power Output: 185.0 kW (248 bhp)
Open Market Value: \$63,494.00
Original Registration Date: 12 Feb 2018
First Registration Date: 12 Feb 2018
Transfer Count: 0
Actual ARF Paid: \$86,290.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 11 Feb 2028
PARF Rebate Amount: \$64,717.00

Intended COE Rebate Details

COE Expiry Date: 11 Feb 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$45,289.00
COE Rebate Amount: \$39,666.00
Total Rebate Amount: \$104,383.00

The information contained herein is correct as at 08 May 2019

OK

PORSCHE

China Taiping Insurance (S) Pte Ltd 3 Anson Rd, #16-00 Springleaf Tower, Singapore 079909		NAME : Ms Ren Xiaorong ADDRESS : 238 Orchard Boulevard #21-07 Singapore 237973 TEL :		WIP : 45298 EXCESS : DATE: 30.04.2019	
ATTN. : MOTOR CLAIMS FAX :					
VEH NO :	SKL9661P	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP1ZZZ95ZJLB05019	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Macan	DATE REG.:	12.02.2018	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
	QTY				
1	FRONT BUMPER (SPORT DESIGN) <i>DD</i>	1	P95B-807-221-H -G2X	<i>4353</i> ✓	\$ 3,970.50
2	FRONT BUMPER GRILLE SUPPORT LH <i>cut ? / BR</i>	1	P95B-807-681-B -G2X	✓	\$ 768.00
3	BUMPER GRILLE SUPPORT COVER LH <i>cut ? / BR</i>	1	P95B-121-333-A -1E0	✓	\$ 144.20
4	FRONT BUMPER SIDE TRIM COVER LH <i>cut</i>	1	P95B-807-819-A -G2X	✓	\$ 731.20
5	FRONT BUMPER SIDE TRIM GARNISH <i>X / BRNN</i>	1	P95B-807-685-A -G2X	<i>X</i>	\$ 365.60
6	EXPANSION RIVET <i>ALC</i>	6	PN -038-501-3 -	✓	\$ 9.00
7	BRACKET, CHARGE AIR COOLER <i>? / BR</i>	1	P95B-805-295-C -	✓	\$ 225.00
8	BUMPER GUIDE <i>? / BR</i>	1	P95B-807-889-C -	✓	\$ 77.40
9	BONNET <i>DD</i>	1	P95B-823-031-KY-GRV	✓	\$ 3,057.90
10	P000-043-305-51-/CAVITY PRESERVATION (AK <i>X nn</i>)	1	P000-043-210-97-	<i>X</i>	\$ 75.30
11	HOOD BADGE NUT <i>ALC</i>	2	PWHT-004-974- -	✓	\$ 3.00
12	BONNET SOUND ABSORBER <i>X nn</i>	1	P95B-863-831-C -	<i>X</i>	\$ 229.90
13	BONNET SEAL <i>ALC</i>	2	P95B-823-739- -	✓	\$ 14.80
14	HEADLAMP TRIM COVER <i>? / BR</i>	1	P95B-807-173-C -1E0	✓	\$ 53.80
15	EXPANSION RIVET <i>ALC</i>	1	PWHT-004-750- -	✓	\$ 2.20
16	LED HEADLAMP <i>cut</i>	1	P95B-941-039-G -	✓	\$ 5,098.70
17	ADDITIONAL HEADLAMP <i>cut</i>	1	P95B-941-181-A -	✓	\$ 348.30
18	P000-043-301-47-/ANTIFREEZE PROTECTION <i>WAB ? / ALC</i>	6	P000-043-305-15-	✓	\$ 190.20
TOTAL PARTS					\$ 15,365.00
LESS 10%					\$ 1,536.50
TOTAL PARTS COST					\$ 13,828.50
Labour Description					
1	TO REPLACE BONNET, FRONT BUMPER, CHARGE AIR COOLER BRACKET & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. <i>1560 x 2</i>				\$ 6,240.00
2	TO RESPRAY BONNET, FRONT BUMPER <i>1300</i>				\$ 3,500.00
3	TO SUPPLY 1 PC CHASSIS STICKER				NETT \$ 150.00
4	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.				\$ 500.00

5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	\$ 200.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$ 600.00
7	SUNDRIES. <i>NEL</i>	NETT	\$ 50.00
TOTAL LABOUR		\$ -	\$ 11,240.00
TOTAL PARTS		\$ -	\$ 13,828.50
TOTAL		\$ -	\$ 25,068.50
LESS EXCESS		\$ -	\$ -
TOTAL AFTER EXCESS		\$ -	\$ -
GST 7%		\$ -	\$ -
GRAND TOTAL		\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

[Signature]
9/5/19

Steve (LKK)
83228813

WIL Prejudice 8/5/19, 10.30am
P/P
Resurvey before spray
5 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



PORSCHE

China Taiping Insurance (S) Pte Ltd 3 Anson Rd, #16-00 Springleaf Tower, Singapore 079909		NAME : Ms Ren Xiaorong ADDRESS : 238 Orchard Boulevard #21-07 Singapore 237973 TEL :		WIP : 45298 EXCESS : DATE: 30.04.2019	
ATTN. : MOTOR CLAIMS FAX :					
VEH NO :	SKL9661P	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP1ZZZ95ZJLB05019	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Macan	DATE REG.:	12.02.2018	POLICY NO. :	

NATURE OF WORKS

Parts Description					
S/NO	QTY			REVISED	PRICES
1	FRONT BUMPER (SPORT DESIGN)	1	P95B-044-801-20	\$ 4,853.00	\$ 3,970.50
2	FRONT BUMPER GRILLE SUPPORT LH	1	P95B-807-681-B -G2X	\$ 768.00	\$ 768.00
3	BUMPER GRILLE SUPPORT COVER LH	1	P95B-121-333-A -1E0	\$ 144.20	\$ 144.20
4	FRONT BUMPER SIDE TRIM COVER LH	1	P95B-807-819-A -G2X	\$ 731.22	\$ 731.20
5	FRONT BUMPER SIDE TRIM GARNISH	1	P95B-807-685-A -G2X	\$ -	\$ 365.60
6	EXPANSION RIVET	6	PN -038-501-3 -	\$ 9.00	\$ 9.00
7	BRACKET, CHARGE AIR COOLER	1	P95B-805-295-C -	\$ 225.00	\$ 225.00
8	BUMPER GUIDE	1	P95B-807-889-C -	\$ 77.40	\$ 77.40
9	BONNET	1	P95B-823-031-KY-GRV	\$ 3,057.90	\$ 3,057.90
10	P000-043-305-51-/CAVITY PRESERVATION (AK	1	P000-043-210-97-	\$ -	\$ 75.30
11	HOOD BADGE NUT	2	PWHT-004-974- -	\$ 3.00	\$ 3.00
12	BONNET SOUND ABSORBER	1	P95B-863-831-C -	\$ -	\$ 229.90
13	BONNET SEAL	2	P95B-823-739- -	\$ 14.80	\$ 14.80
14	HEADLAMP TRIM COVER	1	P95B-807-173-C -1E0	\$ 53.80	\$ 53.80
15	EXPANSION RIVET	1	PWHT-004-750- -	\$ 2.20	\$ 2.20
16	LED HEADLAMP	1	P95B-941-039-G -	\$ 5,098.70	\$ 5,098.70
17	ADDITIONAL HEADLAMP	1	P95B-941-181-A -	\$ 348.30	\$ 348.30
18	P000-043-301-47-/ANTIFREEZE PROTECTION	6	P000-043-305-15-	\$ 190.20	\$ 190.20
SUPPLEMENTARY PARTS					
1	HEADLAMP RETAINER PLATE (A) / BR	1	P95B-941-121-B	\$ 111.00	\$ 111.00
TOTAL PARTS				\$ 15,687.72	\$ 15,476.00
LESS 10%				\$ 1,568.77	\$ 1,547.60
TOTAL PARTS COST				\$ 14,118.95	\$ 13,928.40
Labour Description					
1	TO REPLACE BONNET, FRONT BUMPER, CHARGE AIR COOLER BRACKET & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 3,120.00	\$ 6,240.00
2	TO RESPRAY BONNET, FRONT BUMPER			\$ 2,400.00	\$ 3,500.00
3	TO SUPPLY 1 PC CHASSIS STICKER			\$ 150.00	\$ 150.00
4	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.			\$ 500.00	\$ 500.00

5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 200.00	\$ 200.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 600.00	\$ 600.00
7	SUNDRIES.	\$ 50.00	\$ 50.00
TOTAL LABOUR		\$ 7,020.00	\$ 11,240.00
TOTAL PARTS		\$ 14,118.95	\$ 13,928.40
TOTAL		\$ 21,138.95	\$ 25,168.40
LESS EXCESS		\$ -	\$ -
TOTAL AFTER EXCESS		\$ 21,138.95	
GST 7%		\$ 1,479.73	\$ -
GRAND TOTAL		\$ 22,618.67	\$ -

Number of days: 6 working days(Exclude waiting for survey,authorization,parts,sat,sun & PH)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19007901/ETD3N2

Date: 25/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3002811900
Claimant Vehicle No:	SKL9661P	Insured Vehicle No:	GBE5515Z
Date of Loss:	25/04/2019	Nature of Claim:	TP
		Claim No:	SNM19D201890C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL9661P	Engine No:	094834
Make & Model:	PORSCHE MACAN, 2.0 PDK CYP E6 (A)	Chassis No:	WP1ZZZ95ZJLB05019
Reg. Date:	12/02/2018 (Man. Year: 2017)	Odometer:	14924 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/45R20	Rear Tyre Size:	265/45R20
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,772.67	14,168.95	603.72	4.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,190.00	6,970.00	4,220.00	37.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,962.67	21,138.95	4,823.72	18.58
+ GST 7.00/7.00% (S\$)	1,817.39	1,479.73	337.66	18.58
Nett Amount (S\$)	27,780.06	22,618.68	5,161.38	18.58

INSPECTION

Date of Assignment:	06/05/2019	Inspected At:	Stuttgart Auto Pte Ltd (HQ) 27A Tanjong Penjuru Singapore 609042
Date Inspected:	08/05/2019		

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2019)	
Parts: M1-SUV	PORSCHE MACAN 2.0 PDK CYP E6 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKL9661P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER (SPORT DESIGN)	Dented	4,853.00 FL	*4,853.00 FL
2	1	*FRONT BUMPER GRILLE SUPPORT LH	Broken	768.00 FL	*768.00 FL
3	1	*BUMPER GRILLE SUPPORT COVER LH	Broken	144.20 FL	*144.20 FL
4	1	*FRONT BUMPER SIDE TRIM COVER LH	Cut	731.22 FL	*731.22 FL
5	1	*FRONT BUMPER SIDE TRIM GARNISH	Not Necessary	365.60 FL	*- FL
6	6	*EXPANSION RIVET	Necessary	9.00 FL	*9.00 FL
7	1	*BRACKET,CHARGE AIR COOLER	Broken	225.00 FL	*225.00 FL
8	1	*BUMPER GUIDE	Broken	77.40 FL	*77.40 FL
9	1	*BONNET	Dented	3,057.90 FL	*3,057.90 FL
10	1	*P000-043-305-51/CAVITY PRESERVATION (AK)	Not Necessary	75.30 FL	*- FL
11	2	*HOOD BADGE NUT	Necessary	3.00 FL	*3.00 FL
12	1	*BONNET SOUND ABSORBER	Not Necessary	229.90 FL	*- FL
13	2	*BONNET SEAL	Necessary	14.80 FL	*14.80 FL
14	1	*HEADLAMP TRIM COVER	Broken	53.80 FL	*53.80 FL
15	1	*EXPANSION RIVET	Necessary	2.20 FL	*2.20 FL
16	1	*LED HEADLAMP	Cut	5,098.70 FL	*5,098.70 FL
17	1	*ADDITIONAL HEADLAMP	Cut	348.30 FL	*348.30 FL
18	6	*P000-043-301-47/ANTIFREEZE PROTECTION	Necessary	190.20 FL	*190.20 FL
19	1	*HEADLAMP RETAINER PLATE	Broken	111.00 FL	*111.00 FL
20	1	*SUNDRIES	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,408.52	15,737.72
- List Item Discount on L Items 10.00/10.00% (S\$)	1,635.85	1,568.77
Total Parts (S\$)	14,772.67	14,168.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE BONNET,FRONT BUMPER,CHARGE AIR COOLER BRACKET & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	6,240.00	3,120.00
2	TO RESPRAY BONNET,FRONT BUMPER	New	3,500.00	2,400.00
3	TO SUPPLY 1 PC CHASSIS STICKER	New	150.00	150.00
4	TO TOP-UP GAS,CONDUCT PRESSURE TEST & PERFORM LEAK TEAT ON THE COOLING SYSTEM	New	500.00	500.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	200.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	600.00	600.00
Gross Labour Cost (S\$)			11,190.00	6,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >