

INSURANCE

INS. CASE OWNER

CC 4 / AIG1900 7441

12/05/19

LKK
IDAC

Surveyor: tanfikh.

DOI: ASSIGNMENT
14/6/19.

Date / Time: 6/5/19.

Registered in Merimen: 6/6/19.

Pre-assign / CCU / FTE



Insured Vehicle No.: SLA 84349
Name of Insured: LIHUA HOE THIMIN EWIS
Insured Tel No.: _____ HP: 9/5/19.
Excess Sec II : \$5 _____ D.O.A: 9/5/19.
Is driver the owner? (YES / NO) _____ Nature of Accident: _____
If NO. Driver Name / Age: LIHUA HOE THIMIN EWIS, 28 years old
Driver Tel No.: _____ (V/L: YES / NO) _____

Claim No.: 163452479259
Policy No.: 1800115486
Make / Model: HYUNDAI
Place of Accident: 147 TAMPINES AVE 5 UPEN
SPRINT LP
OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Insured Liability: % Final ? Yes / No



INSRS: _____
WSP: Guan motor
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/Time		STAGE	DATE / PIC
	<u>16-03-20</u>	Non-Reporting (1st)	
	<u>26-03-20</u>	Non-Reporting (2nd)	
	<u>31-03-20</u>	Non-Reporting (Final)	
		Notification (if non-pickup)	
		Call Of:	
		After call (r to OI:	
		Documentation Check List: Handler Typist	
		Notification (if non-pickup)	
		After call (r to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GLA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

Reject Case
By: Shen
Approved by: Vin
Date: 31-03-20

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: \$5 _____ (days) Reduction: % _____ Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email ☐ Call ☐

Final Liability: % 0 (Agreed / Assessed) BOLA S/N No.: 24
Repair Cost: \$5 _____
Loss of Rental (LOR): \$5 _____ (days)
Loss of Use (LOU): \$5 _____ (5 x days)
Loss of Income (LOI): \$5 _____ (5 x days)
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐ [Tick only one]
GLA/LTA Search: \$5 _____
Medical: \$5 _____
Disbursement: \$5 _____ (e.g. Tow/Independent)
Legal Cost: \$5 _____

Total: \$5 _____ Global Sum \$5: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email ☐ Call ☐

Payee 1: \$5 _____ Name 1: _____
Payee 2: (Strike if N.A.) \$5 _____ Name 2: _____
Payee 3: (Strike if N.A.) \$5 _____ Name 3: _____

COPY SENT
11/6/2020

ASS. REC. BY:

REF: CS/AIG19007941/11

Special Instruction:

SA/VOL/

ASSIGNMENT (Office)

From (Person):

Murmen Hor Yinnai

of AIG

Date/Time: 6/5/19 @ 4:14pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX7603E

Insured:

SLA 8434G

at Workshop n/s

Queen Motor

Tel:

6453 6111

of

17G Pin Ming Drive # 02-03

Policy No:

1800115486

Claim No:

163452579366

Sum Insured:

Excess:

Make of Veh:

D.O.A

2/5/19

(Client's Record)

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement

Date/Time:

4:55pm @ 6/5/19

Person Contacted:

Ah Heng

Vehicle IN/OUT

(OIT)

Date/Time

Action/Instruction (✓) Estimate

GX7603E - NA/AIG19007805/21

D.O.A. 2/5/19

SLA 8434G - NA/AIG19007805/21

D.O.A. 2/5/19

16/5 10am

Spoken to Ah Heng, he wants to do DE for this case.

源摩哆廠

GUAN MOTOR WORKS

Business Regn No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 M/P: 9742 6003

REPAIR ESTIMATE FOR GX7603E

No.	Qty	List Items		
1	1	Front bumper	\$	650.80 <i>at</i>
2	1	Front bumper LH side retainer	\$	91.70 <i>ht</i>
3	1	Front LH step garnish	\$	384.30 <i>de</i>
4	1	Front LH step panel	\$	523.00 <i>at</i>
5	1	Front LH door pillar	\$	1,721.30 <i>Ry</i>
6	1	Front LH door	\$	1,228.10 <i>bt</i>
7	1	Front LH door rubber	\$	134.40 <i>ne</i>
8	2	Front LH door hinge (Top & bottom)	\$	138.20 <i>bt</i>
			\$	4,871.80
		Less 10%	\$	487.18
		Total :	\$	4,384.62

Special Nett Items

9	1	Front LH door company sticker	\$	30.00 <i>ne</i>
---	---	-------------------------------	----	-----------------

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	800.00 <i>600</i>
2	To putty and spray Spray Paintings charges.	\$	600.00 <i>500</i>
3	To conduct computerise wheel alignment test.	\$	80.00 <i>60</i>
4	To supply and apply anti rust treatment	\$	80.00 <i>30</i>
	Total :	\$	1,560.00

Total Parts and Labour : \$ 5,974.62

Tanfik 97493749 / 67418434
WP

Lump sum
Resurvey after repair
sure/khanfoun
#days
14/5/19 22pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5773E
Vehicle Details	
Vehicle No.:	GX7603E
Vehicle to be Exported:	No
Intended Deregistration Date:	15 May 2019
Vehicle Make:	NISSAN
Vehicle Model:	URVAN
Primary Colour:	Silver
Secondary Colour:	Grey
Manufacturing Year:	2004
Engine No.:	ZD30043548
Chassis No.:	JN1MG4E25Z0711739
Maximum Power Output:	-
Open Market Value:	\$22,223.00
Original Registration Date:	09 Sep 2004
First Registration Date:	09 Sep 2004
Transfer Count:	3
Actual ARF Paid:	\$1,112.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$21,466.00
COE Rebate Amount:	\$1,257.00
Total Rebate Amount:	\$1,257.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 15 May 2019

OK

Your password will expire in 6 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION REQUEST – GX7603E vs SLA8434G (OI) on D.O.A.: 02/05/2019

From: Hor, Yinnul
To: 'assignments@kkauto.com', Admin A (admin-a@kkauto.com)
Cc: Fang, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kasim, Noor Marissa, Adish, Syazairina, Chan, Yaka Shi, Lim, Sheng Yang, Mithocengh, Aashweejethkaur
Sent: 05/2019 4:14:14 PM

Hi,

Please refer to the enclosed request from **Hin Tat Augustine & Partners**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks & Regards,

Yin Rui, Hor (Viviane)
AIG
Claim Adjuster II (Singapore FNO), Claims Operations – Auto
Yinnul.Hor@aig.com | www.aig.sg

From: Ruby Ong (mailto:ruby@htapartners.com.sg)
Sent: Monday, May 06, 2019 4:03 PM
To: Hor, Yinnul
Subject: [EXTERNAL] RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GX 7603E [OUR REF: TCL.MH.RO.50303.19.gm] Your Ref: SLA 8434G
Importance: High

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

URGENT

Dear Sir

We refer to your email of even date.

Our client is agreeable to use **Mr Kenneth Kong (LKK Auto Consultants Pte Ltd)** from your list to conduct the joint pre-repair survey as a single joint expert for our clients' vehicle **GX 7603E**.

Please make the necessary arrangements with the contact person. The details are as follows :

Venue : Guan Motor Works
176 Sin Ming Drive
#02-03 Sin Ming Autocare
Singapore 575721

Contact Person : Mr Pang (HP. 9742 6002)

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Without Prejudice

Your Reference : TCL.MH.RO.50303.19.gm
Our Reference : SLA8434G

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kinh Keon (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd

Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Quang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Raul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rut, Hor (Vivian)
AIG
Claim Adjuster II, Singapore FNOI, Claims Operations – Auto
Yin.rut@aig.com | www.aig.sg

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Ruby Ong
Sent: Monday, May 06, 2019 1:44 PM
To: Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; darshene.supramaniam@aig.com; Hor, Yinrut <Yinrut.Hor@aig.com>
Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GX 7603E [OUR REF. TCLMH.RD.50303.19.gm]
Importance: High

Your ref: SLA 8434G
Our ref: TCLMH.RD.50303.19.gm

WITHOUT PREJUDICE

6 May 2019

AIG Asia Pacific Insurance Pte Ltd
Motor Claims Department
8 Shenton Way
#08-16 AIG Building
Singapore 068811

By Email Only

VERY URGENT

Dear Sirs,

CLAIMANT: LONG PANG LEASING
NOTICE OF ACCIDENT AND PRE-REPAIR SURVEY - ACCIDENT INVOLVING GX 7603E & SLA 8434G AT CARPARK LOT NO. 436B OF BLOCKS 146 & 147 TAMPINES AVENUE 5 ON 2 MAY 2019 @ 1305HRS

We are instructed by Long Pang Leasing to notify you of a road traffic accident on 2 May 2019 at about 1305hrs at carpark lot no. 436B of Blocks 147 & 147 Tampines Avenue 5 involving our client's vehicle registration number GX 7603E and vehicle registration number SLA 8434G driven by your insured's driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Asher Sng (LKKAuto)

From: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>
Sent: Thursday, 26 March 2020 5:10 PM
To: Asher Sng (LKKAuto)
Subject: RE: [MANDATE REQUEST] Your ref:1634525793SG , ACCIDENT INVOLVING SLA 8434G (OI) & GX 7603E (TP) ON 02/05/2019

Follow Up Flag: Follow up
Flag Status: Flagged

Dear Asher,

Please proceed to reject the TPPD claim.

Kind Regards,
Saliha

Saliha Syed Yusoff
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16, Singapore 079120
Tel +(65) 6419 1917 |
www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Lee, Ming-Yao
Sent: Wednesday, March 11, 2020 11:23 AM
To: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>
Subject: FW: [MANDATE REQUEST] Your ref: 6414897627SG, ACCIDENT INVOLVING SLA 8434G (OI) & GX 7603E (TP) ON 02/05/2019

Hi Saliha,

I think Asher was referring 1634525793SG.

She is seeking our mandate to reject claim. for your consideration please.

Regards,
Lee Ming Yao, George
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1769

Ming-Yao.Lee@AIG.com | www.aig.sg

From: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Sent: 09 March 2020 10:42
To: Lee, Ming-Yao <MingYao.Lee@aig.com>
Subject: [EXTERNAL] RE: [MANDATE REQUEST] Your ref: 6414897627SG, ACCIDENT INVOLVING SLA 8434G (OI) & GX 7603E (TP) ON 02/05/2019

This message is from an external sender; be cautious with links and attachments.

Hi George,

We refer to the email dated 16/10/2019.

Kindly let us have your approval / instruction if any.

Thank You.

Best Regards,
Asher Sng | Case Handler
LKK Auto Consultants Pte Ltd
phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4106
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asher Sng (LKKAuto)
Sent: Wednesday, 16 October 2019 5:02 PM
To: Lee, Ming-Yao <MingYao.Lee@aig.com>
Subject: [MANDATE REQUEST] Your ref: 6414897627SG, ACCIDENT INVOLVING SLA 8434G (OI) & GX 7603E (TP) ON 02/05/2019

Your ref: **6414897627SG**
Our Ref: CC4/AIG19011923/Keb3

Dear Sir/Madam,

ACCIDENT INVOLVING SLA 8434G (OI) & GX 7603E (TP) ON 02/05/2019

We refer to the above matter.

TP reported that reversed into the parking lot OI hit onto his vehicle.

OI reported that TP reversed into the parking lot swerved and hit his vehicle

Based on both party reported that third party reversed into the parking lot and collided.

We are of the opinion that the liability in not third party favour.

In view of the above, we are intending to reject TP claim under BOLA 24.

For your approval/ comments/ instruction.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Asher Sng (LKKAuto)

Subject: ACCIDENT INVOLVING GX 7603E AND SLA 8434G ON 02/05/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

ACCIDENT INVOLVING GX 7603E AND SLA 8434G ON 02/05/2019

We attached here with a copy of our insured's accident statement for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client reversed into the parking lot and collided with our insured vehicle.

We are of the opinion that liability is not in your client's favor.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)
Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2019 Edit Reg		06 May 2019 00:00 Edit Adj Rpt	\$43,200.00 Edit Estimates	\$43,200.00 View Rpt		Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

CHUA HOCK THIAM ELVIS, ID: S1602365E

Main Claimant:

LONG PANG LEASING, Co. Reg. No.: -

Vehicle Reg. No.:

GX7603E

Date of Loss:

02/05/2019 13:00 - :59
[175 Months and 23 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 1634525793SG

Policy/Cover Note No.:

1800115486 (Comprehensive)

Vehicle Reg. No. (Insured):

SLA8434G

Policy No. (Claimant):

D19MFL0001879

Excess:

Repairer:

Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare, 575721 Sin Ming - Tel: 64536111

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com

Claimant's Insurer:

India International Insurance Pte Ltd (HQ) - Tel: 63476100

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/05/2019]

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

AIG_SG (07/05/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GX7603E (1634525793SG)
[SLA8434G]
TP
LONG PANG LEASING
May 2 2019 1:15PM
[CHUA HOCK THIAM ELVIS]
Guan Motor Works

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Photos/Images														3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print	
1	26/09/19 14:38	Odometer Reading													Load JPG	☒	
2	26/09/19 14:38	Chassis Number													Load JPG	☒	
3	26/09/19 14:38	General View													Load JPG	☒	
4	26/09/19 14:38	General View													Load JPG	☒	
5	26/09/19 14:38	General View													Load JPG	☒	
6	26/09/19 14:38	General View													Load JPG	☒	
7	26/09/19 14:38	General View													Load JPG	☒	
8	26/09/19 14:38	General View													Load JPG	☒	
9	26/09/19 14:38	General View													Load JPG	☒	
10	26/09/19 14:38	General View													Load JPG	☒	
11	26/09/19 14:38	General View													Load JPG	☒	
12	26/09/19 14:38	General View													Load JPG	☒	
13	26/09/19 14:38	General View													Load JPG	☒	
14	26/09/19 14:38	General View													Load JPG	☒	
15	26/09/19 14:38	General View													Load JPG	☒	
16	26/09/19 14:38	General View													Load JPG	☒	
17	26/09/19 14:38	General View													Load JPG	☒	
18	26/09/19 14:38	General View													Load JPG	☒	
19	26/09/19 14:38	General View													Load JPG	☒	
20	26/09/19 14:38	General View													Load JPG	☒	
21	26/09/19 14:38	General View													Load JPG	☒	
22	26/09/19 14:38	General View													Load JPG	☒	
23	26/09/19 14:38	General View													Load JPG	☒	
24	26/09/19 14:38	General View													Load JPG	☒	
25	26/09/19 14:38	General View													Load JPG	☒	
26	26/09/19 14:38	General View													Load JPG	☒	
27	26/09/19 14:38	General View													Load JPG	☒	
28	26/09/19 14:38	General View													Load JPG	☒	
29	26/09/19 14:38	General View													Load JPG	☒	
30	26/09/19 14:38	General View													Load JPG	☒	
31	26/09/19 14:38	General View													Load JPG	☒	
Documentation														1 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print	
1	16/05/19 15:06	EMAIL FROM AIG DD 06052019													Load PDF		
2	16/05/19 15:06	TP GIA REPORT													Load PDF		
3	16/05/19 19:24	TP ESTIMATE- MARKED													Load PDF		
4	31/03/20 16:00	APPROVAL TO REJECT TP CLAIM													Load PDF		
5	31/03/20 16:00	FAX TO TP TO REJECT TP CLAIM													Load PDF		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print	
1	07/05/19 12:29	OI GIA REPORT													Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19007941/T1EA3Q2

Date: 06/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800115486
 Claimant Vehicle No : GX7603E Insured Vehicle No : SLA8434G
 Date of Loss: 02/05/2019 Nature of Claim: TP Claim No: 1634525793SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GX7603E
 Make & Model: NISSAN URVAN, 2.4 D (M) Engine No: ZD30043548
 Reg. Date: 09/09/2004 (Man. Year: 2004) Chassis No: JN1MG4E25Z0711739
 Colour: Silver Odometer: 355119 km
 Engine Capacity: 2953 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,414.62	2,865.45	1,549.17	35.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,190.00	370.00	23.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,974.62	4,055.45	1,919.17	32.12
Approved Total (Overridden) (\$\$)		3,200.00		
Nett Amount (\$\$)	5,974.62	3,200.00	2,774.62	46.44
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 06/05/2019
 Date Inspected: 14/05/2019 Inspected At: Guan Motor Works (HQ)
 176 Sin Ming Drive #02-03 Sin Ming
 Autocare
 Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

<https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=ge...> 6/4/2020

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	650.80 FL	*650.80 FL
2	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	91.70 FL	*91.70 FL
3	1		*FRONT LH STEP GARNISH	Deformed	384.30 FL	*384.30 FL
4	1		*FRONT LH STEP PANEL	Bent	523.00 FL	*523.00 FL
5	1		*FRONT LH DOOR PILLAR	Repair	1,721.30 FL	*- FL
6	1		*FRONT LH DOOR	Bent	1,228.10 FL	*1,228.10 FL
7	1		*FRONT LH DOOR RUBBER	Necessary	134.40 FL	*134.40 FL
8	1		*FRONT LH DOOR HINGE (TOP & BOTTOM)	Bent	138.20 FL	*138.20 FL
9	1		*FRONT LH DOOR COMPANY STICKER	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,901.80	3,180.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	487.18	315.05
Total Parts (\$\$)	4,414.62	2,865.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR REMOVE/REFIT ,CUTTING/WELDING AND REPLACEMENT OF DAMAGES	New	800.00	600.00
2	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	600.00	500.00
3	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST	New	80.00	60.00
4	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	30.00
Gross Labour Cost (S\$)			1,560.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >