

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0588/2019/DY/TF
Date : 8-May-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SGD 1808 B

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

3 days - ok - jb - 15 Jun 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Yeow Choon
Address : 495 Yio Chu Kang Road
#11-06
Singapore 787080
Telephone : (HP)+65 96611918
Type of Claim : Third Party Claim
Policy No. : DMPPHQ18-004938
Vehicle No : **SDQ 0880 P**
Model Code : Q3 1.4 TFSI S tronic
Model / Year : 16/8/2016
Engine No : CZD 240305
Chassis No : WAUZZZ8U8GR113304
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Apr-19
Place of Accident : CTE towards SLE after Braddell-

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDQ 0880 P

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function.	S/N \$	280.00	\$ 280.00
2	To dismantle and renew rear bumper. To inspect lhs tail lamp panel and lhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$	1,200.00	\$ 500.00
3	To respray rear bumper.	\$	1,200.00	\$ 550.00
4	Added labour	\$	2,200.00	\$ 1,050.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,072.00	\$ 2,572.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDQ 0880 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 1,354.00	\$ 1,083.00
2	REAR BUMPER FIXING PARTS	\$ 112.00	
3	REAR BUMPER SPOILER	\$ 434.00	\$ 346.80
4	REAR BUMPER TOWING COVER - LH / RH	\$ 63.00	
5	REAR BUMPER TAIL LIGHT - LH	\$ 418.00	\$ 334.40
6	REAR BUMPER CARRIER	\$ 569.00	\$ 454.80
7	FOAM FILLER PIECE	\$ 78.00	
8	REAR BUMPER GUIDE SECTION - LH	\$ 91.00	\$ 72.40
9	REAR BUMPER SENSOR	2 \$ 462.00	
10	REAR BUMPER SENSOR SEAL RING	\$ 5.00	
11	REAR WHEEL ARCH TRIM - LH / RH	\$ 472.00	\$ 377.60
12	Added parts	\$ 123.00	\$ 98.40
13	SUNDRIES	\$ 500.00	
TOTAL SPARE PARTS		\$ 4,681.00	\$ 2,767.40
TOTAL LABOUR CHARGES		\$ 5,072.00	\$ 2,572.00
GRAND TOTAL		\$ 9,753.00	\$ 5,339.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0588/2019/DY/TF 28-May-19 Glory Tan 1 of 1 SDQ 0880 P Q3 1.4 TFSI S tronic
Quantity	Description	Unit Price	Amount
<u>Parts</u> <u>1</u>	Air vent LHS rear	\$ 123.00	\$ 98.40
		\$ 123.00	\$ 98.40
<u>LABORS</u> <u>1</u>	To repair lhs tail lamp panel.	\$ 1,200.00	\$ 500.00
<u>2</u>	To respray lhs tail lamp panel.	\$ 1,000.00	\$ 550.00
		\$ 2,200.00	\$ 1,050.00
		\$ 123.00	\$ 98.40
		\$ 2,323.00	\$ 1,148.40

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant