

INS. CASE OWNER:

CC 4/ 11 1900 1967, R. Q. 3/1

DAC:

Surveyor:

Rural

DOI:

ASSIGNMENT

19/5/19

Date / Time:

6/5/2019

Registered in Merimen:

6/5/2019

Pre-assign / CCU / FTE



Insured Vehicle No.:

SH6765 U

Name of Insured:

C9PV

Insured Tel No.:

HP:

Excess Sec II : SS

D.O.A.:

30/04/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SCE 9938 S



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hitachi



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

SCE 9938 S. x :

SH6765 U - 03/11/1900 1296/7116792

- 04/11/1900 1296/7116792

12/1/19

12/1/19

14-05-19

Seek mandate for liability.

14-05-19

Mandate approve liability.

Mandate not liability claim.

18/6/19

File -> type mandate

12/7/19

PV sent

18/7/19

File -> MK to close.

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

ASSIGNMENT

From: 14/5/19
 Date: 14/5/19
 Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SLE 99385
 at Workshop m/s: HITACHI CAPITAL
 of: JAN TAI YU SERVICE CENTRE
 Insured: NO. 8 FOURTH LOK YANG RD
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh: dam owner waiting
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value:
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: Person Contacted: Vehicle: IN / OUT

Veh No: SLE 99385 Yr Regn: 2016 / 1467
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: TOYOTA COROLLA ALTS 1.6A cc 1598
 Colour: GRAY A/C: Insured / Std / NI / NA
 Sp. Reading: 250820 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: MRO53 REH 104556669
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / SRM / STD A/Rim or
 Tyre Size: F: 205/55R16
 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook
 Front: 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 30/04/19 D.O.I. 14/05/19
 Survey held at HITACHI
 Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PIP \$ 1957.13 CRed \$ 2588.50 / 574)

Date/Time, File Pass to? ☐ : Preli. Report ☐ : Final Report

1) Date/Time, File Return to? ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)

2) Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I.: (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos:

Others:

TOTAL:

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 04/05/2019

INDIA INTERNATIONAL INSURANCE

ACCIDENT DATE : 30/04/2019 @ 21:30

ATTN: MOTOR CLAIMS DEPT

VRN : SLE9938S

MODEL : TOYTA ALTIS 1.6

TP VRN : SH6765U

PARTS REPLACEMENT

1. Body Repair

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
1 REAR BUMPER <i>✓</i>	1	\$ 486.50	\$ 486.50	
2 REAR BUMPER CLIP <i>✓</i>	10	\$ 5.00	\$ 50.00	
3 REAR BUMPER SIDE RETAINER R/L <i>X S/L</i>	2	\$ 120.00	\$ 240.00	
4 REAR BUMPER REFLECTOR R/L <i>X (R/L) 1 pc ✓ (LH)</i>	1	\$ 58.00	\$ 116.00	
5 REVERSE SENSOR <i>7 S/L</i>	1	\$ 290.00	\$ 290.00	
6 REAR BUMPER REINFORCEMENT <i>bt ✓</i>	1	\$ 395.00	\$ 395.00	
7 REAR END PANEL <i>Repair X</i>	1	\$ 590.00	\$ 590.00	
			\$ 2,167.50	
Discount -25%			\$ 541.88	
			\$ 1,625.63	

PARTS TOTAL \$ 1,625.63

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of REAR Affected Area	\$ 1,280.00
Putty, Blend And Spray Paint on REAR Affected Area	\$ 1,000.00
Check Wiring and Ensure Proper Functioning	\$ 80.00
Remove and Refit Rear End Panel Lining and Garnish to Facilitate Repair	\$ 150.00
Remove and Reinstall Reverse Sensors	\$ 120.00
Remove and Reinstall Rear Reverse Camera	\$ 120.00
Cavity Treatment on New Parts	\$ 20.00
Conduct Water Seepage Test	\$ 120.00

LABOURS TOTAL \$ 2,920.00

Grand Total : \$ 4,545.63
 Add 7% GST : \$ 318.19
 Nett Total : \$ 4,863.82

No. of repair days: 7 by Repairer

Signature:
 Date:

CUSTOMER SIGNATURE



HITACHI CAPITAL ASIA PACIFIC PTE LTD
 (MANAGER)

Rasul
Hp 90010068
3 days
P/P
14/05/19 @ 1100
Rasul by paint

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

SUPPLEMENTARY VEHICLE ESTIMATE dated 22/05/2019

INDIA INTERNATIONAL INSURANCE

ATTN: MOTOR CLAIMS DEPT.

ACCIDENT DATE : 30/04/2019 @ 21:30
VRN : SLE9938S
MODEL : TOYOTA ALTIS 1.6
TP VRN : SH6765U

	Qty	S\$ Unit	S\$ Amt	S\$ Labor
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 BUMPER CLIP SCREW <i>✓</i>	4	\$ 5.00	\$ 20.00	
			\$ 20.00	
Discount -25%			\$ 5.00	
			\$ 15.00	
PARTS TOTAL			\$ 15.00	

*P: 989.50
MPP: 20.00
1009.50
- 25%
757.13
L: 1200.00
1957.13*

Grand Total : \$ 15.00
Add 7% GST : \$ 1.05
Nett Total : \$ 16.05

No. of repair days: 7

CUSTOMER SIGNATURE



HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0399N
Vehicle Details	
Vehicle No.:	SLE99385
Vehicle to be Exported:	No
Intended Deregistration Date:	30 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1ZRX590672
Chassis No.:	MR053REH104556669
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$16,800.00
Original Registration Date:	10 Aug 2016 ✓
First Registration Date:	10 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$16,800.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Aug 2026
PARF Rebate Amount:	\$12,600.00
Intended COE Rebate Details	
COE Expiry Date:	09 Aug 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,503.00
COE Rebate Amount:	\$37,768.00
Total Rebate Amount:	\$50,368.00

The information contained herein is correct as at 04 May 2019

OK

Print Received Message

This mail is associated with :

***SLE9938S (MCT19040886)
[SH6765U]**

TP

HITACHI CAPITAL ASIA PACIFIC PTE LTD
Apr 30 2019 9:00PM

Hitachi Capital Asia Pacific Pte. Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 14/05/2019 09:34 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SLE9938S - Claim Handler: Priya

Approved:0.00.

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Tuesday, 14 May 2019 12:05 PM
To: Vonn, LM Siow; Manivel Priyadarshini
Cc: JiongHow, Ng; Jamilah, Binte MohdKassim
Subject: RE: SLE9938S / SH6765U DOA: 30/4/2019 LIABILITY

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Sent: Tuesday, 14 May 2019 11:18 AM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Manivel Priyadarshini <manivel@iii.com.sg>
Cc: JiongHow, Ng <jionghow.ng@hcspl.com.sg>; Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>
Subject: RE: SLE9938S / SH6765U DOA: 30/4/2019 LIABILITY

Dear Asher,

Rasul just surveyed the vehicle.

Please follow up and revert on liability.

Thanks & Regards

Vonn Siow
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
DID: 6833 6274 Mobile: 96435107
e: vonnlm.siow@hcspl.com.sg
w: www.hitachi-capital.com.sg

From: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Sent: Monday, May 13, 2019 4:56 PM
To: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>; Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>
Subject: RE: SLE9938S / SH6765U DOA: 30/4/2019 LIABILITY

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir,

We refer to the email below.

We are still check the liability with our principal, meanwhile please kindly arrange survey as our insured reported that there is no damage to your clients vehicle.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Bk: 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Sent: Monday, 13 May 2019 3:36 PM
To: Manivel Priyadarshini <manivel@iii.com.sg>; Motor Claim - III <motorclaim@iii.com.sg>; SUR <sur@lkkauto.com>
Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Subject: RE: SLE9938S / SH6765U DOA: 30/4/2019 LIABILITY
Importance: High

Dear India International Insurance,

Kindly assist to follow up on the approval to LKK for us to have the liability reply.

Client is chasing on it.

Thanks & Regards

Vonn Siow
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
DID: 6833 6274 Mobile: 96435107
e: vonnlm.siw@hcspl.com.sg
w: www.hitachi-capital.com.sg

From: Vonn, LM Siow
Sent: Monday, May 6, 2019 11:25 AM
To: Manivel Priyadarshini <manivel@iii.com.sg>
Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JlongHow, Ng <jlonghow.ng@hcspl.com.sg>
Subject: RE: SLE99385 / SH6765U DOA: 30/4/2019 LIABILITY

Dear Ms Priya,

We refer to the subject above.

Kindy advise on the liability.

Thanks & Regards

Vonn Siow
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
DID: 6833 6274 Mobile: 96435107
e: vonnlm.siw@hcspl.com.sg
w: www.hitachi-capital.com.sg

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, May 6, 2019 11:19 AM
To: Vonn, LM Siow <vonnlm.siw@hcspl.com.sg>; 'sur@lkkauto.com' <sur@lkkauto.com>; admin-d@lkkauto.com

Cc: Manivel Priyadarshini <manivel@iii.com.sg>

Subject: RE: SLE9938S / SH6765U DOA: 30/4/2019 TP SURVEY & LIABILITY

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLE9938S and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Vonn, LM Siow [<mailto:vonnlm.siow@hcspl.com.sg>]

Sent: 06 May, 2019 10:37 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>

Subject: RE: SLE9938S / SH6765U DOA: 30/4/2019 TP SURVEY & LIABILITY

Dear sirs,

We prefer LKK Auto Consultants Pte Ltd to conduct the PRI.

Thanks & Regards

Vonn Siow

Motor Claims Advisor

Auto Servicing

Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705

DID: 6833 6274 Mobile: 96435107

e: vonnlm.siow@hcspl.com.sg

w: www.hitachi-capital.com.sg

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, May 6, 2019 9:17 AM
To: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Subject: RE: SLE9938S / SH6765U DOA: 30/4/2019 TP SURVEY & LIABILITY

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Vonn, LM Siow [<mailto:vonnlm.siow@hcspl.com.sg>]
Sent: 04 May, 2019 11:45 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Subject: SLE9938S / SH6765U DOA: 30/4/2019 TP SURVEY & LIABILITY

Dear sirs,

We refer to the subject above and the attachment is for your reference.

Vehicle is NOT IN workshop.

Kindly advise on the liability and we will arrange survey with you again.

Thanks & Regards

Vonn Siow

Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
DID: 6833 6274 Mobile: 96435107
e: vonnlm.slow@hcspl.com.sg
w: www.hitachi-capital.com.sg

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.
If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.
Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.
Print this email only if it is absolutely necessary and help in preservation of environment.
India International Insurance Pte Ltd.
Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.
If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.
Therefore, we do not accept liability for any errors or omissions in the content of this

message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Hsiao Tong (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Monday, 17 June 2019 3:43 PM
To: Jamilah, Binte MohdKassim; Manivel Priyadarshini; Hsiao Tong (LKKAUTO)
Cc: 関本崇 / Sekimoto, Takashi; HengCheong, Poon
Subject: RE: Accident SLE9938S DOA: 30/04/2019 Your Ref: SH6765U - LOD
Attachments: juntaio@hcspl.com.sg_20190617_142639.pdf

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Jamilah,

Thank you for the email.

The current case handler for this case is Hsiao Tong.

Hi HT,

FYNA.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>
Sent: Monday, 17 June 2019 3:30 PM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Manivel Priyadarshini <manivel@iii.com.sg>; motorclaim@iii.com.sg
Cc: 関本崇 / Sekimoto, Takashi <sekimoto@hcspl.com.sg>; HengCheong, Poon <poonhengcheong@hcspl.com.sg>
Subject: Accident SLE9938S DOA: 30/04/2019 Your Ref: SH6765U - LOD

Dear Asher,

LOD attached fyn, please.

Appreciate prompt settlement.

Thank you & regards,

Jamilah

Auto Servicing

Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
t: 6833 6265
e: jamilahbegum@hcspl.com.sg
w: www.hitachi-capital.com.sg

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	06 May 2019 21:25	Clm Dtl Modified	Claimant's Name: -> HITACHI CAPITAL ASIA PACIFIC P. Claimant's ID: -> 199400399N.	[A] HOW MEI KWAN
2	06 May 2019 21:26	Clm Veh Model Changed	(204463) TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A).	[A] HOW MEI KWAN
3	06 May 2019 21:26	Clm Created	Reg No: SLE9938S. Acct Date: 2019/04/30. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: MS First Capital Insurance Ltd (HQ). Workshop: Hitachi Capital Asia Pacific Pte. Ltd (HQ)	[A] HOW MEI KWAN
4	06 May 2019 21:26	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	06 May 2019 21:26	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/05/15	[A] HOW MEI KWAN
6	06 May 2019 21:26	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] HOW MEI KWAN
7	06 May 2019 21:26	Label Added	(30653):Direct Settlement.	[A] HOW MEI KWAN
8	06 May 2019 21:26	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] HOW MEI KWAN
9	13 May 2019 16:54	Adj Mandate Request	Cur,Req:0.00:PODS: LIABILITY: 100% REMARK: B:28 3VEH CC OID 2ND	[A] Asher Sng Rong Yi
10	14 May 2019 09:34	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/05/15	[I] Priya
11	14 May 2019 09:34	Adj Mandate Set	Approved:0.00.	[I] Priya
12	15 May 2019 14:12	Adj Adjuster Assigned	MOHD TAUFIKH BIN HAMID -> MOHD RASUL	[A] HOW MEI KWAN
13	21 Jun 2019 12:42	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
14	21 Jun 2019 12:42	Clm Dtl Modified	Insured Name: -> -. Insured ID: -> -.	[A] JOANNE LEE KHANG MIN
15	21 Jun 2019 12:42	Clm Dtl Modified	JPJ Reg. Date: -> 2016/08/10.	[A] JOANNE LEE KHANG MIN
16	21 Jun 2019 12:42	Clm Details Notified		[A] JOANNE LEE KHANG MIN
17	29 Jun 2019 09:49	Adj Mandate Request	Cur,Req:2374.43:PODS Liability: 100% Quantum: (a)CORw/GST: \$2,094.13 + (b)LOR w/GST(3days x \$85.00): \$272.85 + (c)LTA/GIA search fee: \$7.45 = Total: \$2,374.43 V ehicle Model: Toyota Corolla Altis (1598cc) 3 recommendation repair days For your app	[A] CHEW HSTAO TONG

Date From



Date To



Audit Type None

Go

Print Received Message

This mail is associated with :

***SLE9938S (MCT19040886)**
[SH6765U]

TP
HITACHI CAPITAL ASIA PACIFIC PTE LTD
Apr 30 2019 9:00PM
[-]
Hitachi Capital Asia Pacific Pte. Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 01/07/2019 10:43 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2374.43) - SLE9938S - Claim Handler: Priya

Approved:2374.43.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 12 July 2019 8:00 AM
To: Jamilah, Binte MohdKassim
Subject: RE: Accident SLE9938S DOA: 30/04/2019 Your Ref: SH6765U - Amended Claim Letter
Attachments: DV_SLE9938S.pdf

Without Prejudice

Dear Jamilah,

Thank you for your email.

We confirm settlement as follows: -

1. Cost of Repair (w/GST)	\$ 2,094.13
2. Loss of Rental (3days x \$85.00) (w/GST)	\$ 272.85
3. LTA/GIA Search Fee	\$ 7.45
Total	\$ 2,374.43

Please duly sign the **DV** enclosed and return together with the following document to us(LKK) for our necessary action: -

- Original LOD.
- Original Repair Tax Invoice.
- Original Rental Receipt.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>
Sent: Thursday, 11 July 2019 3:57 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: Accident SLE9938S DOA: 30/04/2019 Your Ref: SH6765U - Amended Claim Letter

Dear Hsiao Tong,

Attached fyns, please.

Sorry for the inconvenience caused.

Thank you & regards,
Jamilah
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
t: 6833 6265
e: jamilahbegum@hcspl.com.sg
w: www.hitachi-capital.com.sg

From: Jamilah, Binte MohdKassim
Sent: Monday, June 17, 2019 3:30 PM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Manivel Priyadarshini <manivel@iii.com.sg>;
motorclaim@iii.com.sg
Cc: 関本崇 / Sekimoto, Takashi <sekimoto@hcspl.com.sg>; HengCheong, Poon <poonhengcheong@hcspl.com.sg>
Subject: Accident SLE9938S DOA: 30/04/2019 Your Ref: SH6765U - LOD

Dear Asher,

LOD attached fyns, please.

Appreciate prompt settlement.

Thank you & regards,
Jamilah
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
t: 6833 6265
e: jamilahbegum@hcspl.com.sg
w: www.hitachi-capital.com.sg

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road
Singapore 629705

India International Insurance Pte Ltd
64 Cecil Street
#04/#05 IOB Building
Singapore 049711

Date : 11/07/2019

Re : Accident involving vehicle no.: SLE9938S and vehicle no(s): SH6765U on 30/04/2019 at PIE before enter to BKE

Dear Sir,

Reference to the above accident, we are submitting the following claims on damages to our client's vehicle caused by your insured's vehicle.

<input checked="" type="checkbox"/> Workshop repair bill (Cost of repairs) <u>TP10091368</u>	\$2,094.13
<input type="checkbox"/> Loss of use vehicle for <u>0</u> days at (\$ <u>0.00</u> /day)	
<input type="checkbox"/> Medical expenses	
<input type="checkbox"/> Surveyor report fee	
<input checked="" type="checkbox"/> Rental invoice	\$272.85
<input type="checkbox"/> Pain & suffering	
<input type="checkbox"/> Traffic police investigation fee	
<input checked="" type="checkbox"/> Search fee	\$7.45
<input type="checkbox"/> Others :	
Grand Total :	\$2,374.43

Please find the following documents enclosed,

- | | |
|--|--|
| <input type="checkbox"/> Accident Report | <input type="checkbox"/> Police Investigation Result |
| <input checked="" type="checkbox"/> Repair Bill | <input type="checkbox"/> Medical Receipt |
| <input checked="" type="checkbox"/> Vehicle Rental Receipt | <input type="checkbox"/> Surveyor Bill |
| <input checked="" type="checkbox"/> Search Fee Receipt | <input type="checkbox"/> Excess Bill |
| <input type="checkbox"/> My Insurance Company | |
| <input type="checkbox"/> Policy No | |
| <input type="checkbox"/> Others | |

We look forward to your settlement within 30 days failing which you have to bear all costs incurred for engaging a solicitor to enable us to recover full settlement from your company.

Thank you.
HITACHI CAPITAL ASIA PACIFIC PTE. LTD.


.....
TAKASHI SEKIMOTO (MR)

Hitachi Capital Asia Pacific Pte. Ltd.
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705

Tel: 64663022

Fax: 68966591

Co.Reg.No. 199400399N

GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : India International Insurance Pte Ltd

64 Cecil Street

#04/#05 IOB Building

Singapore 049711

Attn : Motor Claim Dept

Invoice No : TP10091368

Accident Date : 30/04/2019

Veh Regn : SLE9938S

Model : Toyota Altis

Date : 29/05/2019

Terms : 0 days

Due Date : 29/05/2019

Your Insured : SH6765U

Total Pages : 1 / 1

1. Body Repair

Parts & Labour Charges

Qty	S\$Unit	S\$Amt	S\$Labor
1 Parts			757.13
2 Labour			1,200.00

SubTotal : 0.00 1,957.13

Grand Total : 1,957.13

Add 7 % GST : 137.00


Net Total After GST : 2,094.13

INTEREST OF 1% PER MONTH WILL BE CHARGED ON ANY AMOUNT OUTSTANDING FROM DUE DATE

All cheques should be crossed and made payable to :

Hitachi Capital Asia Pacific Pte. Ltd.

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.



TAKASHI SEKIMOTO (MR)

Manager

Auto Servicing

Motor Vehicle Solutions Department

Service Manager

Job done by :

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Talyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64663022 Fax: 68966591
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : Strides Transportation Pte Ltd
60 Woodlands
Industrial Park E4
Singapore 757705
Attn : Timothy Yap


Invoice No : NR40091370
Accident Date : 30/04/2019
Veh Regn : SLE9938S
Model : Toyota A/lis
Date : 29/05/2019
Terms : 0 days
Due Date : 29/05/2019
Your Insured : SH6765U
Total Pages : 1 / 1

	Qty	\$\$Unit	\$\$Amt	\$\$Labor
1. Rental Fee				
1 Rental of SKL517H for 3 days	3.00	85.00	255.00	
			SubTotal :	255.00 0.00
			Grand Total :	255.00
			Add 7 % GST :	17.85
			Net Total After GST :	272.85

INTEREST OF 1% PER MONTH WILL BE CHARGED ON ANY AMOUNT OUTSTANDING FROM DUE DATE

All cheques should be crossed and made payable to :
Hitachi Capital Asia Pacific Pte. Ltd.

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.


TAKASHI SEKIMOTO (MR)
Manager
Auto Servicing
Total Vehicle Solutions Department

Service Manager

Job done by :

Replacement Vehicle Report

Particulars of Hirer

Name : Timothy Yap
 Company's Name : Strides Transportation Pte Ltd
 Address : 60 Woodlands Industrial Park E4 Singapore 757705
 Vehicle No : SLE9938S
 Tel : 63690111
 HP : 90615576 & 92252599

Vehicle Particulars

Vehicle No : SKL517H
 Maker : Toyota
 Model : Altis 1.6L

Reason for Replacement :

- ☒ Accident
☐ Repair
☐ Others

OUT

Petrol: 100


Date : 22/05/2019
 Time : 11:30 am
 Mileage (km) : 132551 km
 No of Keys (pcs) : 1




IN

Petrol: 100

Date : 24/5/19
 Time : 10:02 am
 Mileage (km) : 133240
 No of Keys (pcs) : 1



"X" on Damage Parts



We hereby confirm our acceptance:

Name: Ng Sine Teale
 HP: 9233 5746



For/on behalf of Hitachi Capital Asia Pacific Pte. Ltd.

Name: [Signature]
 HP: [Signature]



For/on behalf of Hitachi Capital Asia Pacific Pte. Ltd.

- Excess \$1,000 in Singapore / \$1,500 in Malaysia. Additional Excess of \$3,000 for young driver age 25 years & below or driving license less than 2 years.
- In case of vehicle's Insurance is under Third Party only, Excess is to cover for any third party damage or injury claims.
- The Lessee shall be responsible for same petrol level (\$25.00 / quarter) and all traffic offences.

Others:

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 04 May 2019 / 10:19:25

Receipt Date/Time : 04 May 2019 / 10:19:25

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190504-000355

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SH6765U

As at 30 Apr 2019/21:30:00

Insurance Co: INDIA INT'L INS PTE LTD

1 Insurance Enquiry - SH6765U

Enquiry Fee

20190504101828042216

Sub-Total	7.00	0.49	7.49
Total Before Rounding	7.00	0.49	7.49
Rounding Difference			0.04
Total Amount Payable			7.45

Paid By

xxxxxxxxxxxx8464	Credit Card: Visa/MasterCard	7.45
------------------	---------------------------------	------

Total	7.45
Cash Change	0.00
Tendered Amount	7.45
Excess Refundable Amount	0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre
No. 8 Fourth Lok Yang Road
Singapore 629705

Date : 11/07/2019

India International Insurance Pte Ltd
64 Cecil Street
#04/#05 IOB Building
Singapore 049711

Re : Accident involving vehicle no.: SLE9938S and vehicle no(s): SH6765U on 30/04/2019 at PIE before enter to BKE

Dear Sir,

Reference to the above accident, we are submitting the following claims on damages to our client's vehicle caused by your insured's vehicle.

<input checked="" type="checkbox"/> Workshop repair bill (Cost of repairs) <u>TP10091368</u>	\$2,094.13
<input type="checkbox"/> Loss of use vehicle for <u>0</u> days at (\$ <u>0.00</u> /day)	
<input type="checkbox"/> Medical expenses	
<input type="checkbox"/> Surveyor report fee	
<input checked="" type="checkbox"/> Rental invoice	\$272.85
<input type="checkbox"/> Pain & suffering	
<input type="checkbox"/> Traffic police investigation fee	
<input checked="" type="checkbox"/> Search fee	\$7.45
<input type="checkbox"/> Others :	
Grand Total :	\$2,374.43

Please find the following documents enclosed,

- | | |
|--|--|
| <input type="checkbox"/> Accident Report | <input type="checkbox"/> Police Investigation Result |
| <input checked="" type="checkbox"/> Repair Bill | <input type="checkbox"/> Medical Receipt |
| <input checked="" type="checkbox"/> Vehicle Rental Receipt | <input type="checkbox"/> Surveyor Bill |
| <input checked="" type="checkbox"/> Search Fee Receipt | <input type="checkbox"/> Excess Bill |
| <input type="checkbox"/> My Insurance Company | |
| <input type="checkbox"/> Policy No | |
| <input type="checkbox"/> Others | |

We look forward to your settlement within 30 days failing which you have to bear all costs incurred for engaging a solicitor to enable us to recover full settlement from your company.

Thank you.

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.


TAKASHI SERIMOTO (MR)

Hitachi Capital Asia Pacific Pte. Ltd.
Total Vehicle Solutions Department

[illegible]

DISCHARGE VOUCHER
III- Direct Settlement (PODS)

Occupation: _____

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64663022 Fax: 68966591
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : India International Insurance Pte Ltd
64 Cecil Street
#04/#05 IOB Building
Singapore 049711
Attn : Motor Claim Dept

Invoice No : TP10091368
Accident Date : 30/04/2019
Veh Regn : SLE9938S
Model : Toyota Altis
Date : 29/05/2019
Terms : 0 days
Due Date : 29/05/2019
Your Insured : SH6765U
Total Pages : 1 / 1

1. Body Repair

- 1 Parts
- 2 Labour

Parts & Labour Charges

Qty	S\$Unit	S\$Amt	S\$Labor
-----	---------	--------	----------

757.13

1,200.00

SubTotal : 0.00 1,957.13

Grand Total : 1,957.13

Add 7 % GST : 137.00

Net Total After GST : 2,094.13

INTEREST OF 1% PER MONTH WILL BE CHARGED ON ANY AMOUNT OUTSTANDING FROM DUE DATE

All cheques should be crossed and made payable to :
Hitachi Capital Asia Pacific Pte. Ltd.

HITACHI CAPITAL ASIA PACIFIC PTE LTD

S. S. S. S.
TAKASHI SEIMOTO (Jr)
Manager
Sales & Marketing

Service Manager
Job done by :

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64663022 Fax: 68966591
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : Strides Transportation Pte Ltd
60 Woodlands
Industrial Park E4
Singapore 757705
Attn : Timothy Yap

Invoice No : NR40091370
Accident Date : 30/04/2019
Veh Regn : SLE9938S
Model : Toyota Altis
Date : 29/05/2019
Terms : 0 days
Due Date : 29/05/2019
Your Insured : SH6765U
Total Pages : 1 / 1

1. Rental Fee

1 Rental of SKL517H for 3 days

Qty	S\$Unit	S\$Amt	S\$Labor
-----	---------	--------	----------

3.00	85.00	255.00	
------	-------	--------	--

SubTotal :	255.00	0.00
------------	--------	------

Grand Total : 255.00

Add 7 % GST : 17.85

Net Total After GST : 272.85

INTEREST OF 1% PER MONTH WILL BE CHARGED ON ANY AMOUNT OUTSTANDING FROM DUE DATE

All cheques should be crossed and made payable to :
Hitachi Capital Asia Pacific Pte. Ltd.

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.


TAKASHI SEKIMOTO (MR)
Manager
Auto Servicing
Unit: Motor Vehicle Servicing

Service Manager

Job done by :

Replacement Vehicle Report

Particulars of Hirer

Name : Timothy Yap
 Company's Name : Strides Transportation Pte Ltd
 Address : 60 Woodlands Industrial Park E4 Singapore 757705
 Vehicle No : SLE9938S
 Tel : 63690111
 HP : 90615576 & 92252599

Vehicle Particulars

Vehicle No : SKL517H
 Maker : Toyota
 Model : Altis 1.6L


Reason for Replacement :

- ☒ Accident
☐ Repair
☐ Others


OUT
 Date : 22/05/2019
 Mileage (km) : 11250
 No of Keys (pcs) : 1
 Petrol: 100
 50
 0

IN
 Date : 24/5/19
 Mileage (km) : 11250
 No of Keys (pcs) : 1
 Petrol: 100
 50
 0


"X" on Damage Parts



We hereby confirm our acceptance:

Name : Ng Jia Hui
 HP : 9233 5746


For/on behalf of Hitachi Capital Asia Pacific Pte. Ltd.

Name :
 HP :


For/on behalf of Hitachi Capital Asia Pacific Pte. Ltd.

- Excess \$1,000 in Singapore / \$1,500 in Malaysia. Additional Excess of \$3,000 for young driver age 25 years & below or driving license less than 2 years.
- In case of vehicle's Insurance is under Third Party only. Excess is to cover for any third party damage or injury claims.
- The Lessee shall be responsible for same petrol level (\$25.00 / quarter) and all traffic offences.

Others:

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 04 May 2019 / 10:19:25

Receipt Date/Time : 04 May 2019 / 10:19:25

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190504-000355

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SH6765U As at 30 Apr 2019/21:30:00 Insurance Co: INDIA INTL INS PTE LTD			
1	Insurance Enquiry - SH6765U Enquiry Fee 20190504101828042216	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx8464 Credit Card Visa/MasterCard			7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2019 Edit Reg		06 May 2019 00:00 Edit Adj Rpt	S\$1,957.13 Edit Estimates	S\$1,957.13 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N								
Vehicle Reg. No.:	SLE9938S	Date of Loss:	30/04/2019 21:00 - :59 [32 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19040886	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SH6765U	Policy No. (Claimant):	MSD/VPCP/18-000756-00						
		Excess:							
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 15/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (01/07/2019): Alert - Adj Mandate Approved (S\$2374.43) - SLE9938S - Claim Handler: Priya III_SG (14/05/2019): Alert - Adj Mandate Approved (S\$0.00) - SLE9938S - Claim Handler: Priya 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE9938S (MCT19040886)
[SH6765U]






































TP

HITACHI CAPITAL ASIA PACIFIC PTE LTD

Apr 30 2019 9:00PM

[COMFORT TRANSPORTATION PTE LTD]

Hitachi Capital Asia Pacific Pte. Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/05/19 16:49	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	28/05/19 16:49	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
3	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
4	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
5	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
6	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
7	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
8	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
9	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
10	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
11	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
12	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
13	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
14	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
15	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
16	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
17	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
18	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
19	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
20	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
21	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
22	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
23	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
24	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
25	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
26	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
27	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
28	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
29	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
30	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
31	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
32	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
33	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
34	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
35	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
36	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>
37	28/05/19 16:49	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	28/05/19 16:49	General View		<input checked="" type="checkbox"/>
39	28/05/19 16:49	General View		<input checked="" type="checkbox"/>
40	28/05/19 16:49	General View		<input checked="" type="checkbox"/>
41	28/05/19 16:49	General View		<input checked="" type="checkbox"/>
42	28/05/19 16:49	General View		<input checked="" type="checkbox"/>
43	28/05/19 16:49	General View		<input checked="" type="checkbox"/>
44	28/05/19 16:49	General View		<input checked="" type="checkbox"/>
45	28/05/19 16:49	General View		<input checked="" type="checkbox"/>
46	28/05/19 16:49	General View		<input checked="" type="checkbox"/>
47	28/05/19 16:49	General View		<input checked="" type="checkbox"/>
48	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
49	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
50	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
51	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
52	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
53	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
54	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
55	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
56	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
57	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
58	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
59	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
60	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
61	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
62	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
63	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
64	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
65	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
66	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
67	29/06/19 09:41	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/05/19 21:26	ACKNOWLEDGEMENT EMAIL TO III DD 06.05.2019		<input type="checkbox"/>
2	06/05/19 21:26	TP ESTIMATE + TP GIA REPORT		<input type="checkbox"/>
3	16/05/19 20:34	TP ESTIMATE - MARKED		<input type="checkbox"/>
4	21/06/19 12:55	WORKSHOP INVOICE		<input type="checkbox"/>
5	21/06/19 12:55	RENTAL RECEIPT		<input type="checkbox"/>
6	21/06/19 12:55	LTA SEARCH		<input type="checkbox"/>
7	23/07/19 10:24	DISCHARGE VOUCHER		<input type="checkbox"/>
8	23/07/19 10:24	LOD		<input type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	07/05/19 08:38	Singapore Accident Statement		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

	^ v
--	--------

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19007967/R1PA3Q2

Date: 23/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant Vehicle No : SLE9938S **Insured Vehicle No :** SH6765U
 Date of Loss: 30/04/2019 Nature of Claim: TP Claim No: MCT19040886

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE9938S**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRX590672
 Reg. Date: 10/08/2016 (Man. Year: 2016) Chassis No: MR053REH104556669
 Colour: Grey Odometer: 250820 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,640.63	757.13	883.50	53.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,200.00	1,720.00	58.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,560.63	1,957.13	2,603.50	57.09
+ GST 7.00/7.00% (\$\$)	319.24	137.00	182.24	57.09
Nett Amount (\$\$)	4,879.87	2,094.13	2,785.74	57.09
+ Car Rental (3.0 x S\$85.00/day + 7.00% GST) (\$\$)		272.85		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,374.43		

INSPECTION

Date of Assignment: 06/05/2019
 Date Inspected: 14/05/2019 Inspected At: Hitachi Capital Asia Pacific Pte. Ltd (HQ)
 No 8 Fourth Lok Yang Road
 Singapore 629705
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2019)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE9938S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	486.51 FL	*486.51 FL
2	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
3	2		*REAR BUMPER SIDE RETAINER R/L	Serviceable	240.00 FL	*- FL
4	1		*REAR BUMPER REFLECTOR R/L	N/S Cracked	116.00 FL	*58.00 FL
5	1		*REVERSE SENSOR	Serviceable	290.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	395.00 FL	*395.00 FL
7	1		*REAR END PANEL	Repair	590.00 FL	*- FL
8	4		*BUMPER CLIP SCREW (SUPP)	Necessary	20.00 FL	*20.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,187.51	1,009.51
- List Item Discount on L Items 25.00/25.00% (\$\$)	546.88	252.38
Total Parts (\$\$)	1,640.63	757.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEAT ,CUT ,WELD ,RE-ALIGN & REPLACE DAMAGED PARTS OF REAR AFFECTED AREA	New	1,250.00	500.00
2	PUTTY ,BLEND AND SPRAY PAINT ON REAR AFFECTED AREA	New	1,000.00	500.00
3	CHECK WIRING AND ENSURE PROPER FUNCTIONING	New	80.00	60.00
4	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New	150.00	60.00
5	REMOVE AND REINSTALL REVERSE SENSORS	New	120.00	60.00
6	REMOVE AND REINSTALL REAR REVERSE CAMERA	New	120.00	0.00
7	CAVITY TREATMENT ON NEW PARTS	New	80.00	20.00
8	CONDUCT WATER SEEPAGE TEST	New	120.00	0.00
Gross Labour Cost (S\$)			2,920.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >