

SERVICE ESTIMATE

67467 - C00001 SL: SERVICE SALES - PC

Ms Chella Ammall D/O Tanggarajo Pakri
16 Ladyhill Road

Singapore 258681

Closed by : Patricia Kueh Anak S
Svc Consultant :
Remarks : Ms Chella Ammall D/O

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 06/05/2019
WIP No. . : 12885
Veh.In/Out:
*Tel.No. . : Mobile: 93868397
Reg.No. . : SKD1712X
Reg.date . : 15/07/2011
Mileage .. : 0
Chassis No: SAJAC22F7BLV11653

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER, HEADLAMP LH,ETC	0	1200.00	0		1,200.00	S
800	TO PUTTY SPRAYPAINT ON FRT BUMPER,ETC	0	1000.00	0		1,000.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S
280	TO FOCUS HEADLAMP LH	0	162.00	0		162.00	S
	BUMPER COVER FRT XJL	1.0 EA	3010.90			3,010.90	S
	BUMPER BLIND RIVET X	10.0 EA	1.90			19.00	S
	POWERWASH COVER LH X	1.0 EA	61.50			61.50	S
	HEADLAMP LH XJL HID	1.0 EA	3179.10			3,179.10	S

Gross Total. 9,118.50

Labour Total 2,848.00
Parts Total 6,270.50
Package Total 0.00

Net..... 9,118.50
GST @ 7.0% 638.30
Total..... 9,756.80
Paid..... 0.00
Please Pay.. 9,756.80

GST: S=StdRated; O=OutOfScope; Z=ZeroRated