

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

Estimate No: ES1991498/WS

Date: 11 May 2019

Policy No: -

Veh Reg No: SLV4763Y

Make/Model: MERCEDES MERCEDES
E200 EXCLUSIVE

Chassis No: WDD2130422A120344

Engine No:

Reg. Date: 29/12/2017

WS Ref: TP AXA

Claim Type: Third Party

Accident Date: 13/04/2019

TP Veh Reg No: SGK5691G

Not Authorised

Running B4 paint

3 days

Estimate Repair Cost to Vehicle No :SLV4763Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 FRONT BUMPER	1,220.00	1 PC	1,220.00	✓
2 FRONT BUMPER SIDE RETAINER RH	24.00	1 PC	24.00	✓
3 FRONT PARKING SENSOR RH	188.90	1 PC	188.90	✓
4 HEADLAMP RH	5,785.00	1 PC	5,785.00	✓
			7,217.90	
		Less 10%	721.79	6,496.11
Labour				
5 TO REMOVE AND REFIX FRT BUMPER ASSY, HEADLAMP, CENTRE LOWER GRILLE, PARKING SENSOR; KNOCK AND RPAIR FRT RH FENDER AND HEDLAMP PANEL AND RE-ALIGN TO SAME	500	1 LA	500.00	350
6 PUTTY AND RESPRAY ON FRT BUMPER, FRT RH FENDER	550	1 LA	550.00	440
			1,050.00	1,050.00
Total				S\$ 7,546.11
Add GST @ 7%				528.23
Total Amount Payable				<u>S\$ 8,074.34</u>

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE