



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: DANIEL PAY

Ref: CS3/ASM19008038/Nhb3s2
Date: 16-12-2019
Code: ASM



1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLB 3426H	Veh. Inspected	FX 1833J
Policy No.	GA179409	Coverage (\$)	0.00
Claim No.	S9M01KP4	Excess (\$)	0.00
Assign From	DANIEL PAY	Assign Date	06/05/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA CBR 150	c.c	150
Engine No.	HIDDEN	Year of Reg.	2003
Chassis No.	NCB1500012097	Colour	RED
Odometer	17814 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	80/90 R17	DUNLOP	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	90/80 R17	DUNLOP	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.	
---	--

5. General Information

Accident Date	16/04/2019	Inspect Date / Time	06/05/2019 (04:51 PM)
Survey held at	39 WOODLANDS CLOSE #01-34/35		
Repairer	JCN AUTOLUTION PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------

Report Ref No. CS3/ASM19008038/Nhb3s2

Inspected By

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.