

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022184
Tang Zheng-Piau Roy

Page 1 of 2
Your ref. TP-SGE 2200S EQ
Job No. 70477
Our ref. 19.05.13
Payment
Date 7/5/2019

Attn

Vehicle No SJK 7802E
Vehicle Model : Honda CRV
Accident on ... 4/5/2019

Not Notarise
Resurvey By pain
4 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
3.00	Pcs	Rear windscreen moulding	13.00		<i>me</i> 39.00
1.00	Pc	Rear boot lid	680.00		<i>me</i> 680.00
1.00	Pc	Rear CRV emblem	25.00		<i>me</i> 25.00
1.00	Pc	Rear boot lid lower cover	170.00		<i>me</i> 170.00
1.00	Pc	Rear bumper	280.00		<i>me</i> 280.00
1.00	Pc	Rear bumper lower spoiler	110.00		<i>me</i> 110.00
1.00	Pc	Rear bumper cover LH	50.00		<i>me</i> 50.00
1.00	Pc	Rear reflector LH	35.00		<i>me</i> 35.00
Total amount of parts supplied - S\$1389.00					
1.00		15% of parts supplied:	208.35		208.35
Labour & Misc:					
1.00		To check/erase fault codes	80.00		80.00 ?
1.00		To remove and refix rear windscreen	140.00		<i>120</i> 140.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the supply dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0022184
Tang Zheng-Piau Roy

Page: 2 of 2
Your ref.: TP-SGE 2200S EQ
Job No.: 70477
Our ref.: 19.05.13
Payment
Date: 7/5/2019

Attn

Vehicle No: SJK 7802E
Vehicle Model : Honda CRV
Accident on ...: 4/5/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To supply sealant	40.00		40.00
1.00		To straighten rear body, to renew of parts	600.00		600.00
1.00		To spray paint	700.00		700.00

Sub-Total 3,157.35
GST 7.00% 221.01
Total S\$ 3,378.36

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."