LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building 78 Shenton Way #08-16

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Attn: Nadaraja, Deeban Date: 31 May 2019

Preliminary Advice

Vehicle No : SMD8483L **Accident Date** : 04/05/2019 Make : AUDI A3 Policy No. : 1800111921 **Assignment Date** : 08/05/2019 **Excess** : S\$0.00 Date of Inspection : 08/05/2019 Est. Duration of Repair : 10 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	60,813.00 (inclusive supplementary)
Revised Amount	:S\$	27,134.00 (inclusive supplementary)
OL 1.10 /F (1 (1)	0.0	0.554.00

Check Items (Estimated) 9,551.00 :S\$ Total :S\$ 36,685.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 110,000.00 COE / PARF Rebate :S\$ 50,741.00

Salvage Value :S\$

59,259.00 Margin for Repair :S\$

Remarks

(X)	The vehicle is repairable at our adjusted amo	unt. We have a	also confirmed	l excess and p	olicy coverage.
	Kindly let us have your authorisation.				

- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments: Supplementary amount is \$ 733.00.