

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:31

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT

AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120 079120

Invoice No: 85014323

Date : 04/10/2019

Order : SMD8483L

Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT

AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

Regn No: SMD8483L (V 39221)

Regn Date: 07/09/2018

Mileage: 13003

WIP No.: 52535

Model: A3 SPORTSBACK 1.4 TFSI COD 8VF

Chassis: WAUZZZ8VXJA136615

Engine: CZE 815159

Dept: U

You have been assisted by :- UB-Lim Kee Siang (43)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	40.00	1.00	40.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHT,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND RENEW ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	1200.00	1.00	1,200.00
S	BODYWORK	M: TO REMOVE AND REINSTALL INTAKE MANIFOLD AND OTHER DAMAGE ENGINE COMPONENTS.	960.00	1.00	960.00
S	BODYWORK	M: TO DISMANTLE BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY	300.00	1.00	300.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,BONNET, BOTH HEADLIGHT.CUT OUT AND REWELD LHS FENDER SUPPORT AND CLOSING ELEMENT.ALIGN BOTH FRONT CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE CRASH MANAGEMENT COMPONENTS.	3500.00	1.00	3,500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BONNET,BOTH FRONT FENDER,BOTH FRONT UPPER A PILLAR AND LHS FRONT DOOR.TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT	3850.00	1.00	3,850.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	384.00	1.00	384.00
S	BODYWORK	M: TO SUPPLY STONE CHIP TREATMENT	180.00	1.00	180.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 17:31

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014323 Date : 04/10/2019 Order : SMD8483L Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SMD8483L (V 39221) Regn Date: 07/09/2018 Mileage: 13003 WIP No.: 52535

Model: A3 SPORTSBACK 1.4 TFSI COD 8VF Chassis: WAUZZZ8VXJA136615 Engine: CZE 815159 Dept: U

You have been assisted by :- UB-Lim Kee Siang (43)

		Details		Qty	Unit Price	Amount
X	A04E129611G	007243/ (V) (SK) AIRCLE	Less 020%	1.00	259.00	207.20
X	A8V3853651AA3FZ	GRILLE	Less 020%	1.00	1301.00	1,040.80
X	A8V0941773D	HEADLIGHT	Less 020%	1.00	5029.00	4,023.20
X	A8V0941774D	HEADLIGHT	Less 020%	1.00	5029.00	4,023.20
X	A8V0821105L	FENDER	Less 020%	1.00	777.50	622.00
X	A8V2819401 9B9	007239/ (V) (GER) COVER	Less 020%	1.00	163.50	130.80
X	A5Q0121251HS	RADIATOR (SK)	Less 020%	1.00	837.00	669.60
X	A8V0805588A	CARRIER	Less 020%	1.00	663.00	530.40
X	A04E129709L	MANIFOLD	Less 020%	1.00	536.50	429.20
X	A8V0807550A	FOAM INSER (SK)	Less 020%	1.00	172.00	137.60
X	A8V4807109E	BEAM	Less 020%	1.00	659.50	527.60
X	AG A13040M2	PREMIX-COOLANT	Less 020%	4.00	21.00	67.20
X	A8V0807065R GRU	COVER (SHARE)	Less 020%	1.00	1698.00	1,358.40
X	A8V0823029D	HOOD	Less 020%	1.00	2501.00	2,000.80
X	A5Q0121367G	BRACKET (LAST)	Less 020%	2.00	38.30	61.28
X	A8V0121285A	AIR DUCT	Less 020%	1.00	10.40	8.32
X	A8V0823126B	EDGING	Less 020%	1.00	24.90	19.92
X	A8V0807217A	COVER	Less 020%	1.00	111.00	88.80
X	A8V3807319	PLATE	Less 020%	1.00	270.00	216.00
X	A8V3807647B 9B9	GRILLE (SHARE)	Less 020%	1.00	145.50	116.40
X	A8V0821135A	SUPPORT	Less 020%	1.00	87.30	69.84
X	A8V3807183B	GUIDE	Less 020%	1.00	34.40	27.52
X	A8V0823301G	(A) (SK) HINGE 18/5/19	Less 020%	1.00	55.30	44.24
X	A8V0823302G	(A) (SK) HINGE 18/5/19	Less 020%	1.00	55.30	44.24
X	A5Q0129621B	AIR DUCT	Less 020%	1.00	18.10	14.48
X	A5Q0129618C	(A) (SK) AIR DUCT 15/5	Less 020%	1.00	31.50	25.20
X	A5Q0129637B	HOSE	Less 020%	1.00	30.60	24.48
X	A8V0121230	SEAL (SK)	Less 020%	1.00	7.10	5.68
X	A1K0121367F	MOUNTING	Less 020%	2.00	8.90	14.24
X	A8V0820536	BRACKET	Less 020%	1.00	16.30	13.04
X	A8V0823185C	CATCH	Less 020%	1.00	99.40	79.52
X	A8V0823186C	CATCH	Less 020%	1.00	99.40	79.52
X	A8V0821467E	BRACKET	Less 020%	1.00	42.60	34.08
X	A4H0823543	COVER	Less 020%	1.00	8.90	7.12

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 3 17:31

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014323 Date : 04/10/2019 Order : SMD8483L Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SMD8483L (V 39221) Regn Date: 07/09/2018 Mileage: 13003 WIP No.: 52535

Model: A3 SPORTSBACK 1.4 TFSI COD 8VF Chassis: WAUZZZ8VXJA136615 Engine: CZE 815159 Dept: U

You have been assisted by :- UB-Lim Kee Siang (43)

		Details		Qty	Unit Price	Amount
X	A8V0821091C	PLATE	Less 020%	1.00	55.30	44.24
X	A8V4823485C	HOOK	Less 020%	1.00	57.20	45.76
X	A8V0823480A	HOOK	Less 020%	1.00	80.90	64.72
X	A8V0823509A	LOCK (LAST)	Less 020%	2.00	183.50	293.60
X	A8V0823531A	BOWD CABLE (SK)	Less 020%	1.00	52.10	41.68
X	A431955465A	GASKET	Less 020%	1.00	6.90	5.52
X	A443955465	GASKET	Less 020%	1.00	2.90	2.32
X	A8K0010520A	PLATE	Less 020%	1.00	12.20	9.76
X	A8V0010515A	STICKER	Less 020%	1.00	6.40	5.12
X	A5Q0129254B	AIR DUCT	Less 020%	1.00	52.30	41.84
X	A8V0121284K	AIR DUCT	Less 020%	1.00	21.40	17.12
X	A8V0121283K	AIR DUCT	Less 020%	1.00	21.40	17.12
X	A8V3853949	PLATE (SHARE)	Less 020%	1.00	173.50	138.80
X	A5Q0955453R	WATER RES.	Less 020%	1.00	185.50	148.40
X	A8V0998474A	LED	Less 020%	1.00	665.50	532.40
X	A7PP941572AC	POWER MOD	Less 020%	1.00	692.50	554.00
X	A8S0907397D	CTRL UNIT	Less 020%	2.00	507.50	812.00
X	A7PP941572AC	(A) (SK) POWER MOD 18/	Less 020%	1.00	692.50	554.00
X	A8V0998473A	LED	Less 020%	1.00	665.50	532.40
X	AN 0161857	POP-RIVET	Less 020%	8.00	3.00	19.20
X	AN 91097201	(A) (SK) SCREW 18/5/19	Less 020%	5.00	2.10	8.40
X	AN 91178401	BOLT	Less 020%	1.00	3.80	3.04
X	AN 91178401	(A) (SK) BOLT 18/5/19	Less 020%	4.00	3.80	12.16
X	AWHT005551	BOLT	Less 020%	10.00	1.20	9.60
X	A5Q0129954	COVER	Less 020%	1.00	26.70	21.36

Parts 20,696.48
Labour 0.00
Sublet 10,774.00
Menus 0.00
Lubricant 0.00



Sub-Total 31,470.48

7% GST 2,202.93

Grand Total 33,673.41

Received by

For & on behalf of
Premium Automobiles Pte Ltd