

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:46

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014610 Date : 16/12/2019 Order : SMG5000B Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SMG5000B (V 39464)	Regn Date: 30/10/2018	Mileage: 16088	WIP No.: 52631
Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV,	Chassis: WAUZZZF42JA229896	Engine: CVK 068490	Dept: U
You have been assisted by :- UB-Kelvin Khoo (138)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	360.00	1.00	360.00
S	BODYWORK	M: TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	600.00	1.00	600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	580.00	1.00	580.00
S	BODYWORK	M: TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	1400.00	1.00	1,400.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIM,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG	1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE REAR BUMPER,REAR LID,RHS FRONT DOOR AND REAR DOOR.CUT OUT AND WELD RHS REAR FENDER, RHS REAR INNER SIDE PANEL,RHS REAR OUTER WHEEL HOUSING AND RHS B PILLAR AND SILL PANEL.TO RENEW RHS FRONT AND REAR DOOR.REORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	6000.00	1.00	6,000.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER,RHS REAR FENDER, RHS FRONT DOOR,RHS REAR DOOR,RHS OUTER WHEEL HOUSING,RHS INNER SIDE PANEL,RHS B PILLAR,RHS SILL PANEL AND END PANNELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT	4400.00	1.00	4,400.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 17:46

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014610 Date : 16/12/2019 Order : SMG5000B Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SMG5000B (V 39464) Regn Date: 30/10/2018 Mileage: 16088 WIP No.: 52631

Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV, Chassis: WAUZZZF42JA229896 Engine: CVK 068490 Dept: U

You have been assisted by :- UB-Kelvin Khoo (138)

		Details	Qty	Unit Price	Amount
S	BODYWORK	SEALER WORK M: TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.TO INSPECT RHS REAR SUSPENSION FOR FURTHER DAMAGES	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	384.00	1.00	384.00
S	BODYWORK	M: TO SUPPLY REAR WINDSCREEN SEALANT,1/4 GLASS SEALANT,ACRYLIC SEALANT,CAVITY WAX, STONE CHIP GUARD AND METAL FILLER POWDER	1080.00	1.00	1,080.00
S	BODYWORK	M: TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER	800.00	1.00	800.00
S	BODYWORK	M: TO PLACE VEHICLE ON CAR-O-LINER	1800.00	1.00	1,800.00
X	A8W5810076	007228/(V) (GER) FRAME	Less 020%	1.00	2856.00
X	A8W5845501B NVB	(A) (SK) REARWINDOW 10	Less 020%	1.00	1049.00
X	A8W5845298D NVB	007228/(V) (GER) SIDE	Less 020%	1.00	560.50
X	A8W0809264	007228/(V) (GER) REINF	Less 020%	1.00	183.00
X	A8W0853374F 9B9	(A) (SK) SCUFF PLAT 10	Less 020%	1.00	109.00
X	A8W0831052D	(A) (SK) DOOR 10/5/19	Less 020%	1.00	2152.00
X	A8W0837912A	SEAL(LAST)	Less 020%	1.00	184.50
X	A8W0010502D	LABEL	Less 020%	1.00	34.20
X	A8W5833052C	(A) (SK) DOOR 10/5/19	Less 020%	1.00	2152.00
X	A8W5839912A	(A) (SK) SEAL 10/5/19	Less 020%	1.00	184.50
X	A8W0601025EF	RIM 16" CX1(LAST)	Less 020%	1.00	651.00
X	A8K5827261	CAP	Less 020%	1.00	3.30
X	A4G5827489	BUMPER	Less 020%	1.00	2.70
X	AWHT005180	BOLT	Less 020%	1.00	8.30
X	A8K9805673C	SPEED NUT	Less 020%	1.00	1.20
X	AN 91233601	NUT	Less 020%	2.00	1.00

Parts 8,106.56
Labour 0.00
Sublet 19,084.00
Menus 0.00
Lubricant 0.00

Sub-Total 26,390.56

7% GST 1,847.34

Grand Total 28,237.90



Received by

For & on behalf of
Premium Automobiles Pte Ltd