

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: LONPAC	DATE	: 6-May-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLT3014T		
MODEL	: TOYOTA C-HR HYBRID 1.8S		
CHASSIS NO	:		
<u>ACCIDENT DETAILS</u>	DATE : 3-May-19		
	TIME : 14:00PM		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

ZYX102059372

Xiao Tong

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rips torn</i>	1	\$ 830.00	\$ 830.00
2	FRONT BUMPER SIDE RETAINER RH <i>new</i>	1	\$ 62.30	\$ 62.30
3	HID HEADLAMP RH <i>new cracked</i>	1	\$ 1,955.20	\$ 1,955.20
4	FRONT FENDER RH <i>Dented</i>	1	\$ 530.50	\$ 530.50
5	FRONT FENDER INNER COWLING RH <i>new</i>	1	\$ 160.20	\$ 160.20
6	FRONT FENDER EMBLEM RH <i>new</i>	1	\$ 90.00	\$ 90.00
7	WHEEL ARCH RH <i>cut</i>	1	\$ 190.00	\$ 190.00
8	FRONT DOOR RH <i>Dented</i>	1	\$ 1,455.80	\$ 1,455.80
9	FRONT DOOR HINGE(UPPER) <i>3 new</i>	1	\$ 92.50	\$ 92.50
10	FRONT DOOR HINGE(LOWER)	1	\$ 92.50	\$ 92.50
11	FRONT DOOR CHECKER <i>new</i>	1	\$ 160.00	\$ 160.00
12	FRONT DOOR STICKER <i>new</i>	1	\$ 110.00	\$ 110.00
13	FRONT DOOR OUTER PROTECTOR <i>cut</i>	1	\$ 322.50	\$ 322.50
14	SIDE SKIRT RH <i>new new</i>	1	\$ 680.50	\$ 680.50
15	FRONT SIDE MIRROR COVER RH <i>Rips</i>	1	\$ 130.00	\$ 130.00
16	FRONT SIDE MIRROR RH <i>new Ripped</i>	1	\$ 920.00	\$ 920.00

6133.20
4599.50

TOTAL PRICE \$7,782.00
LESS 25% \$ 1,945.50
SUB TOTAL PRICE \$5,836.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 25.00	\$ 25.00	+
2	FRONT FENDER INNER COWLING LH (CLIPS) <i>new</i>	1	\$ 25.00	\$ 25.00	✓
3	FRONT FENDER SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
4	HEADLAMP CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
5	WHEEL ARCH CLIP(SET) <i>lt</i>	1	\$ 20.00	\$ 20.00	✓
6	FRONT SIDE SKIRT CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
7	WHEEL TYRE <i>new lt</i>	1	\$ 380.00	\$ 380.00 180.	
8	WHEEL RIM <i>lt</i>	1	\$ 850.00	\$ 850.00 450	
		650	TOTAL	\$1,420.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,200.00	600.	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	700	
3	MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	+	
4	WIRING CHECK	\$ 100.00	30	
5	TO REFOCUS HEADLAMP BEAM	\$ 250.00	+	
6	TO REMOVE AND REFIX FRONT DOOR RH	\$ 180.00	80	
		TOTAL	\$3,110.00	1410

ESTIMATE REPORT

TOTAL PARTS COST : \$7,256.50
 TOTAL LABOUR COST : \$3,110.00
 TOTAL REPAIR COST : \$10,366.50

APPROVED DETAILS

EXCESS :
 NO. OF WORKING DAYS :
 RE-SURVEY :
 PART BY PART OR LUMP SUM :
 DATE & TIME OF SURVEY :
 SURVEYED BY :
 CONTACT NUMBER :
 FAX NUMBER :

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Adrian Lij
 H/c 06/05/19.

Total: 6655.90
 C/S: 531C

05 Days