Not Athornal
The photo sedou pa

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711 Tel: 67472112 (5 lines) Fax: 67438032 Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLJ7462J/1905064

08th May 2019

The Manager Motor Claim Department India International Insurance Pte Ltd 64 Cecil Street #04/05 IOB Building Singapore 049711

Date of Accident

07th May 2019

Location

Holland Road

Third Party Claim Vehicle No :

SGH 1179 L

Repair Cost For Vehicle No

SLJ 7462 J Toyota Harrier

Estimate Supply of Parts & Labours

No.	Particulars	/a Oty	Price	Amounts
1	Rear bumper fascia	DD/De 1	1,381.50	\$ 1,381.50
2	Rear bumper clips	nec 1set	38.00	\$ 38.00
3	Rear bumper lower lip	20 1	586.30	\$ 586.30
4	Rear bumper lower lip reflector L&RH	11 2	54.10	\$ 108.20 X
5	Rear bumper sponge	Toin 1	137.10	\$ 137.10
6	Rear bumper side retainer L&RH	n 1 2	90.80	\$ 181.60 ℃
7	Rear boot cover w/strip	111	387.30	\$ 387.30 X
8	Rear boot cover emblem (Harrier)	nec 1	72.10	\$ 72.10
				\$ 2,892.10
		Less	25%	\$ 723.02
		1.1	-	\$ 2,169.08
9	Rear bumper reverse sensor (s/nett)	Shuffa 1	380.00	\$ 380.00 2005-2
				\$ 2,549.08

7-2215

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711 Tel: 67472112 (5 lines) Fax: 67438032 Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLJ7462J/1905064

08th May 2019

Balance b/f

Labour Charges:Cut out, renew, knocking & welding rear boot cover, rear end panel, remove & install all damage parts & re-align body
Remove & install rear bumper sensor
Spray painting on damage parts (pearl paint)
Check all lighting after repairs

\$ 2,549.08

Amounts
\$ 880.00

\$ 80.00

\$ 1,280.00

\$ 1,280.00

\$ 35.00

\$ 2,930.00

Total Amount

GST will be reflected in the final bills.

Notes: -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

Action The graph of the state o

\$ 5,479.08