

KIM CHWEE AUTO PTE LTD

BLK1 KAKI BUKIT AVE 6

#01-46,48,50 AUTOBAY

SINGAPORE 417883

VEHICLE NO: SLP 4956P

QTY	PARTICULAR		
1 PCS	FRONT BUMPER	103/70	Recurring \$1,266.10
1 PCS	FRONT BUMPER SIDE RETAINER O/S		\$66.50
1 SET	FRONT BUMPER CLIPS		\$50.00
1 PCS	FRONT BUMPER LAMP O/S		11 \$312.30 X
1 PCS	FRONT BUMPER REINFORCEMENT		11 \$546.50 X
1 PCS	HEADLAMP ASSY O/S	2450.00	one \$3,880.20
1 PCS	FRONT FENDER O/S		11 \$611.20 X
1 PCS	FRONT FENDER INNERSHIELD O/S		11 \$215.30 X
1 SET	FRONT FENDER INNERSHIELD CLIPS O/S		11 \$50.00 X
1 PCS	FRONT SPORT RIM O/S		11 \$1,075.00 X
1 PCS	FRONT SHOCK ABSORBER O/S		11 \$319.20 X
1 PCS	FRONT KNUCKLE ARM O/S		11 \$566.20 X
1 PCS	FRONT KNUCKLE ARM BEARING O/S		11 \$285.00 X
1 PCS	FRONT LOWER ARM O/S		11 \$422.10 X
			\$9,665.60
LABOUR CHARGES:			
	TO CHECK WIRING		\$50.00 20
	TO CONDUCT WHEEL ALIGNMENT		\$150.00 60
	TO DISMANTLE & REFIX FRONT UNDERCARRIAGE		11 \$180.00 X
	TO SPRAY RUST PROOFING		11 \$50.00 X
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$680.00 300
	TO PUTTY & SPRAY PAINTING		\$880.00 400
			TOTAL \$11,655.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

1-3598.20
207
2302.84
3658.56

not follow
KIM
9/5/19
2/5 2900
3 hrs.
Whole After repair