SS. REC. BY:	REF: C1 TRD19008250 Reported toleraction ASSIGNMENT (OMES) Kamaliah Kamie or SPF Desertions M H 2019 Bill to:
stimuted Cost: DITTTWST To Inspect Vehi	TP RES / OD BES / EVA / INV / MV / CS Instruct:
Workshop to of	TP 18 DOIR DOIR
	REP. / REV 24 HRS Person Contacted:
Date/Time	Action/Instruction () Estimate SLX 123K-X
	1x16/19 12 10 2007 68 8 106 10 10 10

Special Contraction

cc) Case IAFP-IB-20190416 - Mechanical Inspection of Motorcycle, FBD690M (TP/IP/22973/2019)

On 04/04/2019 at about 7.21 am, the Deceased was riding motor cycle FBD690M along Jalan Boon Lay when he suddenly lost control and self-skidded. Due to his injuries, he was conveyed to NGTF hospital in an unconscious state. He was pronounced dead on the same day.

Vehicles to be inspected: FBD690M (Rider - Deceased)

10 In-Charge: SIO Farhan

dd) Case IAFP-IB-20190416 - Mechanical Inspection of Motor Car, SLX123K (TP/IP/15991/2019)

On 18/03/2019 at about 12.30 pm, the accused was driving motor car SLX123K along Marine Parade Road when he lost control of the car, mounted the left kerb and collided onto a pedestrian (Deceased) who was walking on the footway. Driver claimed of mechanical failure which has led to the accident. Pedestrian was pronounced dead on the same day.

Vehicles to be inspected: SLX123K (Potential Defendant)

10 In-Charge: SIO Farhan

ee) Case IAFP-IB-20190416 - Mechanical Inspection of Motorcycle, FBG8909R (TP/IP/17985/2019)

On 21 February 2019 (Thursday) at about 5.15 p.m., the Deceased who was alone on his motorcycle, was travelling straight along Central Expressway towards the direction of Seletar Expressway, 8km on lane 1 of the 5-lanes road when he wobbled, swerved to the right and collided into the centre guard railings. Due to the impact, the Deceased fell face down on lane 1 of 1 of the 4-lanes road. As a result of the accident, the Deceased sustained facial injuries and was conveyed in an unconscious state by an ambulance to Tan Tock Seng Hospital. However on the same day at 7.25 p.m., the Deceased succumbed to his injuries and he was pronounced dead by Dr Tan Han Yee in Tan Tock Seng Hospital.

Vehicles to be inspected: FBG8909R (Rider - Deceased)

IO In-Charge: SIO Clarence Lim

1) Batters terminal block due

All filter & Jump pouk + i
Sparry Head to Small

2) To measure PCO the rims is

required to be removed

(w Type Tyreshop EQ repaired

Notes