

10/5/2011

ASS. REC. BY:

REF: 01/TPD19008284/NC

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Kamellah Kamie

of

SPFDate/Time: 29/4/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBK 3641Z

Insured:

at Workshop m/s

Tel:

of

Policy No: MHA:SPF06000017235Claim No: TP/IP/07649/2019

Sum Insured:

Excess:

D.O.A. 8/2/2019

Make of Veh:

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction ( ) Estimate

FBK 3641Z - X450X

t) Case IAFP-IB-20190405 - Mechanical Inspection of Motor Car, SJQ5827R (TP/IP/13095/2019)

On 5 March 2019 at about 6.58 p.m., the potential defendant (driver) was driving motor car SJQ5827R along the carpark vicinity of Blk 352 of Jurong East Street 31, towards the exit gantry. The driver was unable to control the said vehicle which resulted it to accelerate forward at fast speed. The vehicle then collided onto the barrier/ barricade and collided onto a pedestrian (Deceased) who was standing on the footway. The vehicle continued to surge forward and collided onto a moving motor cycle and 2 other motor cars. Ambulance arrived at scene and conveyed the Deceased to Ng Teng Fong Hospital in an unconscious state. The Deceased succumbed to her injuries and was pronounced dead in the hospital, A & E Department.

Vehicles to be inspected: SJQ5827R (Potential Defendant)

IO In-Charge: SIO Farhan

u) Case IAFP-IB-20190405 - Mechanical Inspection of Motorcycle, FBE4238E (TP/IP/03035/2019)

On 18th January 2019 at about 2.58 pm, police received a call regarding an accident along Serangoon Road towards Upper Serangoon Road before Hindoo Road. It was later established to be an RTA involving a motor cycle FBE4238E and a pedestrian along Serangoon Road towards Upper Serangoon Road before Hindoo Road, nearby lamp post D36. As a result of the accident, both sustained injuries and pedestrian was conveyed to Tan Tock Seng Hospital while rider conveyed to Raffles Hospital by Ambulance. Pedestrian sustained head injury and succumbed to his injuries and was pronounce dead by Dr Tan Wee How on 22.01.2019 @ 0908 hrs.

Vehicle to be inspected: FBE4238E (Involved party)

IO In-Charge: DOC Saleha

v) Case IAFP-IB-20190405 - Mechanical Inspection of Motorcycle, FBK3641Z (TP/IP/07649/2019)

On 8 February 2019 sometime before 12.52 pm., the Deceased was riding his motorcycle FBK3641Z, alone on the extreme left lane of 3 lanes along Tuas South Avenue 9 towards end when he lost control of his motorcycle and hit onto the left guard railings. The deceased was sent to Ng Teng Fong General Hospital (NTFGH) by ambulance in an unconscious state. The Deceased was pronounced dead at NTFGH at 1.42 pm by Dr Tong Shan Han.

Vehicle to be inspected: FBK3641Z (Deceased)

IO In-Charge: DOC Saleha