Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 17 June 2019 5:56 PM

To:

Boo seng yak; Carrine Leong; jlayee.yap@premiumauto.com.sg; Chang Chee Sing;

SUR

Subject:

RE: FINAL REVISION - SDN7518G - OD AIG - SURVEYED 9 MAY 19

Dear Mr Boo,

Confirm repair cost of \$3832.80 before excess \$1000 and GST @ 3 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Monday, 17 June 2019 5:22 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing

<claims@premiumauto.com.sg>

Subject: FINAL REVISION - SDN7518G - OD AIG - SURVEYED 9 MAY 19

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$3832.80 @ 3 days of repairs.

Your early closure is appreciated.

Best regards - jb

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Friday, 10 May 2019 4:53 PM

To:

Claims; Admin A

Cc:

SUR; (nora.khai@premiumauto.com.sg)

Subject:

RE: OD CLAIMS FOR SDN 7518 G

Dear Sheila,

Vehicle excess \$1000/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>

Sent: Friday, 10 May 2019 2:57 PM

To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: OD CLAIMS FOR SDN 7518 G

Dear All,

Kindly assist to register this car for Own Damage Claims. Survey was done on 9th May 2019 with Adrian, authorization was given.

Attached is GIA report and estimate for your reference.

Kindly advise excess amount.

Thank you and have a nice day.

Best Regards, Sheila M Ismail Claims Advisor

Best Regards, **Diyana**Claims Admin Assistant

Premium Automobiles Pte Ltd (Neg No. 199902271W) 55 Ubi Road 1 Road Singapore 408699 p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

è. claims@premiumauto.com.sg w. www.audi.com.sg



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	7101G	
Vehicle No.:	SDN7518G	
Vehicle to be Exported:	No	
Intended Deregistration Date:	10 May 2019	
Vehicle Make:	AUDI	
Vehicle Model:	Q5 SPORT 2.0 TFSI QU S TRONIC	
Primary Colour:	Blue	
Manufacturing Year:	2017	
Engine No.:	DAX012329	
Chassis No.:	WAUZZZFYXH2045653	
Maximum Power Output:	185.0 kW (248 bhp)	
Open Market Value:	\$44,891.00	
Original Registration Date:	26 Sep 2017	
First Registration Date:	26 Sep 2017	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$54,848.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	25 Sep 2027	
PARF Rebate Amount: Intended COE Rebate Details	\$41,136.00	
COE Expiry Date:	25 Sep 2027	
COE Category:	B - Car above 1600cc or 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$49,000.00	
COE Rebate Amount:	\$41,037.00	
Total Rebate Amount:	\$82,173.00	

The information contained herein is correct as at 10 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Fax Number Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	06/05/2019 09:51
Date Of Accident	04/05/2019 19:35
Exact Location Of Accident	BLK 131 CASHEW ROAD CARPARK
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SDN7518G
Insured/Policyholder	
Name Of Registered Owner	GAN FONG YIN
NRIC No	S6977101G
Email Address	GFONGYIN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97459128
Alternative Phone No	OTHERS-97459128
Vehicle Particulars	
Manufacturer	AUDI
Model	Q5 SPORT 2.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700056950-01
Cover Note Number	
Driver	
Name of Driver	CHONG YIN-YIN
NRIC No	S7129751I
Date Of Birth	20/08/1971
Occupation	INDOOR
Date Of Driving Pass	13/04/1999
Driving Experience	20 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97454168

GFONGYIN@GMAIL.COM

Address 97 HAZEL PARK TERRACE

Postcode Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLIDED INTO PARKED VEHICLE

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

2

Number of Passengers (Including Driver)

NAME:

: ETHAN GAN

GENDER:

: MALE

Details of Police Action

Passenger 1

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 4 MAY 2019 AT 7,30 PM, I WAS ON THE WAY TO PICK MY DAUGHTER AT BLK 130 CASHEW RD. I WAS REVERSING THE CAR IN FRONT OF BLK 131 CASHEW RD, THE CAR-PARK WAS NOT BRIGHTLY LIT (POOR LIGHTING). I REVERSED AND CRASHED ON THE RED MAZDA WHICH WAS PARKED. I HIT THE LEFT (FRONT) OF THE RED MAZDA BUMPER. MY CAR WAS DAMAGED ON THE RIGHT (BEHIND) LIGHTS AND BUMPER. THE ACCIDENT WAS AT 7.35 PM. I HAVE NOTIFIED THE RED CAR OWNER TO CONTACT ME. AT THE TIME OF THE ACCIDENT, THE RED CAR OWNER WAS NOT IN HIS CAR. UNTIL NOW, THE RED CAR OWNER HAS NOT CONTACTED ME.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? YES Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLC5644B MAZDA 6/RED

Vehicle Make/Model/Colour **Details Of Properties**

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode Insurance Company Name Nature Of Damage No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the academ to speed up the claims process
- 2. This form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be an truthful and accurate as possible. Any willful misrepresentation or withholding of muterial facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by sociatance companies is not an admission of policy liability on the part of the mourance. companies.
- 5. Any false reporting may be referred to the Police for lewestigation.
- 5. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the ladgment of this report to the recurrent, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforecald
- 5. Consent under the Personal Data Protection Act (PDPA)

Funderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GAA") may/are permitted to collect, use. disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or powersed by my insurer (rollectively the "Personal Information") and disclose and transfer such Petional hillorination to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the inquiers is awyers/low firms, the Minnetary Authority of Singapore and any relevant government agency/authority (such as the pulice), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims,
 - (ii) investigating the accident and/or my slams;
 - bill carrying out and/or dealing with my instructions or responding to any enquiries by me:
 - (ny) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail (seckages); and/or
 - (v) complying with applicable law in administering, processing, hundling and/or dealing with my claims (or lectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyins/law firms, may/are permitted to collect, use, disclose and/or process my Personal Indocmation for one or more of the above Porposes, and
- (c) mry Fersonal information may/can be distincted by any of the tissurers and/or GIA to their third party service providers or apents/including their lawyers/law firms), which may be sited outlide of Singapore, for one or more of the above Purposes.
- (d) my Fersonal Information will also be collected and used to complie claims followy for the purpose of flaud detection, inventigation and management in present and all future claims
- [it] the information so collected uniter (it) above more be shared / disclosed:
 - (i) As all onseres and/or any other third parties that assist in evaluating, investigating, controlling in managing frault. regulators, law enforcement and government agencies as reaconably required for the purposes stated, or
 - (s) for complying with requirements under any regulations, laws or court orders.

Patticipate (All Spirato) i Date & Time

Date & 1000 6 May 2019

Six masilly 589102606

Sketch Plan #2

SKETCH PLAN		
	CHILPARIC (OPENCING	F)
50N 75186	SLI CON OF SURIES	
DESCRIBE CIRCUMSTANCE	OF THE ACCIDENT	
On 4 May 26	19 at 7:30pm. I was	on the wan to nick my
Janah L	614 to 6 col - 01 7	tion and to pick my
	BIK 130 CASheW Rd. I 1	
		CAR park was not brightly
		crashed on the Red
Mazda which	was panked. I hit the	c left (front) of the red
Mazda . Mu	car was damaged o	in the right [lebind] lights
bumper ?	and tumper The	on the right (behind) lights tent was at 7=3gpm
100	and pumper the accid	ient was at 1-sypm
T (
		to contact me. At the
the time of t	he accident The red co	ar buner was not in
		r has not contacted me.
102 500 101	The races of the	THE STATE OF THE S
ECLARATION		
We disclore the foregoing partic	siles are tree in every respect.	0
	10.000	11 1000
	mondismon	- in
duyhelme's Signature ate & Time	Driver's Signature (If driver to not the policyholder) frame & Time: (a MAW) 2019	HERDERING CENTRE PERSONNEL ENGLISH THE SIL WAS SIL IK







CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: GAN FONG YIN

Period of Insurance

: 26 Sep 2018 To 25 Sep 2019

Engine No.

: DAX012329

Chassis No.

: WAUZZZFYXH2045653

Vehicle No. Policy No.

: SDN7518G

Endorsement No.

Issued Date

: 1700056950-01 29 Aug 2018

ABOUT THE COVER

Make/Model

Driver Restriction

: AUDI Q5 Sport 2.0 TFSI qu

Engine Capacity/Tonnage : 1,984.00 CC

Off Peak Car : No

Sum Insured : Market Value

First Year of Registration : 2017

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

: NA

This Policy will indomnify the Policyholder or any authorised driver only if he/sine meets the specified age condition.

You have to pay an additional sum of \$3,000 as. "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience

Age Condition

: 40 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Moter Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Melayera), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$2000 Theft - \$0 Flood Cover - \$0

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

GAN FONG YIN - \$2000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Util Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hottine at +85 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from (Tunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

WWe hereby certify that the policy to which this Certificate of Insurance relates is request in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of a the Road Transport Act, 1987 (Melaysia) and Motor Vehicles (Third Party Risks) Bulles, 1959 (Melaysia).

0504125264

PREMIUM LEASING -OKT

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pts. Ltd.

prile

AIG Asia Pacific Insurance Pte. Ltd. **AUTHORISED REPRESENTATIVE**

ET 11001 AIO AU 10 HOTLINE, TOO 0330 0200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

What should I do in the event of an accident?

Keep calm and move your car to a safe place

. Do not admit or discuss fault or blame with the other party(les).

Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

Submit Writ/Summons/Correspondences from third party(les) to AIG immediately.

If no one is injured in the accident:

You are not required to make any police report.

Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).

Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident

Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

Report the accident to the police, providing full details of the circumstances of the accident

Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.

Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident

Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your
accident claim.

Your rental car will be made available within 5 working hours of activation with the Rental Car Company.

- At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
- The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.

5. Rental cars are strictly for use in Singapore only.

- Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
- Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Walver, etc.)

IMPORTANT NOTICE


If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.









55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/OD/0581/2019/DY/TF

Date : 6-May-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Gan Fong Yin
Address : 97 Hazel Park Terrace

Singapore 678930

 Telephone
 : HP +65 97459128

 Type of Claim
 : Own Damage Claim

 Policy No.
 : 1700056950-01

Vehicle No : SDN 7518 G

Model Code : Audi Q5 SPORT 2.0 TFSI QU

Model / Year : 26/9/2017 Engine No : DAX 012329

Chassis No : WAUZZZFYXH2045653

Mileage

Date In :

Liability :

Estimated By : Johnny Boo / Allan Wu

Accident Date : 4-May-19

Place of Accident : Blk 131 Cashew Road Carpark

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDN 7518 G

S/n	Nature of Jobs			Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N	s	360.00	
2	To dismantle and renew rear bumper assy. To inspect rhs tail lamp panel. Re-organise rear crash management components. Reinstall all parts removed.		S	1,200.00	550X 2 = 1100
3	To respray rear upper bumper, rear lower bumper, and both rear wheel arch covers.		\$	2,500.00	Arch lover x2 = 200x2 = 400
4	To carry out diagnostic check.	S/N	5	192.00	1500
	TOTAL LABOUR CHARGES	:	\$	4,252.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SDN 7518 G

		Damaged Parts & Prices			
S/N	Parts Description		_	S/Nett	Remark
1	REAR BUMPER 2		\$	1,571.00	
2	REAR BUMPER MID		\$	1,077.00	
3	REAR BUMPER SPOILER Au		\$	754.00	t
4	REAR BUMPER TOWING CAP LH		\$	43.00 *	
5	REAR BUMPER TOWING CAP RH		\$	26.00	
6	REAR BUMPER EXHAUST COVER TRIM - RH		\$	86.00	
7	REAR BUMPER CHROME TRIM RH		S	213.00 t	
8	REAR BUMPER TAILLIGHT RH Could		s	627.00	501.60
9	REAR BUMPER CARRIER 7		5	831.00	
10	REAR BUMPER HOLDING STRAP		s	151.00 +	
11	REAR BUMPER GUIDE SECTION RH		\$	76.00	
12	REAR BUMPER FOAM FILLER PIECE RH 2		\$	56.00 ₺	
13	REAR PARKING AID SENSOR	2	5	462.00 =	
14	REAR PARKING AID SENSOR SEAL		\$	12.00	
15	REAR WHEEL ARCH COVER LH / RH	2	5	974.00	779.2C
16	SUNDRIES		5	500.00	×
	TOTAL SPARE PARTS		\$	7,459.00	
	TOTAL LABOUR CHARGES		\$	4,252.00	
	GRAND TOTAL		\$	11,711.00	
	All charges are not inclusive of CST				

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date Excess Cost

Liability

Remarks

Please Note

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey beforelatter spray painting
- To display damaged part(s) during resurvey.
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary flom(a) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

Arthorsed Reprine, 03 Days

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate

: Accident Repairs

Workshop

Ubi Road 1

Contact No

6366 2323

Fax No

6841 1183

Reference

PA/OD/0581/2019/DY/TF

Date

6-May-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 HI Adrian

3 days - ok - jb - 17 Jun 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Mr. Gan Fong Yin

Address

97 Hazel Park Terrace

Singapore 678930

Telephone

HP +65 97459128

Type of Claim

Own Damage Claim

SDN 7518 G

Policy No.

: 1700056950-01

Vehicle No

1700030830-01

Model Code

: Audi Q5 SPORT 2.0 TFSI QU

Model / Year

26/9/2017

Engine No

.....

milding in

DAX 012329

Chassis No

WAUZZZFYXH2045653

.....

Mileage

Date In

:

:

Liability

:

Excess Cost

.

Estimated By

; Johnny Boo / Allan Wu

Accident Date

4-May-19

Place of Accident

Blk 131 Cashew Road Carpark

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDN 7518 G

S/n	Nature of Jobs			Estimated Charges	Surveyor's Recommendation		
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N	\$	360.00	s	360.00	
2	To dismantle and renew rear bumper assy. To inspect rhs tail lamp panel. Re-organise rear crash management components. Reinstall all parts removed.		\$	1,200.00	\$	500.00	
3	To respray rear upper bumper, rear lower bumper, and both rear wheel arch covers.		\$	2,500.00	\$	1,500.00	
4	To carry out diagnostic check.	S/N	\$	192.00	\$	192.00	
	TOTAL LABOUR CHARGES	:	\$	4,252.00	s	2,552.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SDN 7518 G

		Damaged Parts & Prices				
S/N	Parts Description			S/Nett		Remark
1	REAR BUMPER		\$	1,571.00		
2	REAR BUMPER MID		\$	1,077.00		
3	REAR BUMPER SPOILER		\$	754.00		
4	REAR BUMPER TOWING CAP LH		\$	43.00		
5	REAR BUMPER TOWING CAP RH		\$	26.00		
6	REAR BUMPER EXHAUST COVER TRIM - RH		\$	86.00		
7	REAR BUMPER CHROME TRIM RH		\$	213.00		
8	REAR BUMPER TAILLIGHT RH		\$	627.00	\$	501.60
9	REAR BUMPER CARRIER		\$	831.00		
10	REAR BUMPER HOLDING STRAP		\$	151.00		
11	REAR BUMPER GUIDE SECTION RH		\$	76.00		
12	REAR BUMPER FOAM FILLER PIECE RH		\$	56.00		
13	REAR PARKING AID SENSOR	2	\$	462.00		
14	REAR PARKING AID SENSOR SEAL		\$	12.00		
15	REAR WHEEL ARCH COVER LH / RH	2	\$	974.00	\$	779.20
16	SUNDRIES		\$	500.00		
	TOTAL SPARE PARTS	1	\$	7,459.00	\$	1,280.80
	TOTAL LABOUR CHARGES		\$	4,252.00	\$	2,552.00
	GRAND TOTAL		\$	11,711.00	\$	3,832.80
	AH I COT					

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Yr Ref: SDN 7518 G

6768 9911 6841 1183 Nora.khai@premiumauto.com.sg Body & Paint Dept PA/OD/0581/2019/NK

02 July 2019

Norah Khai

from
Telephone +65Telefax +65EMail
Our department
Our Ref
Your Ref

Date

total pages

Dear Sir.

RE: INSURANCE CLAIM FOR SDN 7518 G, Audi Q5 SB 2.0 TFSI Qu.

With reference to the above-mentioned vehicle, no. SDN 7518 G claimant, Mr. Gan Fong Yin, please find the related document per attached.

- A copy of the Original invoice no. 85013984 S\$ 3,031.10.
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encl AIG - SDN 7518 G Premium Automobiles Pte Ltd Showroom 9 Leng Kee Road Singapore 159090

Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323

Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore 281 Alexandra Road Singapore 159938 Main Telephone 6836 2223 Main Telefax 5471 3733

Alexandra Service Centre 281 Alexandra Road Singapore 159938 Main Telephone 6388 2223 Main Telefax 6475 1023

Util Service Centre 55 Ubi Road 1 Singapore 408699 Main Telephone 6368 2323 Main Telefas 6841 1183

Customer Service Service Appointment 24-hour Breakdown Service 6366.2323 9826 1233 Email customer care@premiumauto.com.sg

INS TAX INVOICE

Page 1

10:32

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120 079120

Invoice: 85013984

Order: SDN7518G

Term : 30

Account: A0006

(7)

Date : 02/07/2019

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT

AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

Regn No: SDN7518G

Regn Date: 26/09/2017

Mileage: 46919

WIP No.: 52429

(V 35400)

Engine: DAX 012329

Dept: 0

Model: Q5 SPORT 2.0 TEST qu S tronic Chassis: WAUMINETYXH2045653

You have been assisted by :- UB-Siti Marsilla (137)

		Details	Qty	Unit Price	Amount
2	EXC	Insurance Excess/Liability	-1000.00	1,00	-1,000.00
S	HOWYDOE	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR, CHECK FUNCTION	360.00	1.00	360.00
	BODYWORK	TO DISMANTLE AND REPAIR REAR SUMPER. TO INSPECT RHS TAIL LAMP PANEL. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
5	BODYWORK	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH COVER	1500.00	1.00	1,500.00
5	BODYWORK	M;	192.00	1.00	192.00

Parts	1,280.80
Labour	2.552.00
Menus	0.00
Lubricant	0.00

A80A853817A GRU

A80A85381BA GRU

A80A945070

Х

X



Less 020%

Less 020%

Less 020%

Sub-Total 2,832.60 198.30 7% GST 3,031,10 **Grand Total**

487.00

627.00 487.00

389.60

501.60 389.60

1.00

1.00

1.00

Received by

TO CARRY OUT DIAGNOSTIC CHECK

(A) TAILLIGHT (SK) 10/

COVER

COVER

For & on behalf of Premium Automobiles Pte Ltd

Telefax

to AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Motor Claims Dept Yr Ref: SDN 7518 G Norah Khai 6768 9828 6841 1183 from Teleph

Telephone +65-Telefax +65-Mobile +65-

Body Repair Our o

Our department Your Claim Ref

Premium Automobiles Pte Ltd

Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres

Telephone (65) 6366 2323 Telefax (65) 6841 1183

55 Ubi Road 1 Singapore 408899

PA/OD/0581/2019/SM

Our Ref Date

Showroom

9 Leng Kee Road Singapore 159090

31 May 2019

I total pages

RE: CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model

Audi Q5 SPORT 2.0 TFSI QU

Vehicle Chassis No. :

WAUZZZFYXH2045653

Vehicle Regn No.

SDN 7518 G

Vehicle Mileage

46912 KM

Vehicle Owner

M'r. Gan Fong Yin

Certificate No

1700056950-01

Own Damage Excess :

\$ 1070.00 (Inclusive GST)

Accident Date

04/05/2019

Place

Block 131 Cashew Road Car Park

Repair Cost

\$ 3,031.10

WIP No.

52429

:

:

Repairer's Name

Premium Automobiles Pte Ltd

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time

*

Date

2 55pm

31/5/17

DISCHARGE VOUCHER- AIG - SDN 7518 C

Merimen e-Claims

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Authled	Status		
10 May 2019 Main 12:09			10 May 2019 10:44 Edit Adj Rpt	S\$3,832.80 Edit Estimates	S\$3,832.80 View Rpt		Pending for Survey Report Cancel Case		
	Main) R	eference	Claim De	stalls I	Documents	Show All		
CLAIM 5	UBFOLDER DET	TAILS				[Create	d by insurer]		
Insured		GAN	FONG YIN, ID: 56	977101G, Tel: +	5597459128	1			
Vehicle Reg. No.:		SDN	7518G	Date of Loss:		04/05/2019 19:00 - :59 [19 Months and 8 Days Fro Reg Date (Man Yr)]			
Claim Typ	oe:	OD /	/ 4502064104SG Polic		over Nate No.:	1700056	00056950-01 (Comprehensive)		
				Excess:		5\$1,000	5\$1,000.00		
Repairer:		Prem	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911						
Handling	Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 [Handled by Lim, Sheng Yang] ShengYang.Lim@aig.com						
Adjuster:			Auto Consultants F 22/05/2019]	te Ltd (HQ) - Tel:	6256-3561 [Han	dled by ADRIAN	LING] [Final Rpt		
Driver/Cu	stodian:	CHON	G YIN-YIN (47 / Fer	nale), NRIC: 571	297511, Tel: +659	97454168 Email: (GFONGYIN@GMAIL.COM		
ASSOCI	ATED MAIL REC	EIVED				View All	Compose Case Mail		
	G (10/05/2019): G (10/05/2019):		CESS D / 04/05/2019 /	Coverage & Exce	ss update				
8		Sent Control	500=2=m-2==			- 4			
ALL ASS	SOCIATED TASK	(S		V	ew Ail Search Ta	sks Create	New Task Complete		
Due Da	te Priority	Type Task	Group Subject	Handler A	ssigned By C	ompleted On	Created On Done?		

Merimen e-Claims Page 1 of 2

Claim Documents

*SDN7518G (4502064104SG) OD May 4 2019 7:35PM [GAN FONG YIN] Premium Automobiles Pte Ltd

	Upload Documents	Upload Photos Compose New Letter Upload Video Upload	Audio View	Use Viewer	
Vide	eo		1 per	page *	U
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnall	Print
1	06/05/19 10:16	Video - Accident [Linked Accident Report Documents]		Load MP4	
Pho	tos/Images		3 per	page *	2
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/05/19 12:12	General View	0	Load JPG	V
2	10/05/19 12:12	General View	0	Load JPG	W
3	10/05/19 12:12	General View	0	Load JPG	[0]
4	10/05/19 12:12	General View	0	Load JPG	V
5	10/05/19 12:12	General View	Ð	Load JPG	190
6	10/05/19 12:12	General View	0	Load JPG	(9)
7	10/05/19 12:12	General View	0	Load JPG	V
В	10/05/19 12:12	General View	0	Load JPG	(92)
9	10/05/19 12:12	General View	0	Load JPG	12
Doc	umentation		1 per	page •	[0]
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Print
1	10/05/19 12:09	Singapore Accident Statement	0	Load PDF	
2	10/05/19 12:10	Certificate of Insurance	0	Load PDF	
3	10/05/19 12:10	Driver's Driving License	0	Load PDF	
4	10/05/19 12:10	MARK ESTIMATE	0	Load PDF	
5	10/07/19 16:39	WORKSHOP INVOICE	0	Load PDF	
6	10/07/19 16:39	DISCHARGE VOUCHER	0	Load PDF	

Linked Accident Report Documents

	View Use Viewer		Use Viewer		
Vide	10		i per p	age *	100
No:	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnall	Prin
1	06/05/19 10:16	Video - Accident	0	Load MP4	
Ass	essment Reports		1 per s	age =	180
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Prin
1	06/05/19 10:18	Accident Statement	0	Load HTM	
Pho	tos/Images		3 per p	age =	[7]
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnall	Print
1	06/05/19 10:15	Accident Photo	0	Load 3PG	100
2	06/05/19 10:15	Accident Photo	0	Load 3PG	图
3	06/05/19 10:15	Driving License	0	Load JPG	区
4	06/05/19 10:15	Accident Photo	0	Load JPG	V
5	06/05/19 10:15	Accident Photo	0	Load 3PG	V
6	06/05/19 10:15	Accident Photo	0	Load JPG	逐
7	06/05/19 10:15	Accident Photo	0	Load JPG	12
8	06/05/19 10:15	Accident Photo	0	Load JPG	7
9	06/05/19 10:15	Accident Photo	0	Load JPG	团
10	06/05/19 10:15	Accident Photo	0	Load JPG	V
11	06/05/19 10:15	Accident Photo	0	Load JPG	V

Merimen e-Claims Page 2 of 2

12	06/05/19 10:15	Accident Photo	0	Load JPG	図
Doc	umentation		1 per p	age -	図
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Prin
1	06/05/19 10:02	Sketch Plan	0	Load JPG	(V)
2	06/05/19 10:02	Sketch Plan #2	0	Load JPG	V
3	06/05/19 10:03	UNDERTAKING LETTER	0	Load JPG	V
4	06/05/19 10:03	MOTOR ACCIDENT INTERVIEW FORM	0	Load JPG	V

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	*
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #08-16

Singapore 079120

Our File No:

Engine No:

Odometer:

CC3/AIG19008297/AVD3N2

Date:

10/07/2019

REFERENCE

Insured/Claimant:

GAN FONG YIN

Policy No:

1700056950-01

Date of Loss:

04/05/2019

Nature of Claim:

OD

Claim No:

4502064104SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SDN7518G

Make & Model:

AUDI Q5, 2.0 TFSI Quattro (A) 26/09/2017 (Man. Year: 2017)

DAX012329 Chassis No: WAUZZZFYXH2045653

45704 km

Reg. Date: Colour:

Blue

Engine Capacity:

1984 cc

Market Value/New Car Price:

\$\$185,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

235/55R19

Rear Tyre Size:

235/55R19

Front Tyre Size: Front Left Side: Front Right Side:

Michelin 6 mm Michelin 6 mm Rear Left Side: Rear Right Side:

Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIM Parts Miscellaneous Item		Repairer's 7,459.00 0.00	Adjuster's 1,280.80 0.00	6,178.20 0.00	Diff % 82.83
Labour Paintwork Labour		4,252.00 0.00	2,552.00	1,700.00	39.98
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	11,711.00	3,832.80	7,878.20	67.27
	- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
	(S\$)	10,711.00	2,832.80	7,878.20	73.55
	+ GST 7.00/7.00% (S\$)	749.77	198.30	551.47	73.55
	Nett Amount (S\$)	11,460.77	3,031.10	8,429.67	73.55

INSPECTION

Date of Assignment:

10/05/2019

Date Inspected:

09/05/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

3.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE. This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,571.00 FS	*-FS
2	1		*REAR BUMPER MID	Repair	1,077.00 FS	*-FS
3	1		*REAR BUMPER SPOILER	Not Necessary	754.00 FS	*-FS
4	1		*REAR BUMPER TOWING CAP LH	Not Necessary	43.00 FS	*-FS
5	1		*REAR BUMPER TOWING CAP RH	Not Necessary	26.00 FS	*-FS
6	1		*RAER BUMPER EXHAUST COVER TRIM-RH	Not Necessary	86.00 FS	*-FS
7	1		*REAR BUMPER CHROME TRIM RH	Not Necessary	213.00 FS	*-FS
В	1		*REAR BUMPER TAILLIGHT RH	Cracked	627.00 FS	*501.60 FS
9	1		*REAR BUMPER CARRIER	Not Necessary	831.00 FS	*-FS
10	1		*REAR BUMPER HOLDING STRAP	Not Necessary	151.00 FS	*-FS
11	1		*REAR BUMPER GUIDE SECTION RH	Not Necessary	76.00 FS	*-FS
12	1		*REAR BUMPER FOAM FILLER PIECE RH	Not Necessary	56.00 FS	*-FS
13	2		*REAR PARKING AID SENSOR	Not Necessary	462.00 FS	*-FS
14	1		*REAR PARKING AID SENSOR SEAL	Not Necessary	12.00 FS	*-FS
15	2		*REAR WHEEL ARCH COVER LH/RH	Necessary	974.00 FS	*779.20 FS
16	1		*SUNDRIES	Not Necessary	500.00 FS	*-FS
F=Fn	anchise	part. S=Spch	Vett.	A		
				Total Parts (S\$)	7,459.00	1,280.80

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items		7 × 2000001 h	
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER ASSY.TO INSPECT RHS TAIL LAMP PANEL.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, AND BOTH REAR WHEEL ARCH COVERS	New	2,500.00	1,500.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labor	ır Cost (S\$)	4,252.00	2,552.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >