

Date: 10.05.2019
Vehicle No: GBG7453M
Model: TOYOTA PROACE COMFORT 2.0M
Chassis: YARVFAHKHGZ068896 - 2016
Reg.Year: 2017

Third Party Insurer: LONPAC
Third Party Veh No: SDF137K
Date of Accident: 08.05.2019

*Not wither
Resurvey 84 point 5 day*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>By</i> \$849.70
2	REAR TAILGATE EMBLEM 'TOYOTA'	1		<i>Ne</i> \$62.50
3	REAR TAILGATE EMBLEM 'PROACE'	1		<i>Ne</i> \$58.40
4	REAR TAILGATE EMBLEM LOGO	1		<i>Ne</i> \$65.00
5	REAR BUMPER	1		<i>CM</i> \$528.50
6	REAR BUMPER REFLECTOR LH	1		<i>CM</i> \$125.60
7	REAR END PANEL	1		REPAIR
SUB TOTAL				\$1,689.70
LESS 25%				-\$422.43
PARTS TOTAL				\$1,267.28

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Win-Lose" basis
• No illegal modification(s) is allowed
• Supplier's warranty item(s) must be provided and is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer

NO.	SPECIAL NETT	Signature:	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE STICKER '70 km/h'	Date:	1		<i>Ne</i> \$15.00
2	REAR TAILGATE STICKER '8 PAX'		1		<i>Ne</i> \$15.00
3	REAR TAILGATE WINDSCREEN SEALANT		1		<i>Ne</i> \$100.00
4	REAR BUMPER CLIPS		1 SET		<i>Ne</i> \$60.00
5	REAR END PANEL JOINT SEALANT		1		\$60.00
S/N TOTAL					\$250.00

LABOUR CHARGES:

LABOUR CHARGES FOR REMOVE, REPLACE & READJUST REAR ACCIDENT AREAS & ETC.
BACK TO ORIGINAL CONDITIONS

\$600.00 *500*

LABOUR CHARGES FOR SPRAY PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS
AT REAR ACCIDENT AREAS & ETC

\$700.00 *600*

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER TRIM PART & ETC.
BACK TO ORIGINAL CONDITIONS

\$100.00 *60*

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE WINDSCREEN TO
PERFORM WATER LEAK TEST

\$150.00 *120*

LABOUR TOTAL \$1,550.00

PEI TING TOTAL \$3,067.28

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

