

ESTIMATE TO REPAIR

VEHICLE NO. : GBC 2955 S
 MAKE : MITSUBISHI
 MODEL : FB70BB1SRDEA
 YEAR : 2011
 CHASSIS NO : FB70BBA20428

SURVEYOR NAME :
 DATE OF SURVEY :
 TIME OF SURVEY :

DATE : 10-May-19
 DATE OF ACCIDENT : 20-Apr-19
 THIRD PARTY REF : SLN 1768 X / AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper				\$ 795.48
1 pc	N/S Front Side Lamp				\$ 222.65
1 pc	N/S Front Signal Lamp				\$ 266.36
1 pc	N/S Headlamp				\$ 501.45
					\$ 1,785.94
	Less 20%				\$ 357.19
					\$ 1,428.75
	N/S Front Door Lettering	S.Nett			\$ 20.00
	To putty and spray painting				\$ 400.00
	To check front wiring and focus headlights				\$ 30.00
	Labour Charges				\$ 300.00
TG/RA-	Total				\$ 2,178.75

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd