

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: DMPC1600347H/JG

Date: 27th May 2019

Our Ref: CS1/ICS19008423/Ksd3s2

M/s ECICS Ltd

10 Eunos Road 8 Singapore Post Centre #09-04A Singapore 408600

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SHC 5103T INSURED VEHICLE: SJY 3542H ACCIDENT DATE: 10/10/2016

We thank you for your instruction on 10/05/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHC 5103T from M/s Appraisal VP Pte Ltd.
- b) Singapore Accident Statement of Vehicles SHC 5103T and SJY 3542H.
- c) Colour damaged vehicle photographs of SHC 5103T.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SHC 5103T

Make & Model

: Renault Latitude

Year of Registration

: 2013

Chassis Number

: VF1ABL15AUC276149

Engine Capacity

: 1995 cc

- We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.