

PLATINUM AUTO SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 #03-36 PREMIER @KAKI BUKIT SINGAPORE 415875

TEL: (65) 97735487

FAX: (65) 69262686

Company Registration No: 201901615G

Date: 15-05-2019

Name: FU CHOON LIN

Address: Blk 258A Punggol Field, #10-17, Singapore 821258

Model: Kia Cerato Forte K3

Accident Date: 05-05-2019

Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 Days

Estimated repair for vehicle no. SLN 7301 U

| Serial No. | Descriptions | Amount(\$\$) |
|------------|--------------|--------------|
|------------|--------------|--------------|

Lists Items

| | | |
|---|--------------------------------------|-----------|
| 1 | Front Bumper <i>x repair</i> | \$ 735.00 |
| 2 | Front Bumper Retainer X2 <i>x NN</i> | \$ 40.00 |
| 3 | Bumper Clips X 14 | \$42.00 |

\$817.00

Labour

| | | |
|---|-------------------------|----------------------|
| 1 | Labour & Spray Painting | \$1000.00 <i>600</i> |
| 1 | Wheel Alignment | \$50.00 <i>x NN</i> |

\$1050.00

Grand – Total: \$1867.00

Dollar: One Thousand Eight Hundred Sixty Seven Only