



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 17/9/2019

Survey details

Date of loss	4/5/2019
Date of appointment	13/5/2019
Date of survey	13/5/2019
Location of survey	EUROSPORTS AUTO PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SMA 838R
Make and Model	LAMBORGHINI HURACAN LP580-2
Date of registration	27/4/2018
Excess	\$18,000
Market Value	\$950,000.00
Parf Rebate	\$284,472.00
Nett Loss	\$665,528.00

Repair details

Initial Estimate	\$143,221.38 (incl. supplementary \$39,582.38)
------------------	--

Proposed/Revised repair cost:

Revised Estimate Amount	\$122,354.88
"Check items (Estimated)	
Labour	\$14,900.00
Total Repair (Estimated)	\$137,254.88 (incl.supplementary \$39,582.38)
Lump Sum (Estimated)	

Number of days of repair	12 DAYS (est)
--------------------------	---------------

Remarks:

The vehicle sustained damages at the front portion and interior.

Damages Consistent
Repair Cost Economical

Repairer is aware that late submitted of supplementary due to parts and prices from the factory in Italy.