

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, SINGAPORE 159096

TEL : (65) 6565 5995 FAX : (65) 6567 5515

Vehicle / Model :

SMA838R

Lamborghini Huracan

CI:

AXA Insurance

Policy:

VPX/P2115122

Accident Date:

May 4th.-2019

*Steve (LKK)**8322 8813**00 - Not Author**12 days***10-04-19***EXTRA - \$18,000**P/P**Reg bel Jy***Own Damage Claim**

			Qty	List Price	Total
1	4T0807109C	STORAGE FRAME FRNT / BT	1	\$ 1,604.00	\$ 1,604.00
2	4T0821021D	WING LF / DD	1	\$ 6,552.00	\$ 6,552.00
3	4T0821022D	WING RH / DD	1	\$ 6,552.00	\$ 6,552.00
4	4T0941004G	HEADLIGHT RH / BR	1	\$ 10,000.00	\$ 10,000.00
5	4T0941003G	HEADLIGHT LF / CUT	1	\$ 10,000.00	\$ 10,000.00
6	4T0805028K	FRONT END / ?	1	\$ 12,248.00	\$ 12,248.00
7	4T0807103G	BUMPER WITH PARKING SENSOR / BR	1	\$ 10,416.00	\$ 10,416.00
8	4T0807253	FRONT SPOILER / MIS	1	\$ 592.00	\$ 592.00
9	4T0807254	FRONT SPOILER RIGHT / ?	1	\$ 592.00	\$ 592.00
10	4T0853745	LAMBORGHINI EMBLEM / CUT	1	\$ 728.00	\$ 728.00
11	4T0823021C	BONNET FRNT / DD	1	\$ 10,296.00	\$ 10,296.00
12	4T0823301B	HINGE LF / BT	1	\$ 336.00	\$ 336.00
13	4T0823302B	HINGE RH / BT	1	\$ 336.00	\$ 336.00
14	4T0823351B	ARM / ?	1	\$ 75.00	\$ 75.00
15	4T0823359	GAS FILLED STRUT / ?	1	\$ 61.00	\$ 61.00
16	4T0805669C	ATTACHMENT BARS LF / ?	1	\$ 97.00	\$ 97.00
17	4T0805670C	ATTACHMENT BARS RH / ?	1	\$ 95.00	\$ 95.00
18	4T0819967	ARM LF / ?	1	\$ 85.00	\$ 85.00
19	4T0819968	ARM RH / ?	1	\$ 85.00	\$ 85.00
20	1K1823509E	BONNET LOCK LOWER PART / BT	1	\$ 147.00	\$ 147.00
21	1Q0823480	CATCH HOOK FRNT / BT	1	\$ 52.00	\$ 52.00
22	WHT001308	CAP NUT , SELF LOCKING / NEC	1	\$ 55.00	\$ 55.00
23	4T2819426D	COVER (centre) BR /	1	\$ 399.00	\$ 399.00
24	4T0821170D	COVER RH / BR	1	\$ 503.00	\$ 503.00
25	4T0821169D	COVER LH / BR	1	\$ 503.00	\$ 503.00
26	4T0821171C	WHEEL HOUSING LINER LH / ?	1	\$ 497.00	\$ 497.00
27	4T0821172C	WHEEL HOUSING LINER RH / ?	1	\$ 497.00	\$ 497.00
28	4T0853745	LAMBORGHINI EMBLEM FRONT X Repack	1	\$ 728.00	\$ 728.00
29	4T0863405D	LUGGAGE COMPARTMENT TRIM SEAL / CRU	1	\$ 4,060.00	\$ 4,060.00
30	4T0823727B	SEAL (Rubber) CRU	1	\$ 207.00	\$ 207.00
31	4T0880201A6PS	AIRBAG FOR STEERING (RH) / BR	1	\$ 900.00	\$ 900.00
32	4G8880204D	AIRBAG UNIT (LH) / BR	1	\$ 2,565.00	\$ 2,565.00
33	4S0121252B	ADDITIONAL COOLER FOR COOLANT - HEC	2	\$ 647.00	\$ 1,294.00
		(A/C Condenser) LH, RH BT /			

10/4/19

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, SINGAPORE 159096

TEL : (65) 6565 5995 FAX : (65) 6567 5515



Vehicle / Model :

SMA838R**10-04-19**

Lamborghini Huracan

CI:

AXA Insurance

Policy:

VPX/P2115122

Accident Date:

May 4th.-2019

Own Damage Claim

34	4T0807157C	AIR GUIDE LH ?	1	\$ 130.00	\$ 130.00
35	4T0807158C	AIR GUIDE RH ?	1	\$ 120.00	\$ 120.00
36	4S0121254B	COOLER FOR COOLANT (center) ? 00	1	\$ 716.00	\$ 716.00
37	4T0121334B	AIR GUIDE CENTER - BR	1	\$ 128.00	\$ 128.00
38	4T0121334C	AIR GUIDE REAR CENTER ?	1	\$ 188.00	\$ 188.00
39		Rivets and fasteners, Glue and Sealers supply	1	\$ 700.00	\$ 700.00

PARTS TOTAL**40****\$ 85,139.00****Labor Charges**

Dismantle, Re Fitting and Repair/knocking (10 Days)

9600 \$ 12,000.00

Respray front bumper and fender and spoiler

4800 \$ 6,500.00

Subtotal for Labor**\$ 18,500.00****GST Total****\$ 7,254.73****Total****\$ 110,893.73**


- 1 This is only an estimate, should any additional job be found necessary in the course of work, extra material and labour, cost will be charged accordingly for which you will be informed prior to action taken.
- 2 All materials prices quoted are subject to change without notification
- 3 All repairs are subject to spare parts availability
- 4 Quotation valid for one month from date of issue.

Lamborghini Singapore**Workshop Contact:**

Richard Harjanto

Service Advisor

97999593

 10/4/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: