

Page 2/2

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: MSIG INSURANCE (SINGAPORE) PTE LTD	Document No.	: SQT19002572	Page	1
	16 RAFFLES QUAY	Date	: 11. Jun 2019		
	HONG LEONG BUILDING	Customer No.	: WZM003		
	SINGAPORE 048581	Svc Advisor	: LIM CHOU SIONG		
Registration No	: SJQ4934X	Engine No	: L15A71806685		
Chassis No	: MRHGM28709P020344	Date Time	: 11. Jun 2019 6:16:11 PM		
Model	: CITY 1.5 SV AUTO	Surveyor Name	:		
Owner's Name	: KASTURIBHAI D/O RAMIAH	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 10/5/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: 72766)						
	OWNER: KASTURIBHAI D/O RAMIAH						
	OWNER INSURER: NTUC INCOME INSURANCE						
	ACC DATE: 10/05/2019						
	SURVEYED BY: LKK MARCUS						
	DATE: 13/5/19						
	REF NO:						
	TP INSURER: MSIG INSURANCE						
	TP VEH: SLS5356Z						
	SUPPLEMENTARY LABOUR & PARTS						
75701-TM0-000	EMBLEM H	1	17.80	25	13.35	0.93	14.28
				Sum Item	13.35	0.93	14.28

Survey By	_____						
Date & Time	_____						
Excess	_____						
Status	_____						
Signature	_____						

	Total Amount	13.35	0.93	14.28
	Total (Inclusive of GST)			14.28

Printed on 11/6/2019 6:21:36 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.60 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.