



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201905-000196(00)

CHINA TAIPING INSURANCE (S) PTE LTD

NO. 3
ANSON RD
SPRINGLEAF TOWER
SINGAPORE 079909

Contact : 96785750

Fax No. : 62247175

Date : 10/05/2019
Vehicle No. : SKL8208Y
Make/Model : MERCEDES BENZ S 300L (HID SR DRL)

Mileage (km) : 0
Chassis No. : WDD2211542A527997
Accident Date : 08/05/2019 00:00:00
Claim No. : SJV2522M
Reference : SKL8208Y
Policy No. : 2100343882-05

*Not Authorized
Resurvey After Repair
11 Sep @? 2 days*

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Rear bumper	1.0	2,520.00	2,520.00 ✓
2	Rear bumper lower	1.0	580.00	580.00 ✓
3	Rear bumper sponge	1.0	245.00	245.00 ✓
4	Rear bumper reinforcement	1.0	670.00	670.00 ✓
5	Rear Bumper clips	12.0	4.50	54.00 ✓
6	LH exhaust dip	1.0	115.00	115.00 ✓
7	Parking sensor	4.0	270.00	1,080.00 X
List Total :				5,264.00
10% Discount S\$				526.40
				4,737.60
LABOUR :				
	* To check and re-wiring of parking sensor	1.0	45.00	45.00 ✓
	-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	450.00	450.00 280
	- Spray painting on affected & replace parts	1.0	650.00	650.00 300
				1,145.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

E. & O.E.

Total S\$:	5,882.60
GST 7% S\$:	411.78
Amount Due S\$:	6,294.38
Acknowledged by Repairer	
Signature:	
Date:	

MA
for CITY AUTO PTE LTD