



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19008533/Kbs3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 11-09-2020



ATTN:KIAN CHUAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJR 3833E	Veh. Inspected	SKT 8493Y
Policy No.	VPA/P2228114	Coverage (\$)	0.00
Claim No.	S9M01MK5	Excess (\$)	0.00
Assign From		Assign Date	14/05/2019

2. Vehicle Particulars & Condition

Make & Model	SUBARU LEGACY (A)	c.c	2498
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JF1BN9KC2FG002812	Colour	METALLIC SILVER
Odometer	83725	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/45 R18	DUNLOP	3 mm
L/H Front Tyre	235/45 R18	DUNLOP	3 mm
R/H Rear Tyre	235/45 R18	DUNLOP	4 mm
L/H Rear Tyre	235/45 R18	DUNLOP	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	06/05/2019	Inspection Date	28/05/2019
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------