INS. CASE OWNE	cc 4/ 68/ 1900 8598	Jass DAC	
Surveyor:	DOI: ASSIGNMENT	Date/Time:	1915/19
		Registered in Merimen.	
Pre-assign / CCU	hasbys		
Insured Vehicle N	O. Claim No.	2	
Name of Insured	C-K. loh westruction PL Policy No.		
Insured Tel No.	HP: Make/Mode		
Excess Sec II :SS	Elcha		
Is driver the owner		dent :	8 7 0
If NO, Driver Na	(O)	^	
Driver Tel	No.: (V/L: YES/NO-) Insured Liabil	ORT: V63 / NO; TP GIA R ity: % Final	EPORT: (ES/NO ? Yes/No
C18D 635	17 → GBE 95G		
INSRS: WSP: Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS:  INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:
Date/ Time			
	G80 6352A 1 NO (WELLO > 3589) NY - 00/1-10/12/1	STAGE	DATE/PIC
(i)	45,668 ]	Non-Reporting ltr (1st):	
2381/19	- 01's incharge not and Email Loi atthe ms cand	Non-Reporting ltr (2nd):	
3/18/19	The bass in the report.	Notification ltr (if non-picku	
74011	runding maindall approva	Call OI:	COL
40	mandate approved up to \$6929.00.	After call ltr to OI:  Documentation Check List	23/11/9 : Handler Typist
0/0	offer \$0895.50' (Pending acceptance)	Notification ltr (if non-picku	
9/9	Admin to close.	After call ltr to OI;	
	Holling to chose.	Authorisation To Act: Release Voucher:	
		Final Repair Bill:	1
	A C 000 1 -	Car Rental Invoice:	X
	# 3,000 / 8 DAY	Towing Invoice	7
n	3 A A A BA	LTA/GIA:	
4	WI amount diff is cettlaunt amount.	Medical Bill:	
	(124 The)	PIR: Mandate/Reject Instruction	
	000	LOD	
DDET DAINA DV. 4 DUTCE	D. CO.	Payment Breakdown Form	1;
PRELIMINARY ADVICE	Date/Time; Sent By:	Post-Repair Photos:	X
FINALIZATION	Date/Time: Confirm with:	Others:	A
Repair Cost: 48	S\$ 5800 - 00 ( & days) Reduction: \$17,500.74% 76	Confirm by: Hwe ?	Call
FINAL SETTLEMENT	Date/Time to MIR /2.3 of Confirm with	Email Call	Can
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.: NIL	If NO or B 28, Ass. Lia:	
Repair Cost: (WGSI) Loss of Rental (LOR);	S\$ (206.00 S\$ (days)	or more out par	
Loss of Use (LOU):	ss 600.00 (s 600 x (1 days) 100 x 11 > 1100	on to TP & Oth	er vehrule.
Loss of Income (LOI):	S\$ (\$ x days)	aniew.	2 2
LOR only LOU only		15/13	7/7
GIA/LTA Search Medical:	22 30.00		1
Disbursement;	S\$ - (c.g. Tow/ Independent )	1) Claim status: Normal/R	eject/Private Settle
Legal Cost	SS , -	2) Report Format: 3) Survey fee:	My way -
Total:	SS 6895.00 Global Sum SS:	,, our roy 100,	1404
FINAL PAYMENT	Date/Time: Confirm with:	Email Call	SHERIUS AND SHEET
Payce 1;		Teun Pte Lto	
Payee 2: (Strike if N.A.) Payee 3: (Strike if N.A.)	S\$ Name 2:		an and the second
ayer at tourse it N.A.)	S\$ Name 3:	1/2 m and mark thomas a second	

\* 8 repair days 2 PRS

Date/Time. File Pass to?	: Preli. Report	Days Of Repair:		
1)	: Final Report	Resurvey No. of Trip:	Survey Fee:	
Date/Time, File Return to?			Transportation:	
2)	93	Add Fee: : Site Insp (\$	)S +PSSI	
		<b>—</b>		

Interview (\$ Report Format: Tech Invs (\$ ) Others Lump Sum / LB 1: 13 Weekend IS

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Owner ID: Vehicle Details Vehicle No.: Vehicle to be Exported:	Company 1609N GBD6352A No
Vehicle Details Vehicle No.: Vehicle to be Exported:	GBD6352A
Vehicle to be Exported:	
	No
Intended Development Pater	
Intended Deregistration Date:	15 May 2019
Vehicle Make:	NISSAN
Vehicle Model:	URVAN
Primary Colour:	Silver
Secondary Colour:	Grey
Manufacturing Year:	2004
Engine No.:	ZD30045760
Chassis No.:	JN1MG4E25Z0712478
Maximum Power Output:	2)
Open Market Value:	\$22,536.00
Original Registration Date:	19 Jan 2005
First Registration Date:	19 Jan 2005
Transfer Count:	2
Actual ARF Paid: Intended PARF Rebate Details	\$1,127.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	•
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	18 Jan 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$29,933.00
COE Rebate Amount:	\$4,121.00
Total Rebate Amount: Message	\$4,121.00
Please note that all future COE renewals for this vehicle can only be vehicle.	for a 5-year period, subject to the statutory lifespan (if applicable) of the

The information contained herein is correct as at 15 May 2019

OK

#### Estimate Report

# Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12 Singapore 737856

Tel: 62562281 Fax: Email: YTMG

#### INSURER: EQ INSURANCE COMPANY LTD

PARTICULARS OF	CLAIM
----------------	-------

Claim Type:

TP 5070638368-04 Ref. No:

YTMG/TP/1905/004

Policy No:

GBD6352A

Date of Loss: Driveable?

06/05/2019

Vehicle Reg. No.:

Driver Age: Any Injuries?

Third Party Vehicle No.:

GZ565S, GBE515G

POWER SOLUTION

Contact No:

62590423

Insured/Claimant:

Driver:

CHIN KENG HANG

ELECTRICAL

ENGINEERING PTE LTD

Make/Model:

Vehicle Colour:

Nissan, Urvan

Vehicle Reg. Date:

19/01/2005

GREY

Engine Number:

ZD30045760

Chassis No: Total Loss?

JN1MG4E25Z0712478 NO

Odometer:

Est. Duration of Repair(Day)

Description of Accident/loss

Remarks:

Present Location:

Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COLLISION - MAJOR/MINOR RD

	GST 7.00%(S\$): Nett Amount(S\$):	1,631.05 <b>24,931.79</b>
	Gross Total(S\$):	23,300.74
Towing	V <sub>2</sub> -V <sub>2</sub> -V <sub>3</sub>	0.00
Paintwork Labour		2,185.00
Labour		3,420.00
Miscellaneous Items		775.00
Parts		16,920.74
COST OF CLAIMS		Amount

This claim is handled by: Lai Yee Meng

# REPAIR DETAILS

	ates On Parts	Destinutes	D-4-		0/ 5:	
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER DEF /	0.00	622.80	-30.00	435.96
2	1	FRONT BUMPER BRACKET LH	0.00	104.70	-10.00	94.23
3	1	FRONT BUMPER BRACKET RH ANX	0.00	104.70	-10.00	94.23
4	1	FRONT BUMPER FOG LAMP LH WAS	0.00	258.00	-10.00	232.20
5	1	FRONT BUMPER FOG LAMP GARNISH LH MIS	0.00	78.60	-10.00	70.74
6	1	FRONT BUMPER REINFORCEMENT 31/	0.00	451.20	-30.00	315.84
7	1	FRONT BUMPER LOWER GRILLE DEF	0.00	270.00	-10.00	243.00
8	1	FRONT HEADLAMP LH CKY	0.00	395.50	-10.00	355.95
9	1	FRONT HEADLAMP RH	0.00	395.50	-10.00	355.95
10	1	FRONT SIDE LAMP LH CRA	0.00	126.10	-10.00	113.49
11	1	FRONT SIDE LAMP RH NY	0.00	126.10	-10.00	113.49
12	1	FRONT GRILLE ANX	0.00			
13	1	FRONT GRILLE CHROME MOULDING *** *		430.90	-30.00	301.63
14	1	THORT CRIEEL CHROME MODERNO	0.00	0.00	-10.00	0.00
15	1	FRONT CORNER PANEL LH BUC	0.00	0.00	0.00	0.00
16	1	- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0.00	578.00	-10.00	520.20
17	1		0.00	761.10	-30.00	532.77
	1	[1] :[1] [1] [2] [2] [2] [2] [2] [2] [2] [2] [2] [2	0.00	470.00	-10.00	423.00
18	1	RADIATOR FAN MOTOR 1 nny	0.00	380.00	-10.00	342.00
19	1	RADIATOR FAN BLADE	0.00	155.00	-10.00	139.50
20	2	RADIATOR BRACKET	0.00	110.00	-10.00	99.00
21	1	FRONT DOOR LH BUC	0.00	1,116.40	-30.00	781.48
22	2	FRONT DOOR HINGES LH 87/	0.00	136.00	-10.00	122.40
23	1	FRONT DOOR PILLAR LH	0.00	2,236.50	-30.00	1,565.55
24	1	FRONT DOOR INNER BOARD LH DEF	0.00	755.70	-30.00	528.99
25	1	FRONT DOOR GLASS REGULATOR LH		203.60	-10.00	183.24
26	1	FRONT DOOR GLASS REGULATOR MOTOR 1M	W <sub>0.00</sub>	576.90	-10.00	519.21
27	1	FRONT DOOR LOCK LH Jam /	0.00	310.20	-10.00	279.18
28	1	FRONT DOOR LOCK CATCH LH	0.00	67.60	-10.00	60.84
29	1	FRONT DOOR RUBBER LH 3 MAX	0.00	130.00	-10.00	117.00
30	1		0.00	716.90	-30.00	501.83
31	1	FRONT DOOR GLASS LH CRA/				
	1		0.00	122.00	-10.00	109.80
32	1		0.00	145.00	-10.00	130.50
33			0.00	398.00	-10.00	358.20
34	1	FRONT DOOR STEP GARNISH LH DEF/	0.00	110.00	-10.00	99.00
35	1	FRONT CHASSIS SIDE MEMBER LH BUC /	0.00	581.70	-10.00	523.53
36	1	FRONT CHASSIS MEMBER LH	0.00	2,200.00	-30.00	1,540.00
37	1	FRONT WASHER TANK BUC /	0.00	257.80	-10.00	232.02
38	1	FRONT WASHER TANK MOTOR CRA /	0.00	155.00	-10.00	139.50
39	1	FRONT FENDER LH REPAIR X	0.00	1,800.00	-30.00	1,260.00
40	1	FRONT WHEEL ARCH INNER PROTECTOR 3	0.00	135.10	-10.00	121.59
41	1	FRONT FENDER INNER SHIELD LH MAX	0.00	247.50	-10.00	222.75
42	1	FRONT UPPER ARM LH & nn x	0.00	382.70	-10.00	344.43
43	1	FRONT LOWER ARM LH & 122×	0.00	271.40	-10.00	244.26
44	i	FRONT KNUCKLE ARM LH 9 nnx	0.00	342.40	-10.00	308.16
45	1	SLIDING DOOR LH REPAIR X	0.00	0.00	0.00	0.00
46	1	REAR FENDER LH Repair X	0.00	1,896.70	-30.00	1,327.69
47	1	REAR BUMPER NA X	0.00	683.60	-30.00	478.52
1.4	1	REAR BUMPER BRACKET LH NEX	0.00	42.10	-10.00	37.89

Total Parts (S\$) 16,920.74

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT DOOR INNER BOARD CLIPS ~~/	0.00	45.00	0.00	45/00 30
2	1	FRONT WHEEL RIM LH Repair *	0.00	550.00	0.00	550.00
3	1	FRONT TYRE (DEPRECIATION) LH ^^ ×	0.00	180.00	0.00	180.00
		Sub To	otal (S\$)			775.00

Estim	ates On La	abour					
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc	
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	70.00	70.00	0.00	78.00	40
2	1	To Dismantle and Refit Front Undercarriage.	180.00	180.00	0.00	180.00	(00)
3 4	1	To Do Up Interior Cleaning and Chemical Wash.	200.00	200.00	0.00	200.00	
4	1	To Dismantle & Refit Front Dashboard & related wire harness & related parts.	350.00	350.00	0.00	350.00	
5	1	To Pressure Test Air Con Condenser and Radiator For Leakage.	120.00	120.00	0.00	120.00	45
6	1	To Transfer Sliding Door.	80.00	80.00	0.00	80.00	K
7	1	To Transfer Door.	60.00	60.00	0.00	60/00	
8	1	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	180.00	180.00	0.00	180.00	×
9	1	To Conduct Computer Wheel Alignment.	80.00	80.00	0.00	80/00	760
10	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	2,100.00	2,100.00	0.00	2,100.00	140

Gross Labour Cost (S\$)	3,420.00
다시아이들은 발견에 위치를 그렇게 되었다.	

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc	
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	0.00	60.00	4D
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	4 <b>5</b> .00	30
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	80.00	0.00	80/00	40
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	2,000.00	2,000.00	0.00	2,0 <b>¢</b> 0.00	1300

Gross Labour Cost (S\$)

2,185.00 Total-\$7300

### < END OF ESTIMATES >

LFK Auto Consu hts ne the approximation following

- To resurvey before after scory painting.
- To display conaged partis, during residues
- Parts prices in a subject to contimation.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s must be resurveyed and is subject to final approval from Insurance Company)

Acknowledged by Repairer

Signature:

Date:

Hwee J.L - LKK
14/5/19
L/S 8days.
23300.74\*

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

DM19HO01247/JT

Our ref:

CC4/EQI19008598/Jja3

Date:

16/05/2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

#### PRELIMINARY ADVICE OF VEHICLE NO.

GBD 6352A

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14/05/19 at the premises of M/s Yew Tee Automobile Tech Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	23,300.74
Revised Estimate Amount	: S\$	5,800.00
"Check" Items Amount	: S\$	(8)
Total (Including Check Items)	: S\$	5,800.00
Market Value	: S\$	10,000.00
LTA Reimbursement Value	: S\$	4,121.00
Nett Value	: S\$	5,879.00

Description of Damage:

The vehicle sustained damages at the

Front N/S portion and N/S portion

front

Comments/Present Status:

Damages Consistent

Estimated normal period for repairs:

8.0 days

Yours faithfully,

ONG HWEE JIE

Licensed Appraiser

## Nivitha (LKK Auto)

From:

Janet Tan <janet.tan@eginsurance.com.sg>

Sent:

Tuesday, 14 May 2019 12:21 PM

To:

assignments

Cc:

Admin A

Subject:

RE: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against

GZ565S (EQ) on 06.05.2019

Attachments:

SAS2596506.pdf; GBD6352A\_06052019.pdf; GBD6352A Estimate.pdf

Dear all,

Please arrange to the PRS.

Liability is cleared. Proceed to direct settle if possible.

persone Ms. feir

Regards,


Janet Tan

Senior Executive | Claims



#### **EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190 www.eqinsurance.com.sg



**®**——

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: YT(MG) [mailto:info@yewteegroup.com]

Sent: Tuesday, May 14, 2019 11:45 AM

To: Janet Tan < janet.tan@eqinsurance.com.sg>

Cc: YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>

Subject: RE: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Hi Janet,

We choose 6) LKK Auto Consultants Pte Ltd

Location at 39 Woodlands Close #01-12 Mega@Woodlands S(737856).

Please let us have the officer in charge and liability too.

Thank You 😉

Best Regards



#### Yew Tee Automobile Tech Pte Ltd

Branch Office: 39 Woodlands Close, #01-12 Mega@Woodlands Singapore 737856 DID: 6256 2081

Email: info@yewteegroup.com

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office: Synergy@KB, 25 Kaki Bukit Road Unit No #01-60/61 Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg

please consider the environment before printing this email.

Notice: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Janet Tan < janet.tan@eqinsurance.com.sg>

Sent: Tuesday, 14 May 2019 11:14 AM To: YT(MG) < info@yewteegroup.com>

Cc: YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>

Subject: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

# Without Prejudice Save As To Costs

Dear Sky

For pre repair survey request, please email to eqiprs@eqinsurance.com.sg

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please <u>revert within 2 working days</u> if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd	2) Automobile Inspection Services Pte Ltd
Tel: 6255 0808	Tel: 6286 0155
Fax: 6849 9155	Fax: 6284 1539
	Contact Person: Sophia
LBS Automotive Appraisal Pte Ltd	4) Priority Services
L.B.S. Auto Consultants Pte Ltd	Tel: 62934822
Tel: 6281 6690 / 62832866	Fax: 62963283
Fax: 6281 8748	<b>Contact Person: Sharon</b>
Contact Person: Amy/ Grace	
RT Appraisal Pte Ltd	6) LKK Auto Consultants Pte Ltd
Tel: 67486076	Tel: 6256-3561
Fax: 67480361	Fax: 6741-4108
Contact Person: Elson/Elgene	
Kelvin Automotive Appraising Services	8) Automotive Appraiser & Surveying
Tel: 81825263	Services
Fax: 67461148	Tel: 96623655
Contact Person: Kelvin	Fax: 67655662
	Contact Person: Mr Chee
JP Knights Pte Ltd	10) Appraisals Associates Pte Ltd
Tel: 63450068	Tel: 67472822
Fax: 63445328	Fax: 67470070
Infiniti Appraisal Service	
Tel: 96684818/90099001	
Fax: 64587432	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Janet Tan
Senior Executive | Claims



## **EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190 www.eqinsurance.com.sg





Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: YT(MG) [mailto:info@yewteegroup.com]

Sent: Tuesday, May 14, 2019 10:50 AM To: EQI PRS < EQIPRS@eqinsurance.com.sg>

Cc: Janet Tan < janet.tan@eqinsurance.com.sg >; Tan Wei Yin < weiyin.tan@eqinsurance.com.sg >; Elaine Cheong <elaine.cheong@eqinsurance.com.sg>; YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>

Subject: RE: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

#### REMINDER

Hi Motor Claims Dept,

Refer to email below, please let us have the list of surveyor for choose to conduct the pre-repair survey.

Thank You (3)

Best Regards

Ms Lai Yee Meng



#### Yew Tee Automobile Tech Pte Ltd

Branch Office: 39 Woodlands Close, #01-12 Mega@Woodlands Singapore 737856 DID: 6256 2081

Email: info@yewteegroup.com

HQ:

Blk 6 Woodlands Road 399F Yew Tee Ind. Est Singapore 678006 DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office: Synergy@KB, 25 Kaki Bukit Road Unit No #01-60/61 Singapore 417800 DID: 6702 3113 Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(MG) < info@yewteegroup.com > Sent: Monday, 13 May 2019 3:41 PM

To: eqiprs@eqinsurance.com.sg

Cc: 'YTKB' <utauto2@singnet.com.sg>; 'YTHQ' <utauto@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>; YTKB

<utauto2@singnet.com.sg>

Subject: RE: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Hi Motor Dept,

Resent to remind.

Thanks.

Best Regards

DRY TON

Mobile: 9747 1475

Website: <u>www.yewteegroup.com</u> Email: <u>info@yewteegroup.com</u>

Like Us On Facebook

Director of

-YEW TEE AUTOMOBILE TECH PTE LTD



WEST HQ Office:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est Singapore 678006 DID: 6762 2081 (3 Lines)

Fax: 6760 4895

Email: utauto@singnet.com.sg

EAST Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4 Unit No #01-60/61

Singapore 417800

DID: 6702 3113 (3 Lines) Fax: 6702 3773

Email: utauto2@singnet.com.sg

NORTH Branch Office:

Mega@Woodlands

39 Woodlands Close #01-12 Singapore 737856

DID: 6256 2081 (3 Lines)

Fax: 6256 2533

Email: info@yewteegroup.com

🗲 please consider the environment before printing this email

Notice: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(MG) [mailto:info@yewteegroup.com]

Sent: Saturday, 11 May, 2019 11:24 AM

To: eqiprs@eqinsurance.com.sg

Cc: YTKB; YTHQ

Subject: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Hi Motor Claims,

Attached report and estimate.

Kindly arrange PRI at 39 Woodlands Close, #01-12 Mega @ Woodlands S(737856).

Please let us have the list of surveyor for choose to conduct the pre-repair survey.

Kindly let us have the liability and officer-in-charge too.

Thank You 3

Best Regards

Ms Lai Yee Meng



#### Yew Tee Automobile Tech Pte Ltd

Branch Office: 39 Woodlands Close, #01-12 Mega@Woodlands Singapore 737856

DID: 6256 2081

Email: info@yewteegroup.com

HQ:

Blk 6 Woodlands Road 399F Yew Tee Ind. Est Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office: Synergy@KB, 25 Kaki Bukit Road Unit No #01-60/61 Singapore 417800 DID: 6702 3113

Email: utauto2@singnet.com.sg

please consider the environment before printing this email

Notice: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

## Mei Kwan (LKKAuto)

From:

Mei Kwan (LKKAuto)

Sent:

Wednesday, 22 May, 2019 10:45 AM

To:

'Janet Tan'

Cc:

Admin A; Joy Irene (LKKAuto); CS A Team

Subject:

RE: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against

GZ565S (EQ) on 06.05.2019

Attachments:

TP ESTIMATE - MARKED.pdf; Preliminary Advice.pdf

Categories:

HMK

# 'WITHOUT PREJUDICE' SAVE AS TO COSTS

EQI ref: DM19H001247/JT

LKK REF: CC4/EQI19008598/Jja3

Dear Janet,

We refer to the above matter.

Enclosed revert of vehicle: GBD 6352A

We have not authorized repairs.

Enclosed for your perusal is:

Estimated cost of repair

Preliminary advice

Please take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

#### To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

#### LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, 14 May, 2019 2:20 PM

To: 'Janet Tan' <janet.tan@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ)

on 06.05.2019

Dear Sir/Mdm.

Thank you for the assignment.

## Location at 39 Woodlands Close #01-12 Mega@Woodlands S(737856).

Please let us have the officer in charge and liability too.

Thank You 3

Best Regards

Ms Lai Yee Meng



#### Yew Tee Automobile Tech Pte Ltd

Branch Office: 39 Woodlands Close, #01-12 Mega@Woodlands Singapore 737856

DID: 6256 2081

Email: info@yewteegroup.com

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61 Singapore 417800 DID: 6702 3113

Email: utauto2@singnet.com.sg

please consider the environment before printing this email

Notice: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Janet Tan < janet.tan@eqinsurance.com.sg>

Sent: Tuesday, 14 May 2019 11:14 AM To: YT(MG) <info@yewteegroup.com>

Cc: YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>

Subject: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on

06.05.2019

Without Prejudice Save As To Costs



#### **EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190 www.eginsurance.com.sg





Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: YT(MG) [mailto:info@yewteegroup.com]

Sent: Tuesday, May 14, 2019 10:50 AM

To: EQI PRS < EQIPRS @eqinsurance.com.sg>

Cc: Janet Tan < janet.tan@eqinsurance.com.sg>; Tan Wei Yin < weiyin.tan@eqinsurance.com.sg>; Elaine

Cheong <elaine.cheong@eqinsurance.com.sg>; YTKB <utauto2@singnet.com.sg>; YTHQ

<utauto@singnet.com.sg>

Subject: RE: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

#### REMINDER

Hi Motor Claims Dept,

Refer to email below, please let us have the list of surveyor for choose to conduct the pre-repair survey.

Thank You 🕲

Best Regards

. No Lai Yee Meng



#### Yew Tee Automobile Tech Pte Ltd

Branch Office:

39 Woodlands Close.

#01-12 Mega@Woodlands

Singapore 737856

DID: 6256 2081

Email: info@yewteegroup.com

HO

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Yew Tee Ind. Est.

Unit No #01-60/61

Singapore 417800

39 Woodlands

Close #01-12

Singapore 678006

737856

DID: 6762 2081 (3 Lines)

2081 (3 Lines) Fax: 6760 4895

DID: 6256

Singapore

Fax: 6702 3773

Fax: 6256

2533

Email: utauto@singnet.com.sg

Email: utauto2@singnet.com.sg

DID: 6702 3113 (3 Lines)

Email:

info@yewteegroup.com

please consider the environment before printing this email

Notice: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(MG) [mailto:info@yewteegroup.com]

Sent: Saturday, 11 May, 2019 11:24 AM

To: eqiprs@eqinsurance.com.sg

Ce: YTKB; YTHQ

Subject: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Hi Motor Claims.

Attached report and estimate.

Kindly arrange PRI at 39 Woodlands Close, #01-12 Mega @ Woodlands S(737856).

Please let us have the list of surveyor for choose to conduct the pre-repair survey.

Kindly let us have the liability and officer-in-charge too.

Thank You (3)

Best Regards

Ms Lai Yee Meng



#### Yew Tee Automobile Tech Pte Ltd

Branch Office: 39 Woodlands Close, #01-12 Mega@Woodlands Singapore 737856 DID: 6256 2081

Email: info@yewteegroup.com

HO: Blk 6 Woodlands Road 399F Yew Tee Ind. Est Singapore 678006