

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Saturday, 31 August 2019 11:48 AM
To: Janet Tan
Subject: YOUR REF: DM19HO01247/JT (OUR REF: CC4/EQI19008598/Jga3s2) *** ACCIDENT INVOLVING GZ 565S (OI) & GBD 6352A (TP) ON 06/05/2019 ***
Attachments: ADJUSTMENT REPORT.pdf; INSPECTION REPORT.pdf; LKK RESURVEY PHOTO.pdf; LKK SURVEY PHOTO.pdf; LOD AND OTHER DOCUMENTS.pdf

EQ ref : **DM19HO01247/JT**
LKK ref : CC4/EQI19008598/Jga3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING GZ 565S (OI) & GBD 6352A (TP) ON 06/05/2019

We refer to the above matter.

OI MOVING OUR OF PARKING LOT, HIT ONTO TPV & OTHER VEHICLE.
A letter was sent out to the Insured to notify Third Party claim and NCD issues. No further feedback till to date.

We seek your approval to offer Third Party repairer "**YEW TEE AUTOMOBILE TECH PTE LTD**" at **\$7,335.00(all-in)**.

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 23,300.74	\$ 5,800.00
2. Loss of Use (12days x \$120.00)	\$ 1,440.00	\$ 1,100.00 (11days x \$100.00)
3. LTA/ GIA Search Fee	\$ 29.00	\$ 29.00
Total	\$ 24,769.74	<u>\$ 7,335.00</u>

**8days recommendation for repair + 1Sunday + 2PRS = 11days

Market Value	: \$10,000.00 (est)
LTA Rebate	: \$ 4,121.00 (est)
Nett Value	: <u>\$ 5,879.00 (est)</u>

Enclosed here with all the relevant documents for your perusal.

Kindly let us have your approval/instruction.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Cecilia Chong (LKK Auto)

From: YT(MG) <info@yewteegroup.com>
Sent: Friday, 6 September 2019 2:23 PM
To: Cecilia Chong (LKK Auto)
Cc: 'YTKB'; 'YTHQ'; 'YTHQ'; 'YTKB'; YTHQ; YTKB
Subject: RE: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Hi Cecilia,

Ok confirm.

Please let us have the DV soon.

Thanks.

Best Regards

Sky Teh

Mobile: 9747 1475
Website: www.yewteegroup.com
Email: info@yewteegroup.com
Like Us On Facebook

Director of
-YEW TEE AUTOMOBILE TECH PTE LTD



WEST HQ Office:

Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6762 2081 (3 Lines)
Fax: 6760 4895
Email: utauto@singnet.com.sg

EAST Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4
Unit No #01-60/61
Singapore 417800
DID: 6702 3113 (3 Lines)
Fax: 6702 3773
Email: utauto2@singnet.com.sg

NORTH Branch Office:

Mega@Woodlands
39 Woodlands Close #01-12
Singapore 737856
DID: 6256 2081 (3 Lines)
Fax: 6256 2533
Email: info@yewteegroup.com

please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Cecilia Chong (LKK Auto) [mailto:CeciliaChong@lkkauto.com]
Sent: Thursday, 5 September, 2019 1:56 PM
To: YT(MG)
Cc: 'YTKB'; 'YTHQ'; YTHQ; YTKB
Subject: RE: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Without Prejudice

Dear Sky,

Breakdown of \$6,895.00 as follow:

COR(w/GST): \$6,206.00
LOU(\$60 x11 days): \$660
GIA/LTA search: \$29.00
Total: \$6,895.00

Kindly confirm acceptance.

Thanks

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: YT(MG) [mailto:info@yewteegroup.com]
Sent: Wednesday, 4 September 2019 1:10 PM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Cc: 'YTKB' <utauto2@singnet.com.sg>; 'YTHQ' <utauto@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>; YTKB <utauto2@singnet.com.sg>
Subject: RE: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Hi Cecilia,

Kindly please let us have your breakdown.

Thanks.

Best Regards

Sky Teh

Mobile: 9747 1475

Website: www.yewteegroup.com

Email: info@yewteegroup.com

Like Us On Facebook

Director of

-YEW TEE AUTOMOBILE TECH PTE LTD



WEST HQ Office:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6762 2081 (3 Lines)

Fax: 6760 4895

Email: utauto@singnet.com.sg

EAST Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4

Unit No #01-60/61

Singapore 417800

DID: 6702 3113 (3 Lines)

Fax: 6702 3773

Email: utauto2@singnet.com.sg

NORTH Branch Office:

Mega@Woodlands


39 Woodlands Close #01-12

Singapore 737856

DID: 6256 2081 (3 Lines)

Fax: 6256 2533

Email: info@yewteegroup.com

 please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Cecilia Chong (LKK Auto) [<mailto:CeciliaChong@lkkauto.com>]

Sent: Wednesday, 4 September, 2019 9:09 AM

To: YT(MG)

Cc: YTKB; YTHQ

Subject: RE: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

WITHOUT PREJUDICE

Dear Ms Lai,

We are pleased to offer total amount of \$6890.00 (all-in).

Kindly confirm acceptance.

Thanks

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: YT(MG) [<mailto:info@yewteegroup.com>]

Sent: Friday, 12 July 2019 4:57 PM

To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>

Cc: YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>

Subject: RE: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Hi Cecilia,

Attached LOD and other claim documents for your kind perusal.

We will post the originals to your good office later.

Thank You ☺

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

Branch Office:

39 Woodlands Close,

#01-12 Mega@Woodlands

Singapore 737856

DID: 6256 2081

Email: info@yewteegroup.com

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(MG) <info@yewteegroup.com>

Sent: Thursday, 30 May 2019 10:31 AM

To: hweejie@lkkauto.com

Cc: YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>

Subject: RE: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Resend

Hi Hwee Jie,

Refer to email below, please assist us to finalise the COR.

Thank You ☺

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

Branch Office:

39 Woodlands Close,

#01-12 Mega@Woodlands

Singapore 737856

DID: 6256 2081

Email: info@yewteegroup.com

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(MG) <info@yewteegroup.com>
Sent: Saturday, 25 May 2019 12:22 PM
To: hweejie@lkkauto.com
Cc: YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>
Subject: RE: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Hi Hwee Jie,

Attached after repair photos.

Kindly finalise COR at \$5,800/- with 8 repair days.

Thank You ☺

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 6256 2081
Email: info@yewteegroup.com

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(MG) <info@yewteegroup.com>
Sent: Tuesday, 14 May 2019 1:01 PM
To: 'Janet Tan' <janet.tan@eqinsurance.com.sg>
Cc: YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>
Subject: RE: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Hi Janet,

Noted with thanks.

Thank You ☺

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 6256 2081
Email: info@yewteegroup.com

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Tuesday, 14 May 2019 12:22 PM
To: YT(MG) <info@yewteegroup.com>
Cc: YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>
Subject: RE: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Without Prejudice
Save As To Costs

Dear Yee Meng

OIC: Janet Tan
Liability: cleared

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: YT(MG) [<mailto:info@yewteegroup.com>]
Sent: Tuesday, May 14, 2019 11:45 AM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>
Subject: RE: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Hi Janet,

We choose 6) LKK Auto Consultants Pte Ltd

Location at 39 Woodlands Close #01-12 Mega@Woodlands S(737856).

Please let us have the officer in charge and liability too.

Thank You ☺

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

Branch Office:

39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856

DID: 6256 2081

Email: info@yewteegroup.com

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:


Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg



Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Janet Tan <janet.tan@eqinsurance.com.sg>

Sent: Tuesday, 14 May 2019 11:14 AM

To: YT(MG) <info@yewteegroup.com>

Cc: YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>

Subject: DM19HO01247/JT: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Without Prejudice
Save As To Costs

Dear Sky

For pre repair survey request, please email to eqiprs@eqinsurance.com.sg

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please **revert within 2 working days** if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon
RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	10) Appraisals Associates Pte Ltd Tel : 67472822 Fax: 67470070
Infiniti Appraisal Service Tel : 96684818/90099001 Fax: 64587432	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: YT(MG) [<mailto:info@yewteegroup.com>]

Sent: Tuesday, May 14, 2019 10:50 AM

To: EQI PRS <EQIPRS@eqinsurance.com.sg>

Cc: Janet Tan <janet.tan@eqinsurance.com.sg>; Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>; Elaine Cheong <elaine.cheong@eqinsurance.com.sg>; YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>

Subject: RE: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

REMINDER

Hi Motor Claims Dept,

Refer to email below, please let us have the list of surveyor for choose to conduct the pre-repair survey.

Thank You ☺

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 6256 2081
Email: info@yewteegroup.com

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg

 please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(MG) <info@yewteegroup.com>
Sent: Monday, 13 May 2019 3:41 PM
To: eqiprs@eqinsurance.com.sg
Cc: 'YTKB' <utauto2@singnet.com.sg>; 'YTHQ' <utauto@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>; YTKB <utauto2@singnet.com.sg>
Subject: RE: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Hi Motor Dept,

Resent to remind.

Thanks.

Best Regards

Sky Teh

Mobile: 9747 1475
Website: www.yewteegroup.com
Email: info@yewteegroup.com
Like Us On Facebook

Director of
-YEW TEE AUTOMOBILE TECH PTE LTD



WEST HQ Office:


Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6762 2081 (3 Lines)
Fax: 6760 4895
Email: utauto@singnet.com.sg

EAST Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4
Unit No #01-60/61
Singapore 417800
DID: 6702 3113 (3 Lines)
Fax: 6702 3773
Email: utauto2@singnet.com.sg

NORTH Branch Office:

Mega@Woodlands
39 Woodlands Close #01-12
Singapore 737856
DID: 6256 2081 (3 Lines)
Fax: 6256 2533
Email: info@yewteegroup.com

 please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(MG) [<mailto:info@yewteegroup.com>]

Sent: Saturday, 11 May, 2019 11:24 AM

To: egiprs@eqinsurance.com.sg

Cc: YTKB; YTHQ

Subject: Accident involving GBD6352A (NTUC) claiming against GZ565S (EQ) on 06.05.2019

Hi Motor Claims,

Attached report and estimate.

Kindly arrange PRI at **39 Woodlands Close, #01-12 Mega @ Woodlands S(737856)**.

Please let us have the list of surveyor for choose to conduct the pre-repair survey.

Kindly let us have the liability and officer-in-charge too.

Thank You ☺

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

Branch Office:

39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856

DID: 6256 2081

Email: info@yewteegroup.com

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQ19008598/Jga3s2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 19-09-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 565S	Veh. Inspected	GBD 6352A	
Policy No.	DMCPHQ18-007546	Coverage (\$)	0.00	
Claim No.	DM19HO01247/JT	Excess (\$)	0.00	
Assign From	JANET TAN	Assign Date	14/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN URVAN	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	JN1MG4E25Z0712478	Colour	SILVER	
Odometer	400727	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	MICHELIN	7 mm	
L/H Front Tyre	195 R15	MICHELIN	7 mm	
R/H Rear Tyre	195 R15	MICHELIN	7 mm	
L/H Rear Tyre	195 R15	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/05/2019	Inspection Date	14/05/2019	
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 6352A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	435.96	435.96
1	FRONT BUMPER BRACKET LH	NECESSARY	94.23	94.23
1	FRONT BUMPER BRACKET RH	NOT NECESSARY	94.23	-
1	FRONT BUMPER FOG LAMP LH	MISSING	232.20	232.20
1	FRONT BUMPER FOG LAMP GARNISH LH	MISSING	70.74	70.74
1	FRONT BUMPER REINFORCEMENT	BENT	315.84	315.84
1	FRONT BUMPER LOWER GRILLE	DEFORMED	243.00	243.00
1	FRONT HEADLAMP LH	CRACKED	355.95	355.95
1	FRONT HEADLAMP RH	NOT NECESSARY	355.95	-
1	FRONT SIDE LAMP LH	CRACKED	113.49	113.49
1	FRONT SIDE LAMP RH	NOT NECESSARY	113.49	-
1	FRONT GRILLE	NOT NECESSARY	301.63	-
1	FRONT GRILLE CHROME MOULDING (NPA)	NOT NECESSARY	-	-
1	BONNET (NPA)	NOT NECESSARY	-	-
1	FRONT CORNER PANEL LH	BUCKLED	520.20	520.20
1	RADIATOR	NOT NECESSARY	532.77	-
1	RADIATOR FAN COWLING	NOT NECESSARY	423.00	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	342.00	-
1	RADIATOR FAN BLADE	NOT NECESSARY	139.50	-
2	RADIATOR BRACKET	NOT NECESSARY	99.00	-
1	FRONT DOOR LH	BUCKLED	781.48	781.48
2	FRONT DOOR HINGES LH	BENT	122.40	122.40
1	FRONT DOOR PILLAR LH	NOT NECESSARY	1,565.55	-
1	FRONT DOOR INNER BOARD LH	DEFORMED	528.99	528.99
1	FRONT DOOR GLASS REGULATOR LH	NOT NECESSARY	183.24	-
1	FRONT DOOR GLASS REGULATOR MOTOR LH	NOT NECESSARY	519.21	-
1	FRONT DOOR LOCK LH	JAMMED	279.18	279.18
1	FRONT DOOR LOCK CATCH LH	NOT NECESSARY	60.84	-
1	FRONT DOOR RUBBER LH	NOT NECESSARY	117.00	-
1	FRONT DOOR GLASS LH	CRACKED	501.83	501.83
1	FRONT DOOR GLASS CHANNEL LH	NOT NECESSARY	109.80	-

Report Ref No. CC4/EQ19008598/Jga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR INNER RUBBER LH	NOT NECESSARY	130.50	-
1	FRONT DOOR STEP PANEL LH	BUCKLED	358.20	358.20
1	FRONT DOOR STEP GARNISH LH	DEFORMED	99.00	99.00
1	FRONT CHASSIS SIDE MEMBER LH	BUCKLED	523.53	523.53
1	FRONT CHASSIS MEMBER LH	NOT NECESSARY	1,540.00	-
1	FRONT WASHER TANK	BUCKLED	232.02	232.02
1	FRONT WASHER TANK MOTOR	CRACKED	139.50	139.50
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	1,260.00	-
1	FRONT WHEEL ARCH INNER PROTECTOR LH	NOT NECESSARY	121.59	-
1	FRONT FENDER INNER SHIELD LH	NOT NECESSARY	222.75	-
1	FRONT UPPER ARM LH	NOT NECESSARY	344.43	-
1	FRONT LOWER ARM LH	NOT NECESSARY	244.26	-
1	FRONT KNUCKLE ARM LH	NOT NECESSARY	308.16	-
1	SLIDING DOOR LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,327.69	-
1	REAR BUMPER LH	NOT NECESSARY	478.52	-
1	REAR BUMPER BRACKET LH	NOT NECESSARY	37.89	-
			16,920.74	5,947.74
	SPECIAL NETT ITEMS			
1	FRONT DOOR INNER BOARD CLIPS (SN)	NECESSARY	45.00	30.00
1	FRONT WHEEL RIM LH (SN)	TO REPAIR SEE LABOUR	550.00	-
1	FRONT TYRE LH (SN)	NOT NECESSARY	180.00	-
			775.00	30.00
	LABOUR			
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.		70.00	40.00
	TO DISMANTLE AND REFIT FRONT UNDERCARRIAGE.		180.00	100.00
	TO DO UP INTERIOR CLEANING AND CHEMICAL WASH.		200.00	50.00
	TO DISMANTLE & REFIT FRONT DASHBOARD & RELATED WIRE HARNESS & RELATED PARTS.	NOT NECESSARY	350.00	-

Report Ref No. CC4/EQ19008598/Jga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PRESSURE TEST AIR CON CONDENSER AND RADIATOR FOR LEAKAGE.		120.00	40.00
	TO TRANSFER SLIDING DOOR.	NOT NECESSARY	80.00	-
	TO TRANSFER DOOR.		60.00	50.00
	TO REMOVE & REFIT AIR-CON COMPRESSOR, AIR-CON MOTOR, CONDENSER, PIPES & VACUUM, INCLUDING REFILLING OF GAS.	NOT NECESSARY	180.00	-
	TO CONDUCT COMPUTER WHEEL ALIGNMENT.		80.00	60.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH, SLIDING DOOR LH, REAR FENDER LH AND FRONT WHEEL RIM LH.		2,100.00	1,400.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		60.00	40.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.		45.00	30.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PARTS FOR RUST PROTECTION.		80.00	40.00
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLAENING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		2,000.00	1,300.00
			5,605.00	3,150.00
GRAND TOTAL			23,300.74	9,127.74
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,800.00

Report Ref No. CC4/EQ19008598/Jga3s2

ONG HWEE JIE
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.