



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

NO. : 34135

- Rev. 1

DATE : 10/05/2019
CLAIM NO. : 11335
POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBB8628C
MAKE/MODEL : YAM / FINO

*not Alvin
1/5/19
15/5/19
the pre Atk up*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALL BEARING P/N: 62247	REPLACE	1.00	\$18.50	18.50
2	BALL BEARING RETAINER P/N: 52980	REPLACE	1.00	\$17.50	17.50
3	BALL RACE 1 P/N: 50622	REPLACE	1.00	\$11.50	11.50
4	BALL RACE 2 P/N: 50623	REPLACE	1.00	\$11.50	11.50
5	COVER LOWER P/N: 38557	REPLACE	1.00	\$41.50	41.50
6	COVER SIDE LH P/N: 38540	REPLACE	1.00	\$68.00	68.00
7	COVER SIDE RH P/N: 38541	REPLACE	1.00	\$68.00	68.00
8	EMBLEM LH (FINO) P/N: 38576	REPLACE	1.00	\$41.50	41.50
9	EMBLEM RH (FINO) P/N: 38542	REPLACE	1.00	\$41.50	41.50
10	FENDER FRONT P/N: 38543	REPLACE	1.00	\$47.50	47.50
11	FENDER REAR	REPLACE	1.00	\$35.50	35.50
12	FORK FRONT ASSY P/N: 52318	REPLACE	1.00	\$275.00	275.00
13	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		1.00	\$280.00	280.00



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-03M3
ISO 9001: 2015

677.50



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 34135

- Rev. 2

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

DATE : 10/05/2019
CLAIM NO. : 11335
POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBB8628C
MAKE/MODEL : YAM / FINO

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALL BEARING P/N: 62247	REPLACE	1.00	\$18.50 Disc %: 10.00	16.65
2	BALL BEARING RETAINER P/N: 52980	REPLACE	1.00	\$17.50 Disc %: 10.00	15.75
3	BALL RACE 1 P/N: 50622	REPLACE	1.00	\$11.50 Disc %: 10.00	10.35
4	BALL RACE 2 P/N: 50623	REPLACE	1.00	\$11.50 Disc %: 10.00	10.35
5	COVER LOWER P/N: 38557	REPLACE	1.00	\$41.50 Disc %: 10.00	37.35
6	COVER SIDE LH P/N: 38540	REPLACE	1.00	\$68.00 Disc %: 10.00	61.20
7	COVER SIDE RH P/N: 38541	REPLACE	1.00	\$68.00 Disc %: 10.00	61.20
8	EMBLEM LH (FINO) P/N: 38576	REPLACE	1.00	\$41.50 Disc %: 10.00	37.35
9	EMBLEM RH (FINO) P/N: 38542	REPLACE	1.00	\$41.50 Disc %: 10.00	37.35
10	FENDER FRONT P/N: 38543	REPLACE	1.00	\$47.50 Disc %: 10.00	42.75
11	FENDER REAR	REPLACE	1.00	\$35.50 Disc %: 10.00	31.95
12	FORK FRONT ASSY P/N: 52318	REPLACE	1.00	\$275.00 Disc %: 10.00	247.50
13	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		1.00	\$250.00	250.00



bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-140363
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	LEG SHIELD 2 P/N: 52328	REPLACE	1.00	\$73.00 Disc %: 10.00	65.70
15	LEVER BRAKE RH P/N: 38548	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
16	PANEL FRONT P/N: 38551	REPLACE	1.00	\$82.00 Disc %: 10.00	73.80
17	PLATE DISC BRAKE RH P/N: 52322	REPLACE	1.00	\$53.00	53.00
18	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$10.00	10.00
19	RACE BALL 2 P/N: 52330	REPLACE	1.00	\$11.50 Disc %: 10.00	10.35
20	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$10.00	10.00
21	TAIL LIGHT ASSY	REPLACE	1.00	\$68.50 Disc %: 10.00	61.65
22	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00

SUB TOTAL

\$1,190.05

GST @ 7 %

\$83.30

GRAND TOTAL

\$1,273.35

50% deposit required before ordering of parts.

Validity: 30 days

Accident quotation

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0303
ISO 9001: 2015