

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBJ3152Z190508

Estimate

Customer		Date:	14-05-19
Name:	AXA Insurance Singapore Pte Ltd	Vehicle No:	GBJ3152Z
Address:	Motor Claims Department	Model/Make:	Nissan NV350
	8 Shenton Way #27-01	Panel Van	5 DR 2.5
	AXA Tower		Singapore 068811

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Lh Sliding Door	\$ 1,255.70	N
2	Wheel Hub-Cab	\$ 251.30	N
3	Bumper	\$ 993.10	N
4	Bumper Clips 1 set	\$ 48.00	SN 305.00
5	Fender	\$ 1,793.60	N
6	Fender Garnish	\$ 504.60	N
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	500
	To putty & spray painting & including touch up paint on accident affected area	\$ 900.00	600
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	40
	To remove, replace and transfer Sliding door panel, fitting and mechanisms	\$ 80.00	50

Total Parts & Labour of estimate for damaged vehicle

\$ 6,706.30

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

Not Authorized
LKK
15/5/19
Take photo before repair.
P/P 3057.35
4 day.

P-2041.50
10%
P-1837.35
S.N- 30.00
1chm- 1190.00
\$ 3057.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: