

1400200

INS. CASE OWNER:

CS
664/QBE1900 8621, F 627LKK:
IDAC:

Surveyor:

KSL

DOI:

ASSIGNMENT

22/5/19

Date / Time:

13/5/19

Registered in Meritum:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SU 3363C

Name of Insured:

LEE BUAN TIANG

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

2/5/19

Is driver the owner?

YES

/ NO

Nature of Accident:

Claim No.:

VL017579

Policy No.:

Make / Model:

Place of Accident:

If NO: Driver Name / Age:

Driver Tel No.:

(V/L) YES / NO

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

6X 34144

INSRS:
WSP:
Tel:
Liability:
RMKS:S10M9
LFEINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

6X 34144 - 1
- pass lawyer, submit PRS.

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

1

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

1

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

S\$

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search:

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

Total:

S\$

Global Sum S\$:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASSIGNMENT

6468 JNE



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

511 BRIDGE ROAD, #02-25 PAVAN INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62563315

Your ref: To Be Advised
Our ref: CC4/QBE19008621/Kjb3

Date: 23.05.2019

The Motor Claims Department
M/s QBE INSURANCE (INTERNATIONAL) LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GX3419Y

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.05.2019 at the premises of M/s Siong Lee Motor and have the following to report:-

Workshop Estimate Amount	: S\$	6,491.76
Revised Estimate Amount	: S\$	3,449.54
"Check" Items Amount	: S\$	1,385.79
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser



松 利 摩 哆
SIONG LEE MOTOR

Sin Ming AutoCity
160 Sin Ming Drive #02-07 Singapore 575722
Tel: 6457 0410, 6453 1255 Fax: 6552 0692

We specialise in repairing all kinds of vehicles and pre-inspection servicing.
We also undertake accident insurance claims for our customers.

Company Reg. No.: 100838/00J

22 May 2019

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: ALPHA FUMIGATION SERVICES PTE LTD

H/P: 6465 5787

Dear Sirs / Madam,

**Accident Claim for Vehicle No.GX 3419 Y , Involving Vehicle No.SLL 3363 G.
Accident on 07 MAY 2019, AT 5 TUKANG INNOVATION GROVE.**

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	FRONT BUMPER 612.20	1PC	\$ Bu 1,341.60
2	FRONT BUMPER REINFORCEMENT 285 432.80	1PC	\$ R 599.70
3	FRONT BUMPER SIDE BRACKET	2PCS	\$ DIT 320.10
5	FRONT GRILLE	1PC	\$ mgm 520.40
6	FRONT GRILLE BADGE	1PC	\$ R 38.20
7	HEADLAMP @ 327.00 @ 41750.01 / mgm	2PCS	\$ n/s mgm 1,380.00
8	FRONT BONNET 850.40	1PC	\$ R 1,201.10
9	FRONT BONNET HINGES	2PCS	\$ R 480.20
10	FRONT BONNET LOCK	1PC	\$ R 250.10
11	FRONT BONNET LOCK PILLAR		\$ R 120.80
TOTAL LIST PRICE			\$ 6,252.20
LESS 20% 308 108			\$ (1,250.44)
TOTAL AMOUNT			\$ 5,001.76

LABOUR :		
1	LABOUR TO SPRAY PAINT	\$ 500 750.00
2	LABOUR TO PANEL BEATING	\$ 450 700.00
3	LABOUR TO FOCUS HEADLAMP.	\$ 20 40.00
TOTAL LABOUR		\$ 1,490.00
TOTAL AMOUNT		\$ 6,491.76

THANK YOU

FROM:

SIONG LEE MOTOR

Mr Tan Leng Huat

Lee Auto Consultants hence notify the Repairer of the following:

• TOTAL LABOUR \$ 1,490.00
• TOTAL AMOUNT \$ 6,491.76

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Not Asker
C/Sy 83,200
Person After Print
4 days

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Wednesday, 15 May 2019 8:42 AM
To: assignments
Subject: FW: Yr ref: V0021292 - ACCIDENT INVOLVING GX3419Y & SLL3363G ON 07.05.2019 (Or ref: LCH.lg/SMSL-90367.19)

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Wednesday, 15 May 2019 8:30 AM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: Yr ref: V0021292 - ACCIDENT INVOLVING GX3419Y & SLL3363G ON 07.05.2019 (Or ref: LCH.lg/SMSL-90367.19)

Our Ref. V0021292

Hi

Please assist to arrange for TP survey on WP basis. FYI our Insured has yet to report.

Thanks & Best Regards

Joyce Foo

Senior Assistant

Claims Dept/Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 64771184 | +65 62246633

Website LinkedIn Twitter



Veh Out

From: Cheonghoh Law <mail@cheonghoh.sg>
Sent: Tuesday, 14 May 2019 5:14 PM
To: Joyce Foo <joyce.foo@qbe.com>
Subject: Re: Yr ref: V0021292 - ACCIDENT INVOLVING GX3419Y & SLL3363G ON 07.05.2019 (Or ref: LCH.lg/SMSL-90367.19)

Dear Sirs,

We refer to the above matter and to your email of even date.

Our client hereby nominate LKK Auto Consultants Pte Ltd named in paragraph 2 of your said email to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be contact our client's workshop, Siong Lee Motor, 160 Sing Ming Drive #02-07 AutoCity Singapore 575722 for the survey of GX 3419 Y.

Contact Person : Mr Tan / Ms Kwee Pin
Telephone : 6453 1255

Kindly proceed to do the needful.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 14 May 2019, at 4:12 PM, Joyce Foo <joyce.foo@qbe.com> wrote:

WITHOUT PREJUDICE

Our ref : V0021292

Dear Sirs/Madam

We refer to the above captioned matter.

We intent to conduct a full survey of the damage to your client's vehicle. We propose to use one of the motor surveyors named in the attached list:

COMPANY
Appraisal Associates Pte Ltd
Automobile Inspection Services
KM Auto Assessors Pte Ltd
LKK Auto Consultants Pte Ltd
Infiniti Appraisal Service
Priority Services
Quantum Risk Management (S) Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

FYI Our insured has yet to report the accident.

Thanks & Best Regards

Joyce Foo

Senior Assistant

Claims Dept/Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 64771184 | +65 62246633

Website LinkedIn Twitter

<image001.png>

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Shu Pei (LKKAuto)

From: twinauto@singnet.com.sg
Sent: Friday, 15 November 2019 2:35 PM
To: Hsiao Tong (LKKAuto)
Cc: Shu Pei (LKKAuto)
Subject: Re: Your Ref: GX3419Y // DOA: 07/05/2019

Dear Shu Pei

We would like to accept the amount @ \$3200.00 / 4days .

Thank you.

Regards.

Siong Lee Motor
Tel: 6457 0410

On Fri Nov 15 2019 09:34:24 GMT+0800 (Singapore Standard Time) Hsiao Tong (LKKAuto)

<chewht@lkkauto.com> wrote:

----- Original Message -----

Without Prejudice

Dear Sirs/Mdm,

For COR, L/sum \$3,200.00 – 4 repair days.

Please confirm.

Best Regards,
Hsiao Tong, Chew (Ms)
| Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com
| fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CS/QBE19008621/Kb3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 09-12-2019



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 3363C	Veh. Inspected	GX 3419Y
Policy No.	8-V0021292-MVA	Coverage (\$)	0.00
Claim No.	V0021292	Excess (\$)	0.00
Assign From	JOYCE	Assign Date	15/05/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN P/UP	c.c	2664
Engine No.	HIDDEN	Year of Reg.	2004
Chassis No.	JN1CHGD22Z0072706	Colour	SILVER
Odometer	723917	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185 R14X8	YOKOHAMA	8 mm
L/H Front Tyre	185 R14X8	YOKOHAMA	8 mm
R/H Rear Tyre	185 R14X8	BRIDGESTONE	3 mm
L/H Rear Tyre	185 R14X8	BRIDGESTONE	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/05/2019	Inspection Date	22/05/2019
Survey held at	160 SIN MING DRIVE #02-07		
Repairer	SIONG LEE MOTOR		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GX 3419Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	1,341.60	682.20
1	FRONT BUMPER REINFORCEMENT	BENT	599.70	432.80
2	FRONT BUMPER SIDE BRACKET	DISTORTED	320.10	320.10
1	FRONT GRILLE	MTG CRACKED	520.40	520.40
1	FRONT GRILLE BADGE	NECESSARY	38.20	38.20
1	HEADLAMP	MTG CRACKED	1,380.00	417.50
1	FRONT BONNET	BENT	1,201.10	850.40
2	FRONT BONNET HINGES	TO REPAIR SEE LABOUR	480.20	-
1	FRONT BONNET LOCK	TO REPAIR SEE LABOUR	250.10	-
1	FRONT BONNET LOCK PILLAR	BENT	120.80	120.80
	LESS 10% DISCOUNT		-625.22	-338.24
			5,626.98	3,044.16
	<u>LABOUR</u>			
	LABOUR TO SPRAY PAINT.		750.00	500.00
	LABOUR TO PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BONNET HINGES AND FRONT BONNET LOCK .		700.00	450.00
	LABOUR TO FOCUS HEADLAMP.		40.00	20.00
			1,490.00	970.00
	GRAND TOTAL		7,116.98	4,014.16
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00

Report Ref No. CS/QBE19008621/Kb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.