

Surveyor: Hwee Jit

ASSIGNMENT (Office)

From (Person): Lionel Tan

of FWD

Date/Time: 15.5.19 17.22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJR 3790V

Insured:

at Workshop n/s: Yew Tee Automobile

Tel: 67622081

of Blk 6 Woodland Road 399F

Policy No: PNPV2012-00007724

Claim No: 1201900012868

Sum Insured:

Excess: \$600.00

Make of Veh:

D.O.A. 13.5.19

(Client's Record)

16.5.2019

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 15.5.19 5.34pm

Person Contacted: Winnie

Vehicle (IN) / OUT

Date/Time: Action/Instruction (✓) Estimate

SJR 3790V - CC4 / FWD/19008607/013

D.O.A. - 13/05/2019

17/5/2019 - Revert via menmen.

21/5/2019 - 2nd revert on lump sum \$6500.

21/5/2019 @ 1:44pm - via email to Yew Tee authorise repair and sign lump sum letter.

REF: FWD

ASSIGNMENT

Front

Date: 16.5.2019

Veh No: SJR3790V

Yr Regn: 22 Jun 2009

Estimated Cost

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No SJR3790V

Make: Audi A4

c.c 1798

at Workshop n/s Yew Tee Automobile

Colour Black

A/C: Insured / Std / NI / NA

of Blk 6 Woodlands Road 399F

Sp. Reading 215229

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No: WAUZZZ8K19A235292

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess: \$600.00

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:


Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size F: 245/40R18

R: -

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Bal. or Market Value:

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal. 6 mm

R/Bal. 6 mm

GIA / PR Seen

Consistent? : Yes or No

L/Bal. 6 mm

L/Bal. 6 mm

Est. Repairs:

days Res: Yes or No

D.O.A. 13/5/19

D.O.A. 16/5/19

Lump Sum:

% 3 Val: Yes or No

Survey held at Yew Tee Auto

CA / ☒ REV / REP. / 24 HRSDes. of Damages: ☒ Front / Rear / O/S / N/S / U/C / Rooftop or

Date

Person Contacted

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-\$25000

PV-\$18077

NV-\$6923

RECEIVED 20 JUN 2019

Continued L/S \$6500/- 7days of repair. (Red: 5950/4790)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 7

2016 Typist

☒ Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Add Fee: ☐ Site Insp (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

2)

Report Format :

Lump Sum / LB.I: (\$)

250
50
50+50

11

411

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2019 Sendback Est	15 May 2019 16:48 S\$12,450.00	15 May 2019 17:22 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	EDDEI RAHMAT BIN TAIB, ID: S7249124F		
Vehicle Reg. No.:	SJR3790U	Date of Loss:	13/05/2019 15:00 - :59 [118 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900012868	Policy/Cover Note No.:	PNPV2018-00007724 (Comprehensive) Coverage: 22/06/2018 - 21/06/2019
		Excess:	S\$600.00
Repairer:	Yew Tee Automobile Tech Pte Ltd (HQ) Blk 6 Woodlands Road 399F,, Yew Tee Ind Estate, 678006 Woodlands - Tel: 67622081		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/05/2019]		
Driver/Custodian:	HAFIDAH BINTE OTHMAN (), NRIC: S7302379C, Tel: +6591770492 Email:		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 21 May 2019 1:44 PM
To: 'utauto@singnet.com.sg'
Cc: SUR
Subject: FW: SJR 3790U / OD / FWD
Attachments: AUTHORIZATION FOR LUMP SUM REPAIR.PDF

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJR 3790U (Excess \$600/-)**. Repair on lump sum repair.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Sign and email back the letter.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 17 May 2019

Preliminary Advice

Vehicle No	: SJR3790U	Accident Date	: 13/05/2019
Make	: AUDI A4	Policy No.	: PNPV2018-00007724
Assignment Date	: 15/05/2019	Excess	: S\$600.00
Date of Inspection	: 16/05/2019	Est. Duration of Repair	: 7.00
Inspection At	: YEW TEE AUTOMOBILE TECH PTE LTD (HQ) BLK 6 WOODLANDS ROAD 399F., YEW TEE IND ESTATE SINGAPORE 678006		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,450.00
Revised Amount	:S\$	7,715.00
Check Items (Estimated)	:S\$	3,382.00
Total	:S\$	11,907.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$		60,000.00
Pre-Accident Value	:S\$	25,000.00	(After renew Value) 18,077.00
COE / PARF Rebate	:S\$	18,087.00	(After Renew COE / PARF Rebate)
Salvage Value	:S\$		
Margin for Repair	:S\$	6,913.00	41,923.00 (After Renew Margin Repair)

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Please be inform that during the Date of LOss, COE was not renew yet. COE was renew only after the accident.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9124F
Vehicle Details	
Vehicle No.:	SJR3790U
Vehicle to be Exported:	No
Intended Deregistration Date:	17 May 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8T FSI MU CVT ABS D/AB 2WD 4DR
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	CDH051484
Chassis No.:	WAUZZZ8K19A235292
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$35,931.00
Original Registration Date:	22 Jun 2009
First Registration Date:	22 Jun 2009
Transfer Count:	2
Actual ARF Paid:	\$35,931.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jun 2019
PARF Rebate Amount:	\$17,965.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$39,563.00
COE Rebate Amount:	\$112.00
Total Rebate Amount:	\$18,077.00

The information contained herein is correct as at 17 May 2019

OK

View Received Message

This mail is associated with :

SJR3790U (1201900012868)

OD

May 13 2019 3:00PM

[EDDEI RAHMAT BIN TAIB]

Yew Tee Automobile Tech Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 21/05/2019 12:07 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6500.00) - SJR3790U - Claim Handler: Lionel Tan

Approved:6500.00:Repairer to upload lump sum form.

Yew Tee Auto @ Singnet.com.sg.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SJR3790U (1201900012868)

OD

May 13 2019 3:00PM

[EDDEI RAHMAT BIN TAIB]

Yew Tee Automobile Tech Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 17/05/2019 18:16 PM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SJR3790U - Claim Handler: Lionel Tan

Maintained:Vehicle was renewed after accident. Please re-look your advice.

DOCUMENTS SUMMARY

There are no documents.

Sell by Consignment

Consign your car to sell direct at the price you want without hassle.
No sale = no charges!

Audi A4

Price Range

Depreciation

2009

Vehicle Type

Home » Used Cars » KelvinCarz Automobile » Audi A4 1.8A TFSI MU S-Line

Audi A4 1.8A TFSI MU S-Line

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$24,955**Depreciation** ⑦ N.A.**Reg Date** 02-Oct-2009
(4mths 14days COE left)**Mileage** 130,000 km (13.5k /yr)**Manufactured** ⑦ 2009**Road Tax** ⑦ \$976 /yr**Transmission** Auto**Dereg Value** ⑦ \$19,873 as of today (change)**OMV** ⑦ \$38,230**COE** ⑦ \$20,200**ARF** ⑦ \$38,230**Engine Cap** 1,798 cc**Power** 118.0 kW (158 bhp)**Curb Weight** ⑦ 1,450 kg**No. of Owners** ⑦ 2**Type of Vehicle** Luxury Sedan

Features

1.8 TurboCharged Engine With 7 Speed Multi-Tronic Transmission. View specs of the Audi A4 (2005-2007)

Accessories

Light Grey With Black Leather Interior. 18" Rims. S-Line Styling Kit.

Description

Proudly Presented By KelvinCarz Automobile. S-Line Edition Comes With Front LED Daytime Running Light, Rear LED Tail Lamps And All Round Factory Styling Kit. Selling " As Is Where Is " Condition. Last Serviced In 125,000 Km. Road Tax Paid Till 10/2019. Guarantee Buy Back At \$20,000 When In Due To Scrap. Search Under KelvinCarz Automobile Listing For More Short Term Vehicles At Super Value Buy.

Category

PARF Car, Premium Ad Car

Status

Available

Re: Compare



Shortlist

Compare

Report Error

M

Seller Information

Company	KelvinCarz Automobile
Address	18 Ubi Ave 1, Sear
Location	Ubi
Contact Person(s)	KL



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 10 Years Coe Renewal Toyota Estima 2.4A



2.98% P.A \$0 Admin Fees @ Gv
Finance 2 Years Warranty \$4800
Down Monthly From \$988
GV Credit Pte Ltd StarAd

Aut
An Inspiration

click here to view
our **PRISTINE**
at

Browse by Category

« Back (1 2) Next »

Sort by Date Posted

24 vehicles

Audi A4

Advanced Search

Search Selection

Audi A4

Any

Any

2009

Any

Any



Audi A4 2.0A TFSI Quattro S-tronic S-Line (New 10-yr COE)

\$72,800

\$7,270 /yr

15-Dec-2009

1,984 cc

113,000 km

Able To Loan Max High Loan, Ideal For Short Term Usage, Optional To Renew 5 Years COE At \$51,800 Beautifully Maintained And Regu No Repairs Needed. Bank/In House Loan And Competitive In...

Posted: 16-May-2019 Tags: 2009 Audi A4, 2009 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi



Audi A4 1.8A TFSI MU S-Line (New 10-yr COE)

\$71,800

\$7,170 /yr

23-Jun-2009

1,798 cc

91,000 km

100% Loan, Immediate Approval! Original Car Paintwork! Extremely Well Maintained! Low Mileage. Accident Free. Don't Miss This Chan Our Friendly Sales Person For Viewing The Car Now.

Straits Euro Motors Pte Ltd

Posted: 16-May-2019 Tags: 2009 Audi A4, 2009 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi



Audi A4 1.8A TFSI MU S-Line (New 10-yr COE)

\$66,777

\$6,670 /yr

25-Jun-2009

1,798 cc

135,000 km

Posted: 16-May-2019 Tags: 2009 Audi A4, 2009 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi



Audi A4 1.8A TFSI MU (COE till 04/2029)

\$63,800

\$6,430 /yr

17-Apr-2009

1,798 cc

5 Years COE Renewal For \$45,800. Selling Cheap! Hurry! View Now. Up To 100% Flexible Loan. We Provide Lowest Interest Rate. Flexil High Trade In Are Available. Package With Unrivalled Warran...

Classic Credit Pte Ltd

Posted: 15-May-2019 Tags: 2009 Audi A4, 2009 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in tow approval in 2 days without effort! Enquire today.

Compare

**A4 1.8A TFSI MU S-Line
(till 04/2024)**

\$48,500

\$9,780 /yr

25-Aug-2009

1,798 cc

89,200 km



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

Audi A4

Price Range ▼

Depreciation ▼

2009 ▼

Vehicle Type ▼


[Home](#) » [Used Cars](#) » [Direct Owners](#) » Audi A4 1.8A TFSI MU

Audi A4 1.8A TFSI MU

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
Price \$24,990

Depreciation ⓘ N.A.

Reg Date 08-Jun-2009
(21days COE left)

Mileage N.A.

Manufactured ⓘ 2009

Road Tax ⓘ \$976 /yr

Transmission Auto

Dereg Value ⓘ \$18,010 as of today (change)

OMV ⓘ \$35,934

COE ⓘ \$7,490

ARF ⓘ \$35,934

Engine Cap 1,798 cc

Power 118.0 kW (158 bhp)

Curb Weight ⓘ 1,450 kg

No. of Owners ⓘ 4

Type of Vehicle [Luxury Sedan](#)

Features

Standard Audi A4 S-Line Tune Up To Stage 1 For More Responsive And Higher Horse Power. View specs of the Audi A4 (2005-2007)

Accessories

As Per Below! COE Rising Now Is The Time To Buy With COE. Guaranteed Best Unit With Tastefully Modified Parts To Go With Car! Kindly Whatsapp Me

Description

Director's 5th Car. Always Sheltered Parking. Built-In In Reverse Camera Upgraded Audio System Carbon Parts Upgraded 19 Inch Rims Tune Up St Age 1 Upgraded Big Brake Kit With Original Brakes Provided New Tyres Clean Interior Great For COE Renewal! Loud Twin Exhaust. Standard Black Interior. S4 Kit. Great Condition Just Serviced 1 Week Back! Cheapest! Hurry! No Dealers Please.

Category

PARF Car, Direct Owner Sale

Status

Avr ⓘ ⓘ ⓘ ⓘ ⓘ

[Compare](#)

[Shortlist](#)
[Compare](#)
[Report Error](#)
[More](#)

Seller Information

Contact Person(s)

Contact No.

Enquiry

ESSENTIAL TRANSACTION

» Indemnity form

» Receipt

» Ownership Transfer



GET HELP WITH
PAPERWORK

sgCarMart Connect handle all your paperwork - send us your car details and we'll help with **Car Loan & Ownership Transfer**. For Adversely Affected Vehicles.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Singapore NRIC

Owner ID:

9124F

Vehicle Details

Vehicle No.:

SJR3790U

Vehicle to be Exported:

No

Intended Deregistration Date:

14 May 2019

Vehicle Make:

AUDI

Vehicle Model:

A4 1.8T FSI MU CVT ABS D/AB 2WD 4DR

Primary Colour:

Black

Manufacturing Year:

2009

Engine No.:

CDH051484

Chassis No.:

WAUZZZ8K19A235292

Maximum Power Output:

118.0 kW (158 bhp)

Open Market Value:

\$35,931.00

Original Registration Date:

22 Jun 2009

First Registration Date:

22 Jun 2009

Transfer Count:

1

Actual ARF Paid:

\$35,931.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

21 Jun 2019

PARF Rebate Amount:

\$17,965.00

Intended COE Rebate Details

COE Expiry Date:

21 Jun 2019

COE Category:

B - Car (1601cc & above)

COE Period(Years):

10

QP Paid:

\$11,889.00

COE Rebate Amount:

\$122.00

Total Rebate Amount:**\$18,087.00**

The information contained herein is correct as at 14 May 2019

OK



FWD - OD.

5/12/2019

PARF/COE Rebate Enquiry

[» Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 9124F

Vehicle Details

Vehicle No: SJR3790J
Vehicle to be Exported: Yes
Intended Deregistration Date: 17 May 2019
Vehicle Make: AUDI
Vehicle Model: A4 1.8T FSI MU CVT ABT L1AB 2WD 4DR
Primary Colour: Black
Manufacturing Year: 2009
Engine No: CDH651484
Chassis No: WAUZZZ8K19A235297
Maximum Power Output: 118.0 kW (158 hp)
Open Market Value: \$35,931.00
Original Registration Date: 22 Jun 2009
First Registration Date: 22 Jun 2009
Transfer Count: 3
Actual ARF Paid: \$35,931.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 21 Jun 2019
PARF Rebate Amount: \$17,965.00

Intended COE Rebate Details

COE Expiry Date: 31 May 2029
COE Category: B - Car (1601cc & below)
COE Period (Years): 10
PQP Paid: \$39,563.00
COE Rebate Amount: \$112.00
Total Rebate Amount: \$18,077.00

The information contained herein is correct as at 17 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	14/05/2019 13:19
Date Of Accident	13/05/2019 15:30
Exact Location Of Accident	CHANGI RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJR3790U
Insured/Policyholder	
Name Of Registered Owner	EDDEI RAHMAT BIN TAIB
NRIC No	S7249124F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91770492
Alternative Phone No	OFFICE-91770492
Vehicle Particulars	
Manufacturer	AUDI
Model	A4
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00007724
Cover Note Number	
Driver	
Name of Driver	HAFIDAH BINTE OTHMAN
NRIC No	S7302379C
Date Of Birth	28/01/1973
Occupation	INDOOR
Date Of Driving Pass	09/10/2011
Driving Experience	7 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91770492
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 166 TAMPINES ST 12 #05-345
Postcode	521166
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMK2724U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOHAMED NOOR BIN MOHAMED YUSOFF
NRIC/Passport Number	S7359874E
Contact Number	85891939
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	
-----------------------------	--

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/Fin no.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I was traveling along CHANGI RD. SUDDENLY a VEHICLE REG NO: SMK 2724 U STOP. I collided. AT my best knowledge.

DECLARATION

Here declare the following assertions are true in every model.

Frictionless & Sign-Matched Rage & Terror

Draw a figure:
(if chosen is not the public provider)
State & know:

Reporting Centre Personnel's Signature:
Name:
NIC No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9124F
Vehicle Details	
Vehicle No.:	SJR3790U
Vehicle to be Exported:	No
Intended Deregistration Date:	17 May 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8T FSI MU CVT ABS D/AB 2WD 4DR
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	CDH051484
Chassis No.:	WAUZZZ8K19A235292
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$35,931.00
Original Registration Date:	22 Jun 2009
First Registration Date:	22 Jun 2009
Transfer Count:	2
Actual ARF Paid:	\$35,931.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jun 2019
PARF Rebate Amount:	\$17,965.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$39,563.00
COE Rebate Amount:	\$112.00
Total Rebate Amount:	\$18,077.00

The information contained herein is correct as at 17 May 2019

OK

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No:200311009C)

Blk 6 Woodlands Road 399F., Yew Tee Ind Estate

Singapore 678006

Tel: 67622081 Fax: 67604895 Email: utauto@singnet.com.sg

INSURER: FWD Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00007724	Date of Loss:	13/05/2019
Vehicle Reg. No.:	SJR3790U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	EDDEI RAHMAT BIN TAIB		
Driver:	HAFIDAH BINTE OTHMAN		
Make/Model:	AUDI A4, 1.8 (A)	Vehicle Reg. Date:	22/06/2009
Vehicle Colour:	BLACK		
Engine No:	CDH051484	Chassis No:	WAUZZZ8K19A235292
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	18		
Present Location:	YEW TEE AUTOMOBILE TECH PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	8,770.00
Miscellaneous Items	0.00
Labour	2,320.00
Paintwork Labour	1,280.00
Towing	80.00
Gross Total (S\$)	12,450.00
+ GST 7.00% (S\$)	871.50
Nett Amount (S\$)	13,321.50

This claim is handled by: TOH TZE CHANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 May 2019)
Parts: 143 AUDI A4 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJR3790U)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>BUC /</i>	0.00	0.00	*845.00 F
2	1		*FRONT BUMPER SIDE RETAINER LH <i>ncc /</i>	0.00	0.00	*20.00 F
3	1		*FRONT BUMPER SIDE RETAINER RH <i>ncc /</i>	0.00	0.00	*20.00 F
4	1		*FRONT BUMPER TOWING COVER <i>mgs /</i>	0.00	0.00	*30.00 F
5	1		*FRONT BUMPER INNER SPONGE <i>lra /</i>	0.00	0.00	*45.00 F
6	1		*FRONT BUMPER REINFORCEMENT <i>DD /</i>	0.00	0.00	*338.00 F
7	1		*FRONT BUMPER CLIPS <i>ncc /</i>	0.00	0.00	*35.00 F
8	1		*FRONT NUMBER PLATE <i>DEF /</i>	0.00	0.00	*35.00 F
9	1		*FRONT GRILLE <i>LRA /</i>	0.00	0.00	*370.00 F
10	1		*FRONT FENDER LH <i>BUC /</i>	0.00	0.00	*351.00 F
11	1		*FRONT FENDER RH <i>BUC /</i>	0.00	0.00	*351.00 F
12	1		*BONNET <i>BUC /</i>	0.00	0.00	*715.00 F
13	1		*BONNET HINGES LH <i>BT /</i>	0.00	0.00	*33.00 F
14	1		*BONNET HINGES RH <i>BT /</i>	0.00	0.00	*33.00 F
15	1		*BONNET LOCK <i>Jam /</i>	0.00	0.00	*78.00 F
16	1		*BONNET INSULATOR <i>nn x</i>	0.00	0.00	*123.00 F
17	1		*BONNET INSULATOR CLIPS <i>nn x</i>	0.00	0.00	*30.00 F
18	1		*BONNET DAMPER <i>dm /</i>	0.00	0.00	*56.00 F
19	1		*FRONT DOOR RH <i>Repa / x</i>	0.00	0.00	*- F
20	1		*FRONT HEADLAMP LH <i>scr /</i>	0.00	0.00	*620.00 F
21	1		*FRONT HEADLAMP RH <i>lra /</i>	0.00	0.00	*620.00 F
22	1		*FRONT HEADLAMP LOWER BRACKET LH <i>lra /</i>	0.00	0.00	*45.00 F
23	1		*FRONT HEADLAMP LOWER BRACKET RH <i>lra /</i>	0.00	0.00	*45.00 F
24	1		*FRONT SUPPORT PANEL <i>? cra</i>	0.00	0.00	*477.00 F
25	1		*FRONT SUPPORT PANEL TOP GARNISH <i>? cra</i>	0.00	0.00	*52.00 F
26	1		*FRONT SUPPORT PANEL TOP GARNISH AIR INTAKE DUCT <i>lra /</i>	0.00	0.00	*160.00 F
27	1		*AIR CON CONDENSER <i>DD /</i>	0.00	0.00	*390.00 F
28	1		*AIR CON CONDENSER AIR GUIDE LH <i>? } nn</i>	0.00	0.00	*19.00 F
29	1		*AIR CON CONDENSER AIR GUIDE RH <i>? } nn</i>	0.00	0.00	*19.00 F
30	1		*AIR CON CONDENSER FAN COWLING <i>? } Jam</i>	0.00	0.00	*163.00 F
31	1		*AIR CON CONDENSER FAN MOTOR <i>? } Jam</i>	0.00	0.00	*351.00 F
32	1		*AIR CON SUCTION PIPE <i>? nn</i>	0.00	0.00	*263.00 F
33	1		*AIR CON RETURN PIPE <i>? nn</i>	0.00	0.00	*234.00 F
34	1		*AIR CON DISCHARGE PIPE <i>? BT</i>	0.00	0.00	*281.00 F
35	1		*RADIATOR <i>? BT</i>	0.00	0.00	*364.00 F
36	1		*RADIATOR FAN COWLING <i>? nn</i>	0.00	0.00	*163.00 F
37	1		*RADIATOR FAN MOTOR <i>? Jam</i>	0.00	0.00	*299.00 F
38	1		*AIR CLEANER BOX <i>? cra</i>	0.00	0.00	*270.00 F
39	1		*AIR CLEANER RESONATOR <i>? nn</i>	0.00	0.00	*95.00 F
40	1		*AIR CLEANER RESONATOR JOINT PIPE <i>? nn</i>	0.00	0.00	*65.00 F
41	1		*AIR CLEANER INTAKE DUCT <i>? cra</i>	0.00	0.00	*55.00 F
42	1		*CARBON CANISTER RH <i>? nn</i>	0.00	0.00	*212.00 F

F=Franchise part.

Total Parts (S\$)

8,770.00

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO CARRY-OUT BODY CAVITY PRESERVATION	New	40.00 ✓
2	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	80.00 40
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	60.00 X
4	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING & SANDING OF SURFACES, FINAL POLISHING & WAXING ARE ALSO AVAILABLE	New	1,100.00 900
Labour Items			
5	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	New	70.00 40
6	TO COMPUTER RESET AND RE-PROGRAM ALL FAULT CODE	New	350.00 120
7	TO PRESSURE TEST AIR CON CONDENSER AND RADIATOR FOR LEAKAGE	New	120.00 60
8	TO REMOVE & REFIT AIR CON COMPRESSOR, AIR CON MOTOR, CONDENSER, PIPES & VACUUM, INCLUDING REFILLING OF GAS	New	180.00 80
9	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO READJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,600.00 1200
Gross Labour Cost (\$\$)			3,600.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature] 21/5/19

Huee Jia - LKK

16/5/19

c/s 7 days

[Signature]

Not Authorise

Excess: \$600/-

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No:200311009C)

Blk 6 Woodlands Road 399F,, Yew Tee Ind Estate

Singapore 678006

Tel: 67622081 Fax: 67604895 Email: utauto@singnet.com.sg

INSURER: FWD Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00007724	Date of Loss:	13/05/2019
Vehicle Reg. No.:	SJR3790U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	EDDEI RAHMAT BIN TAIB		
Driver:	HAFIDAH BINTE OTHMAN		
Make/Model:	AUDI A4, 1.8 (A)	Vehicle Reg. Date:	22/06/2009
Vehicle Colour:	BLACK	Chassis No:	WAUZZZ8K19A235292
Engine No:	CDH051484		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	18		
Present Location:	YEW TEE AUTOMOBILE TECH PTE LTD (HQ)		

COST OF CLAIMS

Parts	8,770.00
Miscellaneous Items	0.00
Labour	2,320.00
Paintwork Labour	1,280.00
Towing	80.00
Gross Total (S\$)	12,450.00
+ GST 7.00% (S\$)	871.50
Nett Amount (S\$)	13,321.50

This claim is handled by: TOH TZE CHANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 May 2019)
 Parts: 143 AUDI A4 1.8 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJR3790U)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER BUC /	0.00	0.00	*845.00 F
2	1		*FRONT BUMPER SIDE RETAINER LH nec /	0.00	0.00	*20.00 F
3	1		*FRONT BUMPER SIDE RETAINER RH nec /	0.00	0.00	*20.00 F
4	1		*FRONT BUMPER TOWING COVER mis /	0.00	0.00	*30.00 F
5	1		*FRONT BUMPER INNER SPONGE CRA /	0.00	0.00	*45.00 F
6	1		*FRONT BUMPER REINFORCEMENT DD /	0.00	0.00	*338.00 F
7	1		*FRONT BUMPER CLIPS nec /	0.00	0.00	*35.00 F
8	1		*FRONT NUMBER PLATE DEF /	0.00	0.00	*35.00 F
9	1		*FRONT GRILLE LRA /	0.00	0.00	*370.00 F
10	1		*FRONT FENDER LH BUC /	0.00	0.00	*351.00 F
11	1		*FRONT FENDER RH BUC /	0.00	0.00	*351.00 F
12	1		*BONNET BUC /	0.00	0.00	*715.00 F
13	1		*BONNET HINGES LH BT /	0.00	0.00	*33.00 F
14	1		*BONNET HINGES RH BT /	0.00	0.00	*33.00 F
15	1		*BONNET LOCK Jam /	0.00	0.00	*78.00 F
16	1		*BONNET INSULATOR n x	0.00	0.00	*123.00 Fx
17	1		*BONNET INSULATOR CLIPS n x	0.00	0.00	*30.00 Fx
18	1		*BONNET DAMPER DM /	0.00	0.00	*56.00 F
19	1		*FRONT DOOR RH Repai / x	0.00	0.00	*FX
20	1		*FRONT HEADLAMP LH SCR /	0.00	0.00	*620.00 F
21	1		*FRONT HEADLAMP RH CRA /	0.00	0.00	*620.00 F
22	1		*FRONT HEADLAMP LOWER BRACKET LH CRA /	0.00	0.00	*45.00 F
23	1		*FRONT HEADLAMP LOWER BRACKET RH CRA /	0.00	0.00	*45.00 F
24	1		*FRONT SUPPORT PANEL ?	0.00	0.00	*477.00 F
25	1		*FRONT SUPPORT PANEL TOP GARNISH ?	0.00	0.00	*52.00 F
26	1		*FRONT SUPPORT PANEL TOP GARNISH AIR INTAKE DUCT CRA /	0.00	0.00	*180.00 F
27	1		*AIR CON CONDENSER DD /	0.00	0.00	*390.00 F
28	1		*AIR CON CONDENSER AIR GUIDE LH ?	0.00	0.00	*19.00 F
29	1		*AIR CON CONDENSER AIR GUIDE RH ?	0.00	0.00	*19.00 F
30	1		*AIR CON CONDENSER FAN COWLING ?	0.00	0.00	*163.00 F
31	1		*AIR CON CONDENSER FAN MOTOR ?	0.00	0.00	*351.00 F
32	1		*AIR CON SUCTION PIPE ?	0.00	0.00	*263.00 F
33	1		*AIR CON RETURN PIPE ?	0.00	0.00	*234.00 F
34	1		*AIR CON DISCHARGE PIPE ?	0.00	0.00	*281.00 F
35	1		*RADIATOR ?	0.00	0.00	*364.00 F
36	1		*RADIATOR FAN COWLING ?	0.00	0.00	*163.00 F
37	1		*RADIATOR FAN MOTOR ?	0.00	0.00	*299.00 F
38	1		*AIR CLEANER BOX ?	0.00	0.00	*270.00 F
39	1		*AIR CLEANER RESONATOR ?	0.00	0.00	*95.00 F
40	1		*AIR CLEANER RESONATOR JOINT PIPE ?	0.00	0.00	*65.00 F
41	1		*AIR CLEANER INTAKE DUCT ?	0.00	0.00	*55.00 F
42	1		*CARBON CANISTER RH ?	0.00	0.00	*212.00 F

F=Franchise part.

Total Parts (\$\$)

8,770.00

Estimates on Miscellaneous Items

are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO CARRY-OUT BODY CAVITY PRESERVATION	New	40.00 ✓
2	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	80.00 40
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	60.00 X
4	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING & SANDING OF SURFACES, FINAL POLISHING & WAXING ARE ALSO AVAILABLE	New	1,100.00 900
<u>Labour Items</u>			
5	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	New	70.00 40
6	TO COMPUTER RESET AND RE-PROGRAM ALL FAULT CODE	New	350.00 120
7	TO PRESSURE TEST AIR CON CONDENSER AND RADIATOR FOR LEAKAGE	New	120.00 60
8	TO REMOVE & REFIT AIR CON COMPRESSOR, AIR CON MOTOR, CONDENSER, PIPES & VACUUM, INCLUDING REFILLING OF GAS	New	180.00 80
9	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO READJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,800.00 1200
Gross Labour Cost (\$\$)			3,600.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Huee Jia - LKK

16/5/19

P/P 7 days



Not Authorise

Excess: \$600/-

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Blk 6 Woodlands Road 399F., Yew Tee Ind Estate

Singapore 678006

Tel: 67622081 Fax: 67604895 Email: utauto@singnet.com.sg

Benjamin

INSURER:

FWD Singapore Pte. Ltd. (HQ)

Sur@lkkauto.com

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
Policy No: PNPV2018-00007724
Vehicle Reg. No.: SJR3790U
Driver Age/Info:
TP Injury Involved? NO
Insured/Claimant: EDDEI RAHMAT BIN TAIB
Driver: HAFIDAH BINTE OTHMAN

Ref. No:
Date of Loss: 13/05/2019
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES

Make/Model: AUDI A4, 1.8 (A)
Vehicle Colour: BLACK
Engine No: CDH051484
Odometer: 0 KM

Vehicle Reg. Date: 22/06/2009
Chassis No: WAUZZZ8K19A235292

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 18

Present Location: YEW TEE AUTOMOBILE TECH PTE LTD (HQ)

COST OF CLAIMS

Parts
~~Miscellaneous Items~~
Labour
Paintwork Labour
Towing

Amount
~~8,770.00~~ 738
~~0.00~~
~~2,320.00~~ 150
~~1,280.00~~ 980
80.00

Gross Total (\$\$) ~~12,450.00~~ 996
+ GST 7.00% (\$\$) 871.50 696
Nett Amount (\$\$) 13,321.50

\$10,640.00

This claim is handled by: TOH TZE CHANG

Generated using Meritman e-Claims Internet Estimation & Adjusting System

Parts \$7384
Paintwork Labour \$980
Labour \$1500
Towing \$80

Total \$9944

(closed @ 65w)

Pis assist finalize the repair cost.

AIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 May 2019)
 Parts: 143 AUDI A4 1.8 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJR3790U)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER BUC /	0.00	0.00	*845.00 F
2	1		*FRONT BUMPER SIDE RETAINER LH nec /	0.00	0.00	*20.00 F
3	1		*FRONT BUMPER SIDE RETAINER RH nec /	0.00	0.00	*20.00 F
4	1		*FRONT BUMPER TOWING COVER mis /	0.00	0.00	*30.00 F
5	1		*FRONT BUMPER INNER SPONGE CRA /	0.00	0.00	*45.00 F
6	1		*FRONT BUMPER REINFORCEMENT DD /	0.00	0.00	*338.00 F
7	1		*FRONT BUMPER CLIPS nec /	0.00	0.00	*35.00 F
8	1		*FRONT NUMBER PLATE DEF /	0.00	0.00	*35.00 F
9	1		*FRONT GRILLE CRA /	0.00	0.00	*370.00 F
10	1		*FRONT FENDER LH BUC /	0.00	0.00	*351.00 F
11	1		*FRONT FENDER RH BUC /	0.00	0.00	*351.00 F
12	1		*BONNET BUC /	0.00	0.00	*715.00 F
13	1		*BONNET HINGES LH BT /	0.00	0.00	*33.00 F
14	1		*BONNET HINGES RH BT /	0.00	0.00	*33.00 F
15	1		*BONNET LOCK Jam /	0.00	0.00	*78.00 F
16	1		*BONNET INSULATOR nax	0.00	0.00	*123.00 F
17	1		*BONNET INSULATOR CLIPS nax	0.00	0.00	*80.00 F
18	1		*BONNET DAMPER DM /	0.00	0.00	*56.00 F
19	1		*FRONT DOOR RH Repair /	0.00	0.00	*F
20	1		*FRONT HEADLAMP LH SCR /	0.00	0.00	*620.00 F
21	1		*FRONT HEADLAMP RH CRA /	0.00	0.00	*620.00 F
22	1		*FRONT HEADLAMP LOWER BRACKET LH CRA /	0.00	0.00	*45.00 F
23	1		*FRONT HEADLAMP LOWER BRACKET RH CRA /	0.00	0.00	*45.00 F
24	1		*FRONT SUPPORT PANEL 7 CRA /	0.00	0.00	*477.00 F
25	1		*FRONT SUPPORT PANEL TOP GARNISH 8 CRA /	0.00	0.00	*52.00 F
26	1		*FRONT SUPPORT PANEL TOP GARNISH AIR INTAKE DUCT CRA /	0.00	0.00	*160.00 F
27	1		*AIR CON CONDENSER DD /	0.00	0.00	*390.00 F
28	1		*AIR CON CONDENSER AIR GUIDE LH 9 nux	0.00	0.00	*19.00 F
29	1		*AIR CON CONDENSER AIR GUIDE RH 9 nux	0.00	0.00	*19.00 F
30	1		*AIR CON CONDENSER FAN COWLING 9 nux	0.00	0.00	*163.00 F
31	1		*AIR CON CONDENSER FAN MOTOR 9 Jam /	0.00	0.00	*351.00 F
32	1		*AIR CON SUCTION PIPE 9 nux	0.00	0.00	*263.00 F
33	1		*AIR CON RETURN PIPE 9 nux	0.00	0.00	*284.00 F
34	1		*AIR CON DISCHARGE PIPE 9 BT /	0.00	0.00	*281.00 F
35	1		*RADIATOR 9 BT /	0.00	0.00	*364.00 F
36	1		*RADIATOR FAN COWLING 9 nux	0.00	0.00	*163.00 F
37	1		*RADIATOR FAN MOTOR 9 Jam /	0.00	0.00	*299.00 F
38	1		*AIR CLEANER BOX 9 CRA /	0.00	0.00	*270.00 F
39	1		*AIR CLEANER RESONATOR 9 nux	0.00	0.00	*95.00 F
40	1		*AIR CLEANER RESONATOR JOINT PIPE 9 nux	0.00	0.00	*65.00 F
41	1		*AIR CLEANER INTAKE DUCT 9 CRA /	0.00	0.00	*55.00 F
42	1		*CARBON GANISTER RH 9 nux	0.00	0.00	*212.00 F

F=Franchise part.

Total Parts (\$\$)

6,770.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

\$7384

Estimates on Miscellaneous Items

are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO CARRY-OUT BODY CAVITY PRESERVATION	New	40.00 ✓
2	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	89.00 40
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	60.00 X
4	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING & SANDING OF SURFACES, FINAL POLISHING & WAXING ARE ALSO AVAILABLE	New	1,100.00 900
<u>Labour Items</u>			
5	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	New	74.00 40
6	TO COMPUTER RESET AND RE-PROGRAM ALL FAULT CODE	New	350.00 120
7	TO PRESSURE TEST AIR CON CONDENSER AND RADIATOR FOR LEAKAGE	New	120.00 60
8	TO REMOVE & REFIT AIR CON COMPRESSOR, AIR CON MOTOR, CONDENSER, PIPES & VACUUM, INCLUDING REFILLING OF GAS	New	180.00 80
9	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS, TO READJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,600.00 1200

Gross Labour Cost (\$\$)

3,600.00

\$2440

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Huee Jin - LKK

16/5/19

4/5 7 days



Not Authorise

Excuse: \$600/-

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2019 Sendback Est	15 May 2019 16:48 S\$12,450.00	15 May 2019 17:22 Edit Adj Rpt	S\$6,500.00 Edit Estimates	S\$6,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: EDDEI RAHMAT BIN TAIB , ID: S7249124F									
Vehicle Reg. No.: SJR3790U		Date of Loss: 13/05/2019 15:00 - :59 [118 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 1201900012868		Policy/Cover Note No.: PNPV2018-00007724 (Comprehensive) Coverage: 22/06/2018 - 21/06/2019							
		Excess: S\$600.00							
Repairer: Yew Tee Automobile Tech Pte Ltd (HQ) Bldg 6 Woodlands Road 399F, Yew Tee Ind Estate, 678006 Woodlands - Tel: 67622081									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 27/05/2019]									
Driver/Custodian: HAFIDAH BINTE OTHMAN () , NRIC: S7302379C, Tel: +6591770492 Email:									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- FWD_SG (21/05/2019): Alert - Adj Mandate Approved (S\$6500.00) - SJR3790U - Claim Handler: Lionel Tan - FWD_SG (17/05/2019): Alert - Adj Mandate Maintained - SJR3790U - Claim Handler: Lionel Tan									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJR3790U (1201900012868)
OD
May 13 2019 3:00PM
[EDDEI RAHMAT BIN TAIB]
Yew Tee Automobile Tech Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 16:48	Repairer Estimates	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/05/19 15:34	Adjuster Immediate Advice	 Load HTM	☐
2	17/05/19 15:43	Adjuster Immediate Advice	 Load HTM	☐
3	21/05/19 11:04	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 16:50	Accident Photo	 Load JPG	☒
2	15/05/19 16:50	Accident Photo	 Load JPG	☒
3	15/05/19 16:50	Accident Photo	 Load JPG	☒
4	15/05/19 16:50	Accident Photo	 Load JPG	☒
5	15/05/19 16:50	Accident Photo	 Load JPG	☒
6	15/05/19 16:50	Accident Photo	 Load JPG	☒
7	15/05/19 16:50	Accident Photo	 Load JPG	☒
8	15/05/19 16:50	Accident Photo	 Load JPG	☒
9	15/05/19 16:50	Accident Photo	 Load JPG	☒
10	15/05/19 16:50	Accident Photo	 Load JPG	☒
11	15/05/19 16:50	Accident Photo	 Load JPG	☒
12	15/05/19 16:50	Accident Photo	 Load JPG	☒
13	15/05/19 16:50	Accident Photo	 Load JPG	☒
14	15/05/19 16:50	Accident Photo	 Load JPG	☒
15	15/05/19 16:50	Accident Photo	 Load JPG	☒
16	15/05/19 16:50	Accident Photo	 Load JPG	☒
17	15/05/19 16:50	Accident Photo	 Load JPG	☒
18	15/05/19 16:50	Accident Photo	 Load JPG	☒
19	15/05/19 16:50	Accident Photo	 Load JPG	☒
20	15/05/19 16:50	Accident Photo	 Load JPG	☒
21	15/05/19 16:50	Accident Photo	 Load JPG	☒
22	15/05/19 16:50	Accident Photo	 Load JPG	☒
23	15/05/19 16:50	Accident Photo	 Load JPG	☒
24	15/05/19 16:50	Accident Photo	 Load JPG	☒
25	15/05/19 16:50	Accident Photo	 Load JPG	☒
26	15/05/19 16:50	Accident Photo	 Load JPG	☒
27	15/05/19 16:50	Accident Photo	 Load JPG	☒
28	15/05/19 16:50	Accident Photo	 Load JPG	☒
29	15/05/19 16:50	Accident Photo	 Load JPG	☒
30	15/05/19 16:50	Accident Photo	 Load JPG	☒
31	15/05/19 16:50	Accident Photo	 Load JPG	☒
32	15/05/19 16:50	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
33	15/05/19 16:50	Accident Photo		☒
34	15/05/19 16:50	Accident Photo		☒
35	15/05/19 16:50	Accident Photo		☒
36	15/05/19 16:50	Accident Photo		☒
37	15/05/19 16:50	Accident Photo		☒
38	15/05/19 16:50	Accident Photo		☒
39	15/05/19 16:50	Accident Photo		☒
40	15/05/19 16:50	Accident Photo		☒
41	15/05/19 16:50	Accident Photo		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/05/19 09:03	General View		☒
2	17/05/19 09:03	General View		☒
3	17/05/19 09:03	General View		☒
4	17/05/19 09:03	General View		☒
5	17/05/19 09:03	General View		☒
6	17/05/19 09:03	General View		☒
7	17/05/19 09:03	General View		☒
8	17/05/19 09:03	General View		☒
9	17/05/19 09:03	General View		☒
10	17/05/19 09:03	General View		☒
11	17/05/19 09:03	General View		☒
12	17/05/19 09:03	General View		☒
13	17/05/19 09:03	General View		☒
14	17/05/19 09:03	General View		☒
15	17/05/19 09:03	General View		☒
16	17/05/19 09:03	General View		☒
17	17/05/19 09:03	General View		☒
18	17/05/19 09:03	General View		☒
19	17/05/19 09:03	General View		☒
20	17/05/19 09:03	General View		☒
21	17/05/19 09:03	General View		☒
22	17/05/19 09:03	General View		☒
23	17/05/19 09:03	General View		☒
24	17/05/19 09:03	General View		☒
25	17/05/19 09:03	General View		☒
26	17/05/19 09:03	General View		☒
27	17/05/19 09:03	General View		☒
28	17/05/19 09:03	General View		☒
29	17/05/19 09:03	General View		☒
30	17/05/19 09:03	General View		☒
31	17/05/19 09:03	General View		☒
32	17/05/19 09:03	General View		☒
33	17/05/19 09:03	General View		☒
34	17/05/19 09:03	General View		☒
35	17/05/19 09:03	General View		☒
36	29/05/19 09:44	Dismantled Parts		☒
37	29/05/19 09:44	Dismantled Parts		☒
38	29/05/19 09:44	Dismantled Parts		☒
39	29/05/19 09:44	Dismantled Parts		☒
40	29/05/19 09:44	Dismantled Parts		☒

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
41	29/05/19 09:44	Dismantled Parts		☒
42	29/05/19 09:44	Dismantled Parts		☒
43	29/05/19 09:44	Dismantled Parts		☒
44	29/05/19 09:44	Dismantled Parts		☒
45	29/05/19 09:44	Dismantled Parts		☒
46	29/05/19 09:44	Dismantled Parts		☒
47	29/05/19 09:44	Dismantled Parts		☒
48	29/05/19 09:44	Dismantled Parts		☒
49	29/05/19 09:44	Dismantled Parts		☒
50	29/05/19 09:44	Dismantled Parts		☒
51	29/05/19 09:44	Dismantled Parts		☒
52	29/05/19 09:44	Dismantled Parts		☒
53	29/05/19 09:44	Dismantled Parts		☒
54	29/05/19 09:44	Dismantled Parts		☒
55	29/05/19 09:44	Dismantled Parts		☒
56	29/05/19 09:44	Dismantled Parts		☒
57	29/05/19 09:44	Dismantled Parts		☒
58	29/05/19 09:44	Dismantled Parts		☒
59	29/05/19 09:44	Dismantled Parts		☒
60	29/05/19 09:44	Dismantled Parts		☒
61	29/05/19 09:44	Dismantled Parts		☒
62	20/06/19 13:33	Photo After Spray		☒
63	20/06/19 13:33	Photo After Spray		☒
64	20/06/19 13:33	Photo After Spray		☒
65	20/06/19 13:33	Photo After Spray		☒
66	20/06/19 13:33	Photo After Spray		☒
67	20/06/19 13:33	Photo After Spray		☒
Documentation			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 16:49	E-filed GIA report		
2	15/05/19 16:49	Claimant's NRIC		☒
3	15/05/19 16:49	Certificate of Insurance		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/05/19 15:43	ESTIMATE		
2	22/05/19 11:33	LUMP SUM LETTER		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19008641/JTD3E2

Date: 25/06/2019

REFERENCE

Insured/Claimant: EDDEI RAHMAT BIN TAIB Policy No: PNPV2018-00007724
Date of Loss: 13/05/2019 Nature of Claim: OD Claim No: 1201900012868

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR3790U**
Make & Model: AUDI A4, 1.8 (A) Engine No: CDH051484
Reg. Date: 22/06/2009 (Man. Year: 2009) Chassis No: WAUZZZ8K19A235292
Colour: Black Odometer: 215229 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$25,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,770.00	7,384.00	1,386.00	15.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,500.00	820.00	35.34
Paintwork Labour	1,280.00	980.00	300.00	23.44
Towing	80.00	0.00	80.00	100.00
Calculated Gross Total (S\$)	12,450.00	9,864.00	2,586.00	20.77
Approved Total (Overridden) (S\$)		6,500.00		
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	12,450.00	5,900.00	6,550.00	52.61
+ GST 7.00/7.00% (S\$)	871.50	413.00	458.50	52.61
Nett Amount (S\$)	13,321.50	6,313.00	7,008.50	52.61

INSPECTION

Date of Assignment: 15/05/2019 Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)
Date Inspected: 16/05/2019 Inspected At: Yew Tee Automobile Tech Pte Ltd (HQ)
Blk 6 Woodlands Road 399F,, Yew Tee
Ind Estate
Singapore 678006

Estimated Period of Repair: 7.0 days

Adjuster: ONG HWEE JIE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2019)
Parts: 143	AUDI A4 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJR3790U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Buckled	845.00 F	*845.00 F
2	1	*FRONT BUMPER SIDE RETAINER LH	Necessary	20.00 F	*20.00 F
3	1	*FRONT BUMPER SIDE RETAINER RH	Necessary	20.00 F	*20.00 F
4	1	*FRONT BUMPER TOWING COVER	Missing	30.00 F	*30.00 F
5	1	*FRONT BUMPER INNER SPONGE	Cracked	45.00 F	*45.00 F
6	1	*FRONT BUMPER REINFORCEMENT	Dented	338.00 F	*338.00 F
7	1	*FRONT BUMPER CLIPS	Necessary	35.00 F	*35.00 F
8	1	*FRONT NUMBER PLATE	Deformed	35.00 F	*35.00 F
9	1	*FRONT GRILLE	Cracked	370.00 F	*370.00 F
10	1	*FRONT FENDER LH	Buckled	351.00 F	*351.00 F
11	1	*FRONT FENDER RH	Buckled	351.00 F	*351.00 F
12	1	*BONNET	Buckled	715.00 F	*715.00 F
13	1	*BONNET HINGES LH	Bent	33.00 F	*33.00 F
14	1	*BONNET HINGES RH	Bent	33.00 F	*33.00 F
15	1	*BONNET LOCK	Jammed	78.00 F	*78.00 F
16	1	*BONNET INSULATOR	Not Necessary	123.00 F	*- F
17	1	*BONNET INSULATOR CLIPS	Not Necessary	30.00 F	*- F
18	1	*BONNET DAMPER	Damaged	56.00 F	*56.00 F
19	1	*FRONT DOOR RH	Repair	0.00 F	*- F
20	1	*FRONT HEADLAMP LH	Scratched	620.00 F	*620.00 F
21	1	*FRONT HEADLAMP RH	Cracked	620.00 F	*620.00 F
22	1	*FRONT HEADLAMP LOWER BRACKET LH	Cracked	45.00 F	*45.00 F
23	1	*FRONT HEADLAMP LOWER BRACKET RH	Cracked	45.00 F	*45.00 F
24	1	*FRONT SUPPORT PANEL	Cracked	477.00 F	*477.00 F
25	1	*FRONT SUPPORT PANEL TOP GARNISH	Cracked	52.00 F	*52.00 F
26	1	*FRONT SUPPORT PANEL TOP GARNISH AIR INTAKE DUCT	Cracked	160.00 F	*160.00 F
27	1	*AIR CON CONDENSER	Dented	390.00 F	*390.00 F
28	1	*AIR CON CONDENSER AIR GUIDE LH	Not Necessary	19.00 F	*- F
29	1	*AIR CON CONDENSER AIR GUIDE RH	Not Necessary	19.00 F	*- F
30	1	*AIR CON CONDENSER FAN COWLING	Not Necessary	163.00 F	*- F
31	1	*AIR CON CONDENSER FAN MOTOR	Jammed	351.00 F	*351.00 F
32	1	*AIR CON SUCTION PIPE	Not Necessary	263.00 F	*- F
33	1	*AIR CON RETURN PIPE	Not Necessary	234.00 F	*- F
34	1	*AIR CON DISCHARGE PIPE	Bent	281.00 F	*281.00 F
35	1	*RADIATOR	Bent	364.00 F	*364.00 F
36	1	*RADIATOR FAN COWLING	Not Necessary	163.00 F	*- F
37	1	*RADIATOR FAN MOTOR	Jammed	299.00 F	*299.00 F
38	1	*AIR CLEANER BOX	Cracked	270.00 F	*270.00 F
39	1	*AIR CLEANER RESONATOR	Not Necessary	95.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*AIR CLEANER RESONATOR JOINT PIPE	Not Necessary	65.00 F	*- F
41	1		*AIR CLEANER INTAKE DUCT	Cracked	55.00 F	*55.00 F
42	1		*CARBON CANISTER RH	Not Necessary	212.00 F	*- F
Total Parts (S\$)					8,770.00	7,384.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO CARRY-OUT BODY CAVITY PRESERVATION	New	40.00	40.00
2	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	80.00	40.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	60.00	0.00
4	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING & SANDING OF SURFACES, FINAL POLISHING & WAXING ARE ALSO AVAILABLE	New	1,100.00	900.00
Labour Items				
5	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	New	70.00	40.00
6	TO COMPUTER RESET AND RE-PROGRAM ALL FAULT CODE	New	350.00	120.00
7	TO PRESSURE TEST AIR CON CONDENSER AND RADIATOR FOR LEAKAGE	New	120.00	60.00
8	TO REMOVE & REFIT AIR CON COMPRESSOR, AIR CON MOTOR, CONDENSER, PIPES & VACUUM, INCLUDING REFILLING OF GAS	New	180.00	80.00
9	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO READJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,600.00	1,200.00
Gross Labour Cost (S\$)			3,600.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >