



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC: 201015366H

3RD PARTY CLAIM ESTIMATION

AIG Aisa Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way #07-16

Singapore 079120

Vehicle number	YP9975Y
Make / Model	MITSUBISHI / CANTER
Chassis number	FEB21EA25350
Accident date	10 May 2019
Reference	KK1905-27

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS			
1	FRONT BUMPER Bnc	1069.50	✓
1	FRONT BUMPER REINFORCEMENT NH	431.02	X
2	FRONT BUMPER SIDE COVER N/S chustayed o/s NH	328.29	29825.70 ✓
1	FRONT CENTRE PANEL Bnc	140.30	✓
2	FRONT CORNER PANEL N/S cut o/s NH	420.90	✓ 210.45
1	FRONT WIPER GARNISH Chut mandy broken	420.90	✓
1	FRONT CENTRE GRILLE broken	618.32	1210.95 ✓
1	FRONT GRILLE EMBELM cut	169.05	✓
1	FRONT SUPPORT PANEL HS	781.21	X
2	FRONT HEADLAMP N/S broken o/s mandy broken	1330.42	421621.50 ✓
2	FRONT BUMPER BRACKET Vst	321.40	✓
2	FRONT BUMPR CHASSIS BRACKET Vst N/S o/s NH	201.90	✓ 100.95
2	FRONT BUMPER CORNER PANEL N/S Dental o/s NH	563.80	✓ 281.90
1	FRONT WINDSCREEN LOWER PANEL repair	871.60	X
2	FRONT HEADLAMP CORNER COVER HS	535.90	X
2	FRONT SIGNAL LAMP N/S broken o/s mandy broken	621.00	✓
1	FRONT LH DOOR STEP crack	140.30	✓
1	FRONT LH DOOR PANEL Vst	2300.00	✓ 2001.44
1	FRONT LH CHASSIS FRAME repair	3277.50	X
1	FRONT BRAKE PUMP NH	2068.85	X
1	FRONT BRAKE PUMP BRACKET NH	345.50	X
1	FRONT CLUTCH PUMP NH	276.00	X
1	FRONT AIRCON COOLING COIL / AIRCON BLOWER broken	2921.00	✓ 1463.32
1	FRONT AIRCON COOLING COIL COVER Dental	207.69	✓
1	FUSE BOX COVER NH	236.44	X
1	AIRCON CONDENSER Vst	1545.60	✓ 1345.50
1	AIRCON FAN COWLING NH	1391.50	X
1	DASHBOARD mandy broken	2279.30	✓ 2208.10
1	DASHBOARD BRACKET NH	201.50	X
1	DASHBOARD INNER BRACKET Vst	258.10	✓
1	METER NH	2185.00	X
1	METER COVER NH	368.43	X
1	AIRCON CONTROL UNIT NH	2405.90	X
1	LH DOOR PILLAR Bnc	1725.00	✓ 1482.40
2	LH DOOR HINGE NH	372.60	X
1	LH DOOR LOWER RUBBER NH	152.30	✓
1	LH SIDE MIRROR NH	116.15	X
1	LH SIDE MIRROR SUPPORT Vst	554.30	✓ 282.85
1	LH SIDE MIRROR SUPPORT COVER Dem	48.30	✓

1	FRONT WIPER MOTOR NH	776.25 X
2	FRONT WIPER ARM Vst	168.59 ✓
1	TAILGATE Rev	3451.30 X
1	FLOOR PANEL NH	3240.80 X
1	TAILGATE STEP GARNISH broken	510.30 ✓
1	TAILGATE REINFORCEMENT broken	784.90 ✓
1	TAILLAMP LH crack	226.25 ✓
1	TAILGATE LOCK NH	367.40 X
2	TAILGATE HINGE NH	231.70 X
1	TAILGATE RUBBER N3	181.30 X
		45522.68
Less 10 %		4552.27
Subtotal		40970.41

16892.82
15203.53

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
Balance B/F		40970.41
1 SET	FRONT BUMPER CLIP NH	60.00 X
1	FRONT NUMBER PLATE Vst	80.00 } 80/-
1	REAR NUMBER PLATE Vst	80.00 }
1	STICKER - 60 KM/H Nue	60.00 20/-
1	STICKER - 22 PAX Nue	60.00 20/-
1	STICKER - COMPANY NAME Nue	100.00 80/-
1	STICKER - TEL NUMBER Nue	80.00 30/-
1	FRONT BUMPER STICKER NH	120.00 X
1	WINDSCREEN SEALANT Nue	150.00 40/-
1	BRAKE FULID NH	60.00 X
Subtotal		850.00
Balance C/F		41820.41
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
Balance B/F		41820.41
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	REMOVE AND REPLACE FRONT WINDSCREEN	150.00 120/-
3	REMOVE AND REPLACE FRONT DASHBOARDS	500.00 180/-
4	REMOVE AND REFIT LINING, TR sa	200.00 120/-
5	REMOVE AND RENEW AIRCON COOLING COIL	200.00 80/-
6	REMOVE AND RENEW AIRCON BLOWER	200.00 30/-
8	TRANSFER PARTS, ATTACHMENT FROM OLD DOOR TO NEW	200.00 60/-
9	MOUNT VEHICLE ON BENCH FOR CHASSIS REPLACEMENT	200.00 NH
10	PANEL BEATING ON AFFECTED AREAS	3000.00 1400/-
11	SPRAY PAINTING ON AFFECTED AREAS	2000.00 1200/-
12	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
Subtotal		6860.00
Grand total		48680.41

15/05/2019 @ 1030m

N/A Antenn

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

14 days.

1873353

2/3 15000/-