

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022259
Heng Yeow Kwang

Page 1 of 2
Your ref. TP-SKL 3108K AXA
Job No. 70502
Our ref. 19.05.25
Payment
Date 15/5/2019

Attn

Vehicle No SGZ 7977R
Vehicle Model : Toyota Wish
Accident on ... 11/5/2019

Not Withheld
Running B4paim
4 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear tailgate	1,175.90	25.00	881.93 ✓
1.00	Pc	Rear bumper	491.90	25.00	368.93 ✓
1.00	Pc	Rear Elegance emblem	42.80	25.00	32.10 ✓
1.00	Pc	Rear Valve Matic emblem	45.40	25.00	34.05 ✓
1.00	Pc	Rear logo emblem	66.20	25.00	49.65 ✓
1.00	Set	Rear windscreen moulding	125.60	25.00	94.20 ✓
Labour & Misc:					
1.00		To remove + refix rear windscreen	140.00		140.00 ✓
1.00		To supply sealant	40.00		40.00 ✓
1.00		To transfer rear parking sensor	40.00		40.00 ✓
1.00		To knock dents on rear end panel and renew of parts	650.00		650.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和失铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022259
Heng Yeow Kwang

Page 2 of 2
Your ref. TP-SKL 3108K AXA
Job No. 70502
Our ref. 19.05.25
Payment
Date 15/5/2019

Attn

Vehicle No SGZ 7977R
Vehicle Model : Toyota Wish
Accident on ... 11/5/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To spray paint	650.00	550/	650.00

Sub-Total 2,980.86
GST 7.00% 208.66
Total S\$ 3,189.52

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."