

18/5/19

Insured Liability : 0 % Final ? Yes / No

Liability,

SS	180.00	Name 2:	G04
----	--------	---------	-----

COPY SENT 4-10-9

10/10/2010 10:00:00 AM

Name 2:	
---------	--

PREMIUM AUTOMOBILES PTE LTD
GOH SIAK MING

Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC / Incident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 hrs days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLJ32m.Yr Regn: 2016

December

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 Sedan c.c. 1395Colour: White A/C: Insured / Std / Nil / NASp. Reading: 30667 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WAW2228V5J1008931Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim orTyre Size: F: 245/40R18R: 245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 21/05/19Survey held at: PremiumDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPALG.

P/P 23,813.60CR60: 23,752.40 (60%)

mv:

pv:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS. SI

Photos

Others

TOTAL

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0634/2019/GW
Date	:	17-May-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : SLP 1887 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Goh Siak Ming
Address	:	42 Hillcrest Road
	:	Singapore 288917
Telephone	:	HP +65 91183160
Type of Claim	:	Third Party Claims
Policy No.	:	SI18V14537/VPC/R02
Vehicle No	:	SLJ 32 M
Model Code	:	A4 Sedan 1.4 TFSI
Model / Year	:	12-09-2017
Engine No	:	CHZ 521068
Chassis No	:	WAUZZZ8V5J1008931
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	14-May-19
Place of Accident	:	Start of Hillcrest Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 32 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	✓
2	To dismantle and renew rear bumper. To inspect rhs tail lamp panel, end panelling and rhs rear fender. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00	500-
3	To respray rear bumper and rhs rear fender.	\$ 1,700.00	550 - 1,100 x ✓
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 3,302.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 32 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>replaced</i>	\$ 2,015.00	✓ 1,612
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 66.00	x
3	REAR BUMPER SECURING STRIP <i>? MV</i>	\$ 203.00	X X
4	REAR BUMPER SPOILER <i>new</i>	\$ 227.00	+
5	REAR LIGHT REFLECTOR-RH <i>changed</i>	\$ 38.00	✓ 29.68
6	REAR BUMPER CARRIER <i>new</i>	\$ 819.00	+
7	REAR BUMPER SEAL <i>new</i>	2 \$ 25.00	+
8	REAR BUMPER GUIDE SECTION-RH <i>new</i>	\$ 41.00	+
9	REAR BUMPER UPPER GUIDE SECTION-RH/LH <i>new</i>	2 \$ 40.00	+
10	REAR SENSOR <i>new</i>	2 \$ 462.00	+
11	REAR SENSOR SEAL RING <i>new</i>	4 \$ 12.00	+
12	LED TAILLIGHT-RH OUTER/INNER <i>new</i>	2 \$ 1,862.00	+
13	LED TAILLIGHT TRIM-RH OUTER/INNER <i>new</i>	2 \$ 54.00	+
14	SUNDRIES <i>new</i>	\$ 400.00	? 19.92
TOTAL SPARE PARTS CHARGES		: \$ 6,264.00	
TOTAL LABOUR CHARGES		: \$ 3,302.00	
GRAND TOTAL		: \$ 9,566.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 21/05/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days

1. All claimants must notify
the Repairs of the following:

- To survey pre-repair spray painting
- To survey damaged parts during resurvey
- These notes are subject to confirmation
- The entire survey is on a "Without Prejudice" basis
- For part modification is allowed
- Supplementary items must be resurveyed and
subject to final approval from Insurance Company

Acknowledged by Repairs
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 32 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew rear bumper. To inspect rhs tail lamp panel , end panelling and rhs rear fender. Re-organise crash management components. Reinstall all parts removed.		\$ 1,050.00	\$ 500.00
3	To respray rear bumper and rhs rear fender.		\$ 1,700.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 3,302.00</u>	<u>\$ 2,152.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 32 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 2,015.00	\$ 1,612.00
2	REAR BUMPER FIXING PARTS	\$ 66.00	
3	REAR BUMPER SECURING STRIP	\$ 203.00	
4	REAR BUMPER SPOILER	\$ 227.00	
5	REAR LIGHT REFLECTOR-RH	\$ 38.00	\$ 29.68
6	REAR BUMPER CARRIER	\$ 819.00	
7	REAR BUMPER SEAL	2 \$ 25.00	
8	REAR BUMPER GUIDE SECTION-RH	\$ 41.00	
9	REAR BUMPER UPPER GUIDE SECTION-RH/LH	2 \$ 40.00	
10	REAR SENSOR	2 \$ 462.00	
11	REAR SENSOR SEAL RING	4 \$ 12.00	
12	LED TAILLIGHT-RH OUTER/INNER	2 \$ 1,862.00	
13	LED TAILLIGHT TRIM-RH OUTER/INNER	2 \$ 54.00	
14	SUNDRIES	\$ 400.00	\$ 19.92
TOTAL SPARE PARTS CHARGES		: \$ 6,264.00	\$ 1,661.60
TOTAL LABOUR CHARGES		: \$ 3,302.00	\$ 2,152.00
GRAND TOTAL		: \$ 9,566.00	\$ 3,813.60

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Friday, 24 May 2019 4:21 PM
To: bettypu@pomin.com.sg
Cc: Admin A
Subject: ACCIDENT INVOLVING SLP 1887A AND SLJ 32M ON 14/05/19

PU XIA
Policy Holder

Dear Madam,

ACCIDENT INVOLVING SLP 1887A AND SLJ 32M ON 14/05/19

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Vic (LKKAUTO)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Tuesday, 13 August, 2019 10:46 AM
To: Vic (LKKAUTO)
Cc: 'Chang Chee Sing'; jiayee.yap@premiumauto.com.sg; Adrian Ling (LKKAUTO); Admin A; 'Boo seng yak'; 'Nora Khai PA'
Subject: RE: FINAL REVISION - SLJ32M - TP AIG - SURVEYED 21 MAY 19

Dear Vic,

For labour 3 respray rhs rear fender, our colleague Kee Siang has spoken with Adrian and approved on 27 May, please check with Adrian.

Please confirm repair cost of \$3813.60 @ 3 days.

Your early closure is well appreciated.

Thanks & Best Regard

Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]

Sent: Thursday, 8 August, 2019 12:09 PM

To: Carrine Leong <carrine.leong@premiumauto.com.sg>

Cc: 'Chang Chee Sing' <claims@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>

Subject: RE: FINAL REVISION - SLJ32M - TP AIG - SURVEYED 21 MAY 19

Without Prejudice

Dear Carrine,

We refer to your below email.

Our surveyor had recommended COR @ \$3,263.60 with 3 Days.

BREAKDOWN OF PAYMENT

Vehicle No: S25 32 M

Accident on 14/5/19 at Start of Hillcrest Road

Involving vehicle/s SIP 1887 A

1) Repair cost \$ 4,080.55

Payable to: Premium Automobiles Pte Ltd

2) GIA/LTA search fee \$ 2.00

Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or Rental Car \$ 180.00

Payable to: Goh Siak Ming

4) Medical fees \$ _____

Payable to: _____

5) Others \$ _____

Payable to: _____

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189); Motor Vehicles (Third-Party Risks And Compensation) Rules, 1960; Road Transport Act, 1987 (Malaysia); Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Name of Policyholder:		Certificate No.:
GOH SIAK MING		SI18V14537/ VPC / R02
Date of Issue:	Effective Date of Commencement:	Date of Expiry:
29 Nov 2018	27 Dec 2018 00:00	26 Dec 2019 23:59
Registration No.:	Chassis No.:	Type of Certificate:
SLJ32M	WAUZZZF48HA066682	MX1

Persons or Classes of Persons entitled to drive*:

- A) The Policyholder.
- B) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

Limitations as to use:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

- A) Use for hire or reward.
- B) Use for racing, pace-making, reliability trials or speed-testing.
- C) Use for the carriage of goods (other than samples) in connection with any trade or business.
- D) Use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).



For and on behalf of
LIBERTY INSURANCE PTE LTD
Approved Insurers

For Information Only:

Coverage(s):	Comprehensive, Unlimited Windscreen, Buy Up Excess (From \$800 To \$1,500)
Sum Insured:	MARKET VALUE AT THE TIME OF LOSS
Excess:	Section I: S\$1500, Additional Excess for Young & Inexperienced Drivers: S\$3000, Windscreen Excess: S\$100
Name of Finance Company:	UNITED OVERSEAS BANK LIMITED
Name of Producer:	PREMIUM LEASING PTE LTD (A1704-2)

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: CC3/AIG19008843/ja3 / SLP 1887 A

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/TP/0634/2019/KK

6 Sep 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLJ 32 M, Audi A4 SEDAN 1.4 TFSI.

With reference to the above-mentioned vehicle, no. **SLJ 32 M**, claimant, **Mr. Goh Siak Ming**, please find the related document as per attached.

1. A copy of the Original invoice no. 85014209 – S\$ 4,080.55
2. A copy of Authorization to Act duly signed by client
3. A copy of the Release Voucher attached
4. A copy of Breakdown of Payment attached
5. Loss of Use - S\$ 180.00 (S\$60.00 x 3 working days)
6. GIA Search Fee – S\$ 2.00

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLJ 32 M



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

30 AUGUST 2019

**PU XIA
530 JOO CHIAT ROAD
#17-03
SINGAPORE 427710**

Dear Sir/Madam,

**OUR REF : CC3/AIG19008843/Aha3
YOUR REF : SLP 1887A**

**ACCIDENT INVOLVING SLP 1887A AND SLJ 32M ALONG HILLCREST ROAD ON
14.05.2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SLJ 32M against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2096 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)


AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, GOH SIAK MING (the third party claimant) of 42 HILLCREST ROAD
S(288917) (address), owner of SLJ 32 M (vehicle no.)
hereby authorize PREMIUM AUTOMOBILES PTE LTD ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SLJ 32 M that was damaged pursuant to the accident which occurred on 14/05/2019
(date) along START OF HILLCREST ROAD (location) involving vehicle no/s
SLP 1887 A ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 3 (day) of June (month) 2019 (year)

Goh Siau Ming


Signed by "the third party claimant"
(with chop if applicable)




Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, PREMIUM AUTOMOBILES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 4,080.55 (Repair Cost), S\$ 180.00 (Loss of ~~rental~~ use), S\$ 2.00 (Disbursement), for vehicle no. SLJ 32 M that was damaged pursuant to the accident which occurred on 14/05/2019 (date) along START OF HILLCREST ROAD (location) involving vehicle no/s SLP1887A. This is pursuant to the inspection conducted on 21/5/19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner GOH SIAK MING ("the third party claimant") of vehicle no. SLJ 32 M make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLJ 32 M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 19 (day) of 09 (month) 2019 (year)



LWP

Signed by appointed surveyor



[Signature]

Signed by "the workshop" (with chop)

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
65 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 1 13:58

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014209 Date : 05/09/2019 Order : SLJ0032M Term : 30	Account: A0006 (T) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
Regn No: SLJ0032M (V 31639) Model: A4 SEDAN 1.4 TFSI S tronic You have been assisted by :- UB-Nora	Regn Date: 27/12/2016 Chassis: WAUZZZF48HA066682 (11)	Mileage: 33880 Engine: CVN 024223 Dept: U

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER.TO INSPECT RHS TAIL LAMP PANEL,END PANNELLING AND RHS REAR FENDER.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER AND RHS REAR FENDER	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8W5807067A GRU	COVER(LAST)	1.00	2015.00	1,612.00
X	A8W5807890	GUIDE	1.00	19.90	15.92
X	A8W0945106C	(SK) REFLECTOR	1.00	37.10	29.68
X	AWHT007374	(SK) PIN	2.00	2.50	4.00

Parts 1,661.60
Labour 0.00
Sublet 2,152.00
Menus 0.00
Lubricant 0.00



Sub-Total	3,813.60
7% GST	266.95
Grand Total	4,080.55

Received by

For & on behalf of
Premium Automobiles Pte Ltd



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-076448

Date of Request: 14/05/2019

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd
55 Ubi Road 1
Singapore 408699

Dear Sir/Madam,

Enquiry Date 14/05/2019
Enquiry By Lim Kee Siang
TP Vehicle No. SLP1887A
Accident Date 14/05/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLP1887A	AIG Asia Pacific Insurance Pte. Ltd.	29/05/2018-28/05/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-076448

Date of Request: 14/05/2019

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd
55 Ubi Road 1
Singapore 408699

Dear Sir/Madam,

Enquiry Date 14/05/2019
Enquiry By Lim Kee Siang
TP Vehicle No. SLP1887A
Accident Date 14/05/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 May 2019 Edit Reg		21 May 2019 00:00 Edit Adj Rpt	S\$3,813.60 Edit Estimates	S\$3,813.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	PU XIA, ID: 57188474								
Main Claimant:	GOH SIAK MING, ID: 57905373B								
Vehicle Reg. No.:	SLJ32M	Date of Loss: 14/05/2019 07:00 - :59 [28 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 0543536255SG	Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured):	SLP1887A	Policy No. (Claimant): SI18V14537/VPC/R02							
		Excess:							
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 29/05/2019]								
ASSOCIATED MAIL RECEIVED									
		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLJ32M (0543536255SG)
[SLP1887A]
TP
GOH SIAK MING
May 14 2019 7:00AM
[PU XIA]
Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/08/19 15:23	General View		Load JPG	<input checked="" type="checkbox"/>
2	30/08/19 15:23	General View		Load JPG	<input checked="" type="checkbox"/>
3	30/08/19 15:23	General View		Load JPG	<input checked="" type="checkbox"/>
4	30/08/19 15:23	General View		Load JPG	<input checked="" type="checkbox"/>
5	30/08/19 15:23	General View		Load JPG	<input checked="" type="checkbox"/>
6	30/08/19 15:23	General View		Load JPG	<input checked="" type="checkbox"/>
7	30/08/19 15:23	General View		Load JPG	<input checked="" type="checkbox"/>
8	30/08/19 15:23	General View		Load JPG	<input checked="" type="checkbox"/>
9	30/08/19 15:23	General View		Load JPG	<input checked="" type="checkbox"/>
10	30/08/19 15:23	General View		Load JPG	<input checked="" type="checkbox"/>
11	30/08/19 15:23	General View		Load JPG	<input checked="" type="checkbox"/>
12	30/08/19 15:23	General View		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/05/19 19:43	TP ESTIMATE		Load PDF	
2	18/05/19 19:43	TP GIA REPORT		Load PDF	
3	22/05/19 19:02	TP ESTIMATE - MARKED		Load PDF	
4	30/08/19 15:44	LETTER TO OI		Load PDF	
5	27/09/19 11:35	WORKSHOP INVOICE		Load PDF	
6	27/09/19 11:35	AUTHORISATION TO ACT FORM		Load PDF	
7	27/09/19 11:35	Release Voucher		Load PDF	
8	27/09/19 11:35	GIA SEARCH		Load PDF	
9	27/09/19 11:35	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	21/05/19 10:47	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLP1887A (Insd veh)	Model:	AUDI A4 1.4 TFSI S TRONIC (A)
	SLJ32M (TP veh)		
Date of Accident:	14/05/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	10,235.62
Final Repair Cost	:	\$	4,080.55
Loss of Use	:	\$	180.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,262.55

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/~~No~~ BOLA Scenario No: 27

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 4,082.55
2)	Goh Siak Ming	:	\$ 180.00
3)		:	\$

JOANNE LEE KHANG MIN

27 Sep
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19008843/AHA3Q2

Date: 27/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SLJ32M

Insured Vehicle No : SLP1887A

Date of Loss: 14/05/2019

Nature of Claim: TP

Claim No: 0543536255SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ32M

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A)

Engine No: CVN024223

Reg. Date: 27/12/2016 (Man. Year: 2016)

Chassis No: WAUZZZF48HA066682

Colour: White

Odometer: 30667 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 245/40 R18

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,264.00	1,661.60	4,602.40	73.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,302.00	2,152.00	1,150.00	34.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,566.00	3,813.60	5,752.40	60.13
+ GST 7.00/7.00% (S\$)	669.62	266.95	402.67	60.13
Nett Amount (S\$)	10,235.62	4,080.55	6,155.07	60.13
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,262.55		

INSPECTION

Date of Assignment: 21/05/2019

Date Inspected: 21/05/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,015.00 FS	*1,612.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	66.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	203.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	227.00 FS	*- FS
5	1		*REAR LIGHT REFLECTOR -RH	Cracked	38.00 FS	*29.68 FS
6	1		*REAR BUMPER CARRIER	Not Necessary	819.00 FS	*- FS
7	2		*REAR BUMPER SEAL	Not Necessary	25.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION -RH	Not Necessary	41.00 FS	*- FS
9	2		*REAR BUMPER UPPER GUIDE SECTION -RH/LH	Not Necessary	40.00 FS	*- FS
10	2		*REAR SENSOR	Not Necessary	462.00 FS	*- FS
11	4		*REAR SENSOR SEAL RING	Not Necessary	12.00 FS	*- FS
12	2		*LED TAILLIGHT -RH OUTER /INNER	Not Necessary	1,862.00 FS	*- FS
13	2		*LED TAILLIGHT TRIM -RH OUTER/INNER	Not Necessary	54.00 FS	*- FS
14	1		*SUNDRIES	Necessary	400.00 FS	*19.92 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					6,264.00	1,661.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SESOR ,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .TO INSPECT RHS TAIL LAMP PANEL ,END PANELLING AND RHS REAR FENDER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER	New	1,700.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			3,302.00	2,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >