

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0634/2019/GW
Date : 17-May-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : SLP 1887 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Goh Siak Ming
Address : 42 Hillcrest Road
: Singapore 288917
Telephone : HP +65 91183160
Type of Claim : Third Party Claims
Policy No. : SI18V14537/VPC/R02
Vehicle No : **SLJ 32 M**
Model Code : A4 Sedan 1.4 TFSI
Model / Year : 12-09-2017
Engine No : CHZ 521068
Chassis No : WAUZZZ8V5J1008931
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-May-19
Place of Accident : Start of Hillcrest Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 32 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>del d</i>	\$ 2,015.00	✓
2	REAR BUMPER FIXING PARTS <i>neu</i>	\$ 66.00	x
3	REAR BUMPER SECURING STRIP <i>?</i>	\$ 203.00	?
4	REAR BUMPER SPOILER <i>neu</i>	\$ 227.00	x
5	REAR LIGHT REFLECTOR-RH <i>canb d</i>	\$ 38.00	✓
6	REAR BUMPER CARRIER <i>{ neu</i>	\$ 819.00	+
7	REAR BUMPER SEAL	2 \$ 25.00	+
8	REAR BUMPER GUIDE SECTION-RH <i>neu</i>	\$ 41.00	+
9	REAR BUMPER UPPER GUIDE SECTION-RH/LH <i>neu</i>	2 \$ 40.00	+
10	REAR SENSOR <i>{ neu</i>	2 \$ 462.00	+
11	REAR SENSOR SEAL RING	4 \$ 12.00	+
12	LED TAILLIGHT-RH OUTER/INNER <i>{ neu</i>	2 \$ 1,862.00	+
13	LED TAILLIGHT TRIM-RH OUTER/INNER	2 \$ 54.00	+
14	SUNDRIES <i>?</i>	\$ 400.00	?
TOTAL SPARE PARTS CHARGES		: \$ 6,264.00	
TOTAL LABOUR CHARGES		: \$ 3,302.00	
GRAND TOTAL		: \$ 9,566.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 21/05/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant