

Not Authorized  
Putty & Paint  
2 days



# ESTIMATE TO REPAIR

VEHICLE NO. : SLL 4881 S  
MAKE : AUDI  
MODEL : Q3 1.4 TFSI S TRONIC  
YEAR : 2017  
CHASSIS NO : WAUZZZ8U9HR060095

SURVEYOR NAME : Kenneth (LKK)  
DATE OF SURVEY : 28th May 2019  
TIME OF SURVEY :

DATE : 18-May-19  
DATE OF ACCIDENT : 15-May-18  
THIRD PARTY REF : SJV 7683 Z / AIG

| No.    | Parts Description/ Labour               | Type | Unit Price | Nett Item Amt    | Amount      |
|--------|-----------------------------------------|------|------------|------------------|-------------|
| 1 pc   | Rear Bumper                             |      |            | Bu 1pc \$ 950.00 | ✓           |
| 1 pc   | Rear Bumper Reinforcement               |      |            | \$ 450.00        | ✓           |
| 1 pc   | Rear Bumper Lower Garnish               |      |            | \$ cm 350.00     | ✓           |
| 2 pcs  | Rear Bumper Sensor                      |      | \$ 200.00  | \$ 400.00        | ✓           |
|        |                                         |      |            | \$ 2,150.00      |             |
|        | Less 10%                                |      |            | \$ 215.00        |             |
|        |                                         |      |            | \$ 1,935.00      |             |
|        | To putty and spray painting             |      |            | \$ 300.00        | 2501        |
|        | To check rear wiring and replace sensor |      |            | \$ 120.00        | 601         |
|        | Labour Charges                          |      |            | \$ 250.00        | ✓           |
| TG/RA- | Total                                   |      |            |                  | \$ 2,605.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd