

22/03/2001

ASS. REC. BY:

REF: CS/FC119008911/K9.d3ⁿ²

Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Sthara

of

FC1

Date/Time: 21.5.19 4.26 p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: GBC 824A

Insured: SHC 06925

at Workshop m/s City Auto

Tel: 64531235

of BIC 8 Sin ming Road # 01-58160162

Policy No:

Claim No: D19003324 MP514

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 16.5.2019

22.5.2019

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 21.5.19 4.51 p.m

Person Contacted: Veronica Law

Vehicle-IN/OUT

Date/Time	Action/Instruction
	Tohmatil (✓)
	GBC 824A - CCB / AIG 13018 619 / tsb292
	SHC 06925-X
23/5/19 @ 3.58pm	verified to Sthara by email.
30/5	61 Lyr 8380d Confirmed (Red #3563.95, 48%)

(08/11/13)

REF FCI

ASS. REC. BY:

ASSIGNMENT

From:

Date: 22.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 824 A

at Workshop m/s City Auto

of BK160 sin ming Drive #05-01

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 817k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

sup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBC 824 A

Yr Regn: 03.11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS NV200

G.C.

1461

Colour:

Pilm

A/C:

Insured / Std / NI / NA

Sp.Reading

173534

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN14BAM 2011 0003194

Gen. Cond:

Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70R14

R:

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

16/5/19

D.O.I.

22/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 30 MAY 2019

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TP

3800

150

50

50+50

21

321



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003324MFSH

Date: 23 May 2019

Our Ref: CS/FCI19008911/Kqd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBC 824A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/05/2019 at the premises of M/s CITY AUTO, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 6,810.11</u> .
Revised Estimate Amount	: <u>S\$ 3,439.53</u> .
"Check" Items Amount	: <u>S\$ 940.62</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	21-05-2019	Our Ref No.	D19003324MFSH
Accident Date	16-05-2019	Claim Type.	Third Party
Insured Vehicle	SHC0692S	Third Party Vehicle.	GBC824A
Survey Location	BLK 8 SIN MING ROAD #01-58/60/62 SIN MING IND EST		
Contact Person.	VRONICA LAW		
Contact No.	64531235/ 0	Fax No.	64537344
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CITY AUTO PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	SITHARA		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 23 May 2019 3:58 PM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'Sithara'
Subject: RE: SURVEY ASSESSMENT - D19003324MFSH/1
Attachments: CSFC19008911Kqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of GBC 824A.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 21 May 2019 4:49 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19003324MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 21 May, 2019 4:26 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003324MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	GBC824A
Vehicle Type:	A50 - Goods (Closed) Van/Van Panel (Delivery)
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5L MT ABS AIRBAG 2WD 6DR
Chassis No.:	JN1YBAM20U0003194
Propellant:	Diesel
Engine No.:	K9KF276D099372
Engine Capacity:	1461 cc
Maximum Power Output:	-
Maximum Laden Weight:	2000 kg
Unladen Weight:	1280 kg
Year Of Manufacture:	2010
Original Registration Date:	28 Mar 2011
Lifespan Expiry Date:	27 Mar 2031
COE Category:	C - Goods Vehicle & Bus
Quota Premium:	\$28,589.00
COE Expiry Date:	27 Mar 2021
Road Tax Expiry Date:	27 Sep 2019
Inspection Due Date:	27 Mar 2020
Intended Transfer Date:	28 May 2019
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

INDIA INTERNATIONAL INSURANCE PTE LTD

NO. 64
CECIL ST
IOB BLDG
SINGAPORE 049711

Contact : -

Fax No. : 6225 7743

*Not Authorized
11/2/19 83800
Heavy After Paint*

Estimate : QUOT201905-000376(00)

Date : 18/05/2019

Vehicle No. : GBC824A

Make/Model : NISSAN NV200 15L MT ABS
AIRBAG 2WD 6DR

Mileage (km) : 0

Chassis No. : JN1YBAM20U0003194

Accident Date : 16/05/2019 00:00:00

Claim No. : SHC692S

Reference : GBC824A

Policy No. : D-19092991MFCV/1

S/No	Particular	Quantity	Unit Price	Amount S\$
NET ITEMS :				
				<i>5 days</i>
1	Rear RH door	1.0	960.90	<i>Bz</i> 960.90 ✓
2	Rear LH door	1.0	1,281.10	<i>Bz</i> 1,281.10 ✓
3	Rear bumper	1.0	481.70	<i>Bz</i> 481.70 ✓
4	Rear door rubber	2.0	96.40	<i>Sm</i> 192.80 X
5	Rear bumper reflector	2.0	67.60	<i>Sm</i> 135.20 X
6	Rear door lock	1.0	261.00	<i>n</i> 261.00 X
7	RH door hinges	2.0	184.60	<i>n</i> 369.20 X
8	LH door hinges	2.0	184.60	<i>n</i> 369.20 X
9	Rear end panel outer	1.0	211.80	<i>Bz</i> 211.80 ✓
10	Rear end panel inner	1.0	544.00	<i>n</i> 544.00 X
11	Emblem - Nv200	1.0	68.00	<i>n</i> 68.00 ✓
12	Emblem - Logo	1.0	65.00	<i>n</i> 65.00 ✓
13	Emblem - DCI	1.0	65.00	<i>n</i> 65.00 ✓
14	Tail lamp	2.0	236.50	<i>Sm</i> 473.00 X
List Total :				5,477.90
10% Discount S\$				547.79
				4,930.11
SPECIAL NET :				
1	Sticker - 70Km/h	1.0	20.00	<i>n</i> 20.00 <i>15sm</i>
2	Sticker - 5 pax	1.0	20.00	<i>n</i> 20.00 <i>15sm</i>
3	Windscreen sealant	2.0	40.00	<i>n</i> 80.00 ✓
SPECIAL NET Total S\$:				120.00
LABOUR :				
	* To remove and install rear windscreen glass	2.0	80.00	<i>100h</i> 160.00
	-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	750.00	<i>600h</i> 750.00 ?
	- Spray painting on affected & replace parts	1.0	850.00	<i>600h</i> 850.00
				1,760.00

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis.
• No legal action may be taken
• Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

INDIA INTERNATIONAL INSURANCE PTE LTD

NO. 64
CECIL ST
IOB BLDG
SINGAPORE 049711

Contact : -

Fax No. : 6225 7743

Estimate : QUOT201905-000376(00)

Date : 18/05/2019
Vehicle No. : GBC824A
Make/Model : NISSAN NV200 1.5L MT ABS
AIRBAG 2WD 6DR
Mileage (km) : 0
Chassis No. : JN1YBAM20U0003194
Accident Date : 16/05/2019 00:00:00
Claim No. : SHC692S
Reference : GBC824A
Policy No. : D-19092991MFCV/1

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

E. & O.E.

Total S\$:	6,810.11
GST 7% S\$:	476.71
Amount Due S\$:	<u>7,286.82</u>


for CITY AUTO PTE LTD

7363.95



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Supplementary Estimate : QUOT201905-000376(00)

MS FIRST CAPITAL INSURANCE LTD

NO. 36

ROBINSON RD

CITY HOUSE

SINGAPORE 068877

Contact : -

Fax No. : 65073849

Date : 18/05/2019

Vehicle No. : GBC824A

Make/Model : NISSAN NV200 1.5L MT ABS
AIRBAG 2WD 6DR

Mileage (km) : 173534

Chassis No. : JN1YBAM20U0003194

Accident Date : 16/05/2019 00:00:00

Claim No. : SHC692S

Reference : JO201905-0504

Policy No. : D-19092991MFCV/1

S/No	Particular	Quantity	Unit Price	Amount S\$
NET ITEMS :				
1	Rear bumper sponge ✓	1.0	182.30	182.30
2	Rear end panel top garnish ✓	1.0	155.30	155.30
List Total :				337.60
10% Discount S\$				33.76
				303.84
SPECIAL NET :				
1	Reverse sensor ✓	1.0	250.00	250.00
SPECIAL NET Total S\$:				250.00

P - \$ 3,133.50

-10%

\$ 2,820.15

SN - \$ 110.00

L - \$ 1,300.00

(N) supplementary - \$ 203.24

(CN) - \$ 250.00

\$ 4,783.99

-20%

\$ 3,827.19

4S - \$ 3,850.00

5 Days -

E. & O.E.

Total S\$: 553.84

GST 7% S\$: 38.77

Amount Due S\$: 592.61

for CITY AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19008911/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-06-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 692S	Veh. Inspected	GBC 824A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003324MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	21/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	JN1YBAM20U0003194	Colour	SILVER	
Odometer	173534	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	DUNLOP	6 mm	
L/H Front Tyre	175/70 R14	DUNLOP	6 mm	
R/H Rear Tyre	175/70 R14	DUNLOP	6 mm	
L/H Rear Tyre	175/70 R14	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/05/2019	Inspection Date	22/05/2019	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 824A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR RH DOOR (N)	BENT	960.90	960.90
1	REAR LH DOOR (N)	BENT	1,281.10	1,281.10
1	REAR BUMPER (N)	BUCKLED	481.70	481.70
2	REAR DOOR RUBBER @\$96.40 (N)	SERVICEABLE	192.80	-
2	REAR BUMPER REFLECTOR @\$67.60 (N)	SERVICEABLE	135.20	-
1	REAR DOOR LOCK (N)	TO REPAIR SEE LABOUR	261.00	-
2	RH DOOR HINGES @\$184.60 (N)	TO REPAIR SEE LABOUR	369.20	-
2	LH DOOR HINGES @\$184.60 (N)	TO REPAIR SEE LABOUR	369.20	-
1	REAR END PANEL OUTER (N)	BENT	211.80	211.80
1	REAR END PANEL INNER (N)	TO REPAIR SEE LABOUR	544.00	-
1	EMBLEM - NV200 (N)	NECESSARY	68.00	68.00
1	EMBLEM - LOGO (N)	NECESSARY	65.00	65.00
1	EMBLEM - DCI (N)	NECESSARY	65.00	65.00
2	TAIL LAMP @\$236.50 (N)	SERVICEABLE	473.00	-
1	REAR BUMPER SPONGE (ADDITIONAL)(N)	CRACKED	182.30	182.30
1	REAR END PANEL TOP GARNISH (ADDITIONAL)(N)	MTG DISTORTED	155.30	155.30
	LESS 10% DISCOUNT		-581.55	-347.11
			5,233.95	3,123.99
SPECIAL NETT ITEMS				
1	STICKER - 70KM/H (SN)	NECESSARY	20.00	15.00
1	STICKER - 5 PAX (SN)	NECESSARY	20.00	15.00
2	WINDSCREEN SEALANT (SN)	NECESSARY	80.00	80.00
1	REVERSE SENSOR (ADDITIONAL) (SN)	SHORTED	250.00	200.00
			370.00	310.00
LABOUR				
	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS.		160.00	100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO KNOCK JACKOUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR DOOR LOCK, RH DOOR HINGES, LH DOOR HINGES AND REAR END PANEL INNER.		750.00	600.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		850.00	600.00
			1,760.00	1,300.00
GRAND TOTAL			7,363.95	4,733.99
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CS/FCI19008911/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.