


Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:17

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014091 Date : 07/08/2019 Order : SMG6426A Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SMG6426A (V 40461) Regn Date: 27/12/2018 Mileage: 7358 WIP No.: 53892

Model: A3 SPORTSBACK 1.0 TFSI 8VFANG Chassis: WAUZZZ8V2KA030712 Engine: CHZ C25976 Dept: U

You have been assisted by :- UB-Siti Marsilla (137)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, LHS HEADLIGHT AND BONNET. TO REPAIR LHS FRONT FENDER. TO INSPECT LOCK CARRIER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1500.00	1.00	1,500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V3853651AA3FZ	GRILLE Less 020%	1.00	1301.00	1,040.80
X	A8V0941773D	HEADLIGHT Less 020%	1.00	5029.00	4,023.20
X	A8V0807550A	(SK) FOAM INSERT Less 020%	1.00	172.00	137.60
X	A8V0807065R GRU	(GER) COVER Less 020%	1.00	1698.00	1,358.40
X	A8V0823029D	007247/ (V) (GER) HOOD Less 020%	1.00	2501.00	2,000.80
X	A8V0823126B	EDGING Less 020%	1.00	24.93	19.95
X	A8V3807319	PLATE (LAST) Less 020%	1.00	270.00	216.00
X	A431955465A	GASKET Less 020%	1.00	6.90	5.52
X	A443955465	GASKET Less 020%	1.00	2.90	2.32
X	A8K0010520A	PLATE Less 020%	1.00	12.20	9.76
X	A8V0010515A	STICKER Less 020%	1.00	6.40	5.12
X	A8V3853949	PLATE (LAST) Less 020%	1.00	173.50	138.80
X	A5Q0955453R	WATER RES. Less 020%	1.00	185.50	148.40

Parts 9,106.67
Labour 0.00
Sublet 3,742.00
Menus 0.00
Lubricant 0.00

Sub-Total 12,248.67

7% GST 857.41

Grand Total 13,106.08



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SMG 6426 A

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0642/2019/SM
31 May 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SB 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V2KA030712
Vehicle Regn No. : **SMG 6426 A**
Vehicle Mileage : 7358 KM
Vehicle Owner : Mr. Chan Wei Wen Nicolas
Certificate No : 1800149510
Own Damage Excess : \$642.00 (Inclusive 7%GST)
Accident Date : 16/05/2019
Place : George Street T-Junction (Merging into Pickering St)
Repair Cost : \$13,106-08
WIP No. : 53892
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 8:45am
Date : 1/6/19