

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

18/05/2019 14:43

JOB-NO: 50111657

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHA0783Z
 MAKE / MODEL: HYUNDAI / i40

TRANS: AUTO

CHASSIS: KMHLB41UMFU066071

ENGINE: D4FDDU371615

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	450.00	0.00	450.00		Y	300
2 DIAGNOSTIC VEHICLE & RESETTING HEADLAMP ADJUSTMENT	1.00	250.00	0.00	250.00		Y	150
3 CONDUCT 4 WHEEL ALIGNMENT	1.00	120.00	0.00	120.00		Y	60
4 REMOVE & REFIT WHEEL CAP & CHECK UNDERCARRIAGE NECESSARY ADJUSTMENT	1.00	80.00	0.00	80.00		Y	30
5 SUNDRIES	1.00	50.00	0.00	50.00		Y	20
6 RESPRAY FRONT BUMPER	1.00	230.00	0.00	230.00		Y	200
7 RESPRAY FRONT FENDER RHS	1.00	230.00	0.00	230.00		Y	200
TOTAL:		1,410.00	0.00	1,410.00			
MATERIALS							
1 FRONT BUMPER V2	1.00	699.58	139.92	559.66	L	Y	del
2 FRONT BUMPER RETAINER RH	1.00	42.98	8.60	34.38	L	Y	re
3 FRONT BUMPER RETAINER LH	1.00	42.98	8.60	34.38	L	Y	X
4 HEAD LAMP RHS	1.00	1,808.10	361.62	1,446.48	L	Y	X
5 FRONT FENDER RHS	1.00	623.86	124.77	499.09	L	Y	bb
6 FRONT FENDER INNER SHIELD RHS	1.00	175.00	35.00	140.00	L	Y	X
7 FRONT WHEEL CAP RHS	1.00	265.80	53.16	212.64	L	Y	ab
8 FRONT BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	na
9 FRONT FENDER QTR GARNISH CLIP SET	1.00	15.00	0.00	15.00	S	Y	X
TOTAL:		3,708.30	731.67	2,976.63			
TOTAL PARTS & LABOUR :		5,118.30	731.67	4,386.63			

EXCESS/LOADING:S\$ 0.00

No. Of Day: 3

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: 22/5/19 1800 WP

SURVEYED BY: Tan Jiah

CONTACT NO: 97495749

FAX NO:

surelkhanto.com

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: